

Incident Report INC-14 — Tank overfill near-miss

Plant: Shakti Petrochem Unit-2 | **Asset:** TK-501 | **Date:** 2025-09-27

Description

Storage tank approached overfill during a receipt; high-high alarm arrested the transfer.

Root Cause

Level transmitter drift not caught between calibrations.

Lessons Learned

Shorten calibration interval for custody-critical level instruments.