

Inspection Report IR-17 — Vibration survey

Plant: Shakti Petrochem Unit-2 | **Asset:** P-204A | **Date:** 2026-06-10 | **Result:**
ABNORMAL | **Next Due:** 2026-07-10

Findings

DE bearing vibration measured at 6.2 mm/s RMS, above 4.5 mm/s alarm. Spectrum suggests misalignment / early bearing wear. Recommend coupling alignment and post-repair verification.

Result

ABNORMAL