

Inspection Report IR-19 — Thermal performance inspection

Plant: Shakti Petrochem Unit-2 | **Asset:** HX-102 | **Date:** 2026-06-08 | **Result:** ATTENTION | **Next Due:** 2026-09-08

Findings

Tube-side fouling observed. Outlet temperature elevated. Cleaning recommended.

Result

ATTENTION