

Work Order WO-129 — Seal leakage reported

Plant: Shakti Petrochem Unit-2 | **Asset:** P-204A | **Date:** 2026-05-28 | **Status:** closed

Description

Operator reported gland weepage on boiler feed pump P-204A during routine round.

Findings

Mechanical seal showing steady weep at gland. Vibration noted as elevated by operator.

Action Taken

Raised for seal inspection and replacement. Advised alignment check.

Post-Repair Test

n/a