

MAINTENANCE & REPAIR REPORT

Plant Engineering Dept. · Form ME-07 Rev C

REPORT NO.

RPT-4001

FAULT PATTERN ID

FP-01

DATE OF FAILURE

09/07/2026 03:00

ASSET ID

AST-003

MODEL NO.

ATLAS-GA30

LINKED WO

WO-24101

SYMPTOMS OBSERVED

Comp tripped high vib alarm 8.2mm/s. NDE 6312 brg cage broken, rollers pitted, inner race scored.

DIAGNOSIS / ROOT CAUSE

Grease contamination via auto-luber

PARTS REPLACED

BRG-6312-2RS x2, GRS-EP2

DOWNTIME (HRS)

9.5

FAULT CATEGORY

Bearing Wear

TECHNICIAN

A. Shirodkar

SIGNATURE

