

MAINTENANCE & REPAIR REPORT

Plant Engineering Dept. · Form ME-07 Rev C

REPORT NO.

RPT-4014

FAULT PATTERN ID

FP-03

DATE OF FAILURE

31/05/2025 19:00

ASSET ID

AST-012

MODEL NO.

SIEM-1LE1

LINKED WO

-

SYMPTOMS OBSERVED

Current reading frozen mid-value, agitator fine. CT wiring loose in panel.

DIAGNOSIS / ROOT CAUSE

Loose terminal, panel vibration

PARTS REPLACED

nil

DOWNTIME (HRS)

0.5

FAULT CATEGORY

Sensor Fault

TECHNICIAN

V. Gawas

SIGNATURE

