

MAINTENANCE & REPAIR REPORT

Plant Engineering Dept. · Form ME-07 Rev C

REPORT NO.
RPT-4016

FAULT PATTERN ID
FP-04

DATE OF FAILURE
09/07/2024 03:00

ASSET ID
AST-004

MODEL NO.
SIEM-1LE1

LINKED WO
-

SYMPTOMS OBSERVED

Conveyor speed hunting +-40rpm, squeal on load steps. Belt glazed and loose.

DIAGNOSIS / ROOT CAUSE

Belt tension lost, glazing from slip

PARTS REPLACED

BELT-SPB-2500

DOWNTIME (HRS)

2.0

FAULT CATEGORY

Belt Slip Rpm

TECHNICIAN

M. D'Souza

SIGNATURE

