

MAINTENANCE & REPAIR REPORT

Plant Engineering Dept. · Form ME-07 Rev C

REPORT NO.

RPT-4017

FAULT PATTERN ID

FP-04

DATE OF FAILURE

16/07/2025 22:00

ASSET ID

AST-004

MODEL NO.

SIEM-1LE1

LINKED WO

-

SYMPTOMS OBSERVED

RPM dips under load, product spacing drifting. Belt worn, sheave groove polished.

DIAGNOSIS / ROOT CAUSE

Belt end of life, sheave wear starting

PARTS REPLACED

BELT-SPB-2500

DOWNTIME (HRS)

3.0

FAULT CATEGORY

Belt Slip Rpm

TECHNICIAN

S. Kadam

SIGNATURE

