

MAINTENANCE & REPAIR REPORT

Plant Engineering Dept. · Form ME-07 Rev C

REPORT NO.

RPT-4018

FAULT PATTERN ID

FP-04

DATE OF FAILURE

13/11/2024 08:00

ASSET ID

AST-012

MODEL NO.

SIEM-1LE1

LINKED WO

-

SYMPTOMS OBSERVED

Agitator speed unstable, slipping on start. Belt oil-contaminated from gearbox leak.

DIAGNOSIS / ROOT CAUSE

Oil on belt - gearbox seal weep

PARTS REPLACED

BELT-SPB-2500, SEAL-TC-50x72

DOWNTIME (HRS)

4.0

FAULT CATEGORY

Belt Slip Rpm

TECHNICIAN

A. Shirodkar

SIGNATURE

