

# MAINTENANCE & REPAIR REPORT

Plant Engineering Dept. · Form ME-07 Rev C

REPORT NO.

RPT-4002

FAULT PATTERN ID

FP-01

DATE OF FAILURE

27/06/2026 01:38

ASSET ID

AST-009

MODEL NO.

ABB-M3BP-180

LINKED WO

WO-24290

SYMPTOMS OBSERVED

DE brg failed night shift, line down. Vib trending up 10 days, alert missed. 6316 seized, pressed out.

DIAGNOSIS / ROOT CAUSE

End of brg life ~14 months duty, monitoring gap

PARTS REPLACED

BRG-6316-C3 x2

DOWNTIME (HRS)

12.0

FAULT CATEGORY

Bearing Wear

TECHNICIAN

S. Kadam

SIGNATURE

