

MAINTENANCE & REPAIR REPORT

Plant Engineering Dept. · Form ME-07 Rev C

REPORT NO.

RPT-4003

FAULT PATTERN ID

FP-01

DATE OF FAILURE

15/04/2025 04:38

ASSET ID

AST-007

MODEL NO.

ATLAS-GA30

LINKED WO

-

SYMPTOMS OBSERVED

Vib rose from 3.4 to 7+ over a week, NDE brg rough on stethoscope, temp up 8C.

DIAGNOSIS / ROOT CAUSE

Brg wear early stage, caught on rounds

PARTS REPLACED

BRG-6312-2RSx2, GRS-EP2

DOWNTIME (HRS)

6.0

FAULT CATEGORY

Bearing Wear

TECHNICIAN

R. Naik

SIGNATURE

