

MAINTENANCE & REPAIR REPORT

Plant Engineering Dept. · Form ME-07 Rev C

REPORT NO.

RPT-4004

FAULT PATTERN ID

FP-01

DATE OF FAILURE

19/08/2023 07:38

ASSET ID

AST-005

MODEL NO.

ABB-M3BP-160

LINKED WO

-

SYMPTOMS OBSERVED

Main motor vib 6.8mm/s and climbing, brg temp 74C. Axial play felt at DE.

DIAGNOSIS / ROOT CAUSE

DE brg wear, lubrication starvation suspected

PARTS REPLACED

BRG-6312-2RS x1, GRS-EP2

DOWNTIME (HRS)

7.5

FAULT CATEGORY

Bearing Wear

TECHNICIAN

A. Shirodkar

SIGNATURE

