

MAINTENANCE & REPAIR REPORT

Plant Engineering Dept. · Form ME-07 Rev C

REPORT NO.

RPT-4005

FAULT PATTERN ID

FP-01

DATE OF FAILURE

25/01/2026 05:38

ASSET ID

AST-001

MODEL NO.

ABB-M3BP-160

LINKED WO

-

SYMPTOMS OBSERVED

Vib alarm 8mm/s, brg noisy. Cage wear visible on strip down, rollers dull.

DIAGNOSIS / ROOT CAUSE

Normal wear, PM interval too long for duty

PARTS REPLACED

BRG-6312-2RS x2

DOWNTIME (HRS)

8.0

FAULT CATEGORY

Bearing Wear

TECHNICIAN

M. D'Souza

SIGNATURE

