

MAINTENANCE & REPAIR REPORT

Plant Engineering Dept. · Form ME-07 Rev C

REPORT NO.

RPT-4008

FAULT PATTERN ID

FP-02

DATE OF FAILURE

23/02/2025 05:38

ASSET ID

AST-007

MODEL NO.

ATLAS-GA30

LINKED WO

-

SYMPTOMS OBSERVED

Discharge temp high alarm 82C. Aftercooler fouled, fan belt glazed.

DIAGNOSIS / ROOT CAUSE

Cooler fouling + fan belt slip

PARTS REPLACED

COIL-CLEAN-KIT, BELT-SPB-2500

DOWNTIME (HRS)

4.0

FAULT CATEGORY

Cooling Degradation

TECHNICIAN

R. Naik

SIGNATURE

