

MAINTENANCE & REPAIR REPORT

Plant Engineering Dept. · Form ME-07 Rev C

REPORT NO.

RPT-4010

FAULT PATTERN ID

FP-02

DATE OF FAILURE

04/03/2025 23:38

ASSET ID

AST-006

MODEL NO.

REXROTH-A10

LINKED WO

-

SYMPTOMS OBSERVED

Hyd oil temp 68C vs 60 normal, vib ok. Heat exchanger scaled inside.

DIAGNOSIS / ROOT CAUSE

Cooling water hardness, exchanger scaling

PARTS REPLACED

COIL-CLEAN-KIT

DOWNTIME (HRS)

5.0

FAULT CATEGORY

Cooling Degradation

TECHNICIAN

A. Shirodkar

SIGNATURE

