

MAINTENANCE & REPAIR REPORT

Plant Engineering Dept. · Form ME-07 Rev C

REPORT NO.

RPT-4019

FAULT PATTERN ID

FP-04

DATE OF FAILURE

14/07/2024 21:38

ASSET ID

AST-008

MODEL NO.

CG-ND132

LINKED WO

-

SYMPTOMS OBSERVED

Fan rpm sagging 5% intermittent, airflow alarms. Belt stretched beyond adjuster range.

DIAGNOSIS / ROOT CAUSE

Belt stretched, adjuster at limit

PARTS REPLACED

BELT-SPB-2500

DOWNTIME (HRS)

2.5

FAULT CATEGORY

Belt Slip Rpm

TECHNICIAN

S. Kadam

SIGNATURE

