## Pre Plane Assembly Summary

Panel No	Plane No	Cleaned/ Prepped		Missing wires	Missing wires confirmed	PFN & stnd. off epoxy	install	Ear leak test	Prep Finished
MNO41	20		8			V	grey /	Vol de la constante de la cons	
	stay boit stands need to be epoxied  Replaced wives 38, 46 on 8/27/24  Clear straws 0,2,4,6,18,26,28,32  Cleared 14,70,83,86,92,94  Replaced wires 70,83,86 on 9/19/24  drilled 75  removed wires 38,46  open vectra repair on wire #42, passed resistance me as we ments  open vectra repair on wire #42, passed resistance me as we ments								
HV issues	with 38, wire 32, blocked	70 short 70,83, 42,46 migh	, 86, 94 sh, outhout	icult, Ramo	de-calthode Huside 38,46 Ranoh-ca	Note Calride ~ 1	en e	s.l.cn	
			- I DMB	gap test u	uls mil kapton :	3 gir -V			

9th sept. 2024, MNO4) High current wire (88) Short wise: (14) (70) (3) (86) (94 Blocked Strow at Cathode ch. 137 HV test V Govins fer 24th Od. 2024, MN041 Short wine: (19) (94) Toip issul: (90) Blocked Straw at conthode ch. (37) HV test V govin test V