Pre Plane Assembly Summary

	1 To Than on the combinery curring y									Poine 1 Pie-	
Panel No	Plane No	Cleaned/ Prepped	Blocked straws	Missing wires	Missing wires confirmed	PFN & stnd. off epoxy	Ear install	Ear leak test	Prep Finished	Assy.gas	
MN253	.21	· V				· /	grey V	1	-1/	- \	
Repairs	Ear F	looding -	7			isalawaninimaaninimaaninimaaninimaaninima	dammannan Amanas.	alimentum macanenarum.	oliminimiamiamiamiamiamiamiamiamiamiamiamiamia		
HV											
issues										A PROPERTY OF THE PROPERTY OF	
	TOBA Y	st - 0									
	Fe55 te ttv test cain te	-0								To provide the second s	
	Gain te	St - 0									
Notes &	Air teste	d for hi	locked str	aws-ok							
	DMB ga	ip test i	of 5 mil	kapton:	à Air-OK						
3	backsid	le PFN (heck-O	K							
	Clan mar	+ plasact	1000	handam	age to outer a	dia confoca	-Sliver	REMAIS	of 45moz	thed out	
and the same of th	idon ba	1 (10323)		unanaminithamitinahamitinahamitinahamitinahamitinahamitinahamitinahamitinahamitinahamitinahamitinahamitinahami	acyc 10 00 lott	and Johnson	Re	moved +	Smooth.	thed out	