


23L-6006 Mudassar Hussain


6B1

Ex1


a) $k=0$




$K = \infty$




B




C




D



E




F




Ex2


A,k=0



k=inf




B




C - The point and gain where locus crosses jw axis, no jw crossing

D - Range of gain is $0 < k < \infty$

E




F




Ex3

A) $k=0$


top ▶ matlab




$k=\infty$



B



C



D

