
After macOS 12.1 Install macOS is change by Apple. Followed every steps for the fix!


After the 29 Minutes don't reboot on macOS Installer, use another Mac or Hackintosh then setup config.plist ➤ Misc:Security like this on the USB key



Boot to macOS Installer

after all the RAMRODs put back on Disable and boot on the macOS Monterey disk to complete the last stage, it will reboot again and then after it's the user account.

You will have to do the same thing for the update, simply setup config.plist ➤ Misc:Security like this on the USB key



after rebooting the Update

and after installing the update remove the USB key then boot from disk and reinstall the HD 4000 patch.