


Task #1 Main Component






KeyPad FlowChart start Init I/O pins used for **KeyPad Connection** Set all Row Pins to Ground Apply required function related to Read All Columns pressed key No any key pressed? **Identify Pressed Key** Yes Run Timer No No Read All Set Next Yes Yes Set all Raw Timer Key Still Read All Pressed Key Columns Raw pin Expired? Pressed? pins to high Columns at this Row? pins To Ground No Run any Regular

Tasks





Send Command To LCD FlowChart

