
(a) Look-away ≥ 2 s
n = 0
(b) Fatigue level increase
n = 8, latency 0.8 s (median)
(c) Confidence < 0.5
n = 32, latency 0.0 s (median)
(d) Hand closer than 0.30 m
n = 76, latency 2.8 s (median)
Commanded speed (deg/s)
Time from trigger (s)
0
10
20
30
-5
0
5
10
15