


University of Jordan School of Engineering Department of Mechatronics Engineering Microprocessor and Microcontroller Laboratory 0908432



Exp. 11: PWM

Assignment (Bonus): -

* Write a code using PWM technique to get a speed profile for soft start/stop motors such as following timing-diagram.



- The START push button must to be pressed to generate this timing-diagram.
- -PWM Duty Cycle increased/decreased by 5% every 0.1 Sec.

** To Send ASM File follow the link below

https://docs.google.com/forms/d/e/1FAIpQLSf7TALb2s97ar7GXiSR4288Y9umkzN68FFdPpIahfQ51lOkzQ/viewform