

Unit 1D, Building A

Synthetic demo document - fictional company, not real data. Routine inspection reports for Harbourview Residences, January to August 2026. One report per page.

Routine inspection report INS-2026-0173 for Unit 1D, Building A, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0173
- Date of inspection: 20 July 2026
- Inspector: Grace Holloway
- Tenant: Laura Fischer
- Tenant present: Yes
- Overall condition: Needs attention

Condition by Room

- Kitchen: Good
- Bathroom: Poor
- Living area: Good
- Bedrooms: Good
- Laundry: Poor
- Balcony: Good
- Smoke alarms: One alarm failed the test (see Issues Found)

Issues Found

- Bathroom: Bathroom exhaust fan not working.
- Laundry: Washing machine tap leaking at the connection.
- Smoke alarms: Hallway smoke alarm failed the test.

Follow-up Actions

- Work order WO-6672 raised with Brightwire Electrical to replace the exhaust fan motor, due by 3 August 2026.
- Work order WO-6904 raised with Coastline Plumbing to replace the washing machine tap washer, due by 3 August 2026.
- Smoke alarm battery replaced on site by the inspector; alarm retested and working.
- Next routine inspection due: January 2027.

Inspector Notes

The tenant keeps the unit clean and tidy.

Unit 2D, Building A

Routine inspection report INS-2026-0396 for Unit 2D, Building A, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0396
- Date of inspection: 3 April 2026
- Inspector: Grace Holloway
- Tenant: Uma Turner
- Tenant present: No
- Overall condition: Fair

Condition by Room

- Kitchen: Good
- Bathroom: Fair
- Living area: Good
- Bedrooms: Fair
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Bathroom: Mould on the bathroom ceiling above the shower.
- Bedrooms: Water stain on the main bedroom ceiling.

Follow-up Actions

- Work order WO-6612 raised with FreshAir Mould Solutions to treat the mould and check the exhaust fan, due by 17 April 2026.
- Work order WO-6984 raised with Coastline Plumbing to investigate a possible leak from the unit above, due by 17 April 2026.
- Next routine inspection due: October 2026.

Inspector Notes

The tenant keeps the unit clean and tidy.

Unit 4B, Building A

Routine inspection report INS-2026-0259 for Unit 4B, Building A, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0259
- Date of inspection: 18 June 2026
- Inspector: Samuel Okafor
- Tenant: Jordan Ellis
- Tenant present: Yes
- Overall condition: Good

Condition by Room

- Kitchen: Good
- Bathroom: Fair
- Living area: Good
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Bathroom: Mould on the bathroom ceiling above the shower.

Follow-up Actions

- Work order WO-6470 raised with FreshAir Mould Solutions to treat the mould and check the exhaust fan, due by 2 July 2026.
- Next routine inspection due: December 2026.

Inspector Notes

An indoor cat is kept at the unit as approved under Clause 10.1 of the lease. No pet damage observed.

Unit 4D, Building A

Routine inspection report INS-2026-0113 for Unit 4D, Building A, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0113
- Date of inspection: 19 June 2026
- Inspector: Samuel Okafor
- Tenant: Wen Fischer
- Tenant present: Yes
- Overall condition: Needs attention

Condition by Room

- Kitchen: Good
- Bathroom: Good
- Living area: Good
- Bedrooms: Poor
- Laundry: Fair
- Balcony: Good
- Smoke alarms: One alarm failed the test (see Issues Found)

Issues Found

- Bedrooms: Wardrobe sliding door has come off its track.
- Laundry: Cracked floor tile at the laundry entrance.
- Smoke alarms: Hallway smoke alarm failed the test.

Follow-up Actions

- Work order WO-6823 raised with Harbour Handyman Services to refit the wardrobe door, due by 3 July 2026.
- Work order WO-6536 raised with Harbour Handyman Services to replace the cracked tile, due by 3 July 2026.
- Smoke alarm battery replaced on site by the inspector; alarm retested and working.
- Next routine inspection due: December 2026.

Inspector Notes

The tenant reported no other concerns during the inspection.

Unit 5A, Building A

Routine inspection report INS-2026-0289 for Unit 5A, Building A, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0289
- Date of inspection: 30 April 2026
- Inspector: Grace Holloway
- Tenant: Rosa Rossi
- Tenant present: Yes
- Overall condition: Fair

Condition by Room

- Kitchen: Good
- Bathroom: Fair
- Living area: Good
- Bedrooms: Good
- Laundry: Good
- Balcony: Fair
- Smoke alarms: Tested, all working

Issues Found

- Bathroom: Mould on the bathroom ceiling above the shower.
- Balcony: Balcony sliding door lock is stiff and hard to engage.

Follow-up Actions

- Work order WO-6950 raised with FreshAir Mould Solutions to treat the mould and check the exhaust fan, due by 14 May 2026.
- Work order WO-6502 raised with SecureLock Locksmiths to service the sliding door lock, due by 14 May 2026.
- Next routine inspection due: October 2026.

Inspector Notes

Windows and window tracks are clean. No signs of damp apart from the items noted.

Unit 5B, Building A

Routine inspection report INS-2026-0287 for Unit 5B, Building A, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0287
- Date of inspection: 27 February 2026
- Inspector: Grace Holloway
- Tenant: Mateo Gupta
- Tenant present: Yes
- Overall condition: Fair

Condition by Room

- Kitchen: Good
- Bathroom: Fair
- Living area: Good
- Bedrooms: Good
- Laundry: Good
- Balcony: Fair
- Smoke alarms: Tested, all working

Issues Found

- Bathroom: Bathroom exhaust fan not working.
- Balcony: Balcony sliding door lock is stiff and hard to engage.

Follow-up Actions

- Work order WO-6369 raised with Brightwire Electrical to replace the exhaust fan motor, due by 13 March 2026.
- Work order WO-6944 raised with SecureLock Locksmiths to service the sliding door lock, due by 13 March 2026.
- Next routine inspection due: August 2026.

Inspector Notes

The unit is presented in good order overall.

Unit 5C, Building A

Routine inspection report INS-2026-0337 for Unit 5C, Building A, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0337
- Date of inspection: 16 January 2026
- Inspector: Mei Tanaka
- Tenant: Uma Yilmaz
- Tenant present: Yes
- Overall condition: Fair

Condition by Room

- Kitchen: Fair
- Bathroom: Good
- Living area: Good
- Bedrooms: Good
- Laundry: Fair
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Kitchen: Evidence of cockroaches in the cupboard under the sink.
- Laundry: Cracked floor tile at the laundry entrance.

Follow-up Actions

- Work order WO-6205 raised with Evergreen Pest Control to carry out a pest treatment, due by 30 January 2026.
- Work order WO-6267 raised with Harbour Handyman Services to replace the cracked tile, due by 30 January 2026.
- Next routine inspection due: July 2026.

Inspector Notes

The tenant asked about repainting the second bedroom; referred to the property manager.

Unit 5D, Building A

Routine inspection report INS-2026-0317 for Unit 5D, Building A, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0317
- Date of inspection: 2 June 2026
- Inspector: Samuel Okafor
- Tenant: Hana Novak
- Tenant present: Yes
- Overall condition: Good

Condition by Room

- Kitchen: Good
- Bathroom: Poor
- Living area: Good
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Bathroom: Shower screen seal is cracked and leaking onto the floor.

Follow-up Actions

- Work order WO-6710 raised with Coastline Plumbing to reseal the shower screen, due by 16 June 2026.
- Next routine inspection due: December 2026.

Inspector Notes

The tenant reported no other concerns during the inspection.

Unit 6A, Building A

Routine inspection report INS-2026-0147 for Unit 6A, Building A, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0147
- Date of inspection: 26 January 2026
- Inspector: Grace Holloway
- Tenant: Nadia Walsh
- Tenant present: No
- Overall condition: Good

Condition by Room

- Kitchen: Good
- Bathroom: Good
- Living area: Fair
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Living area: Carpet stain of about 30 cm near the balcony door.

Follow-up Actions

- Tenant advised to arrange carpet cleaning before the next inspection.
- Next routine inspection due: July 2026.

Inspector Notes

The tenant keeps the unit clean and tidy.

Unit 6B, Building A

Routine inspection report INS-2026-0305 for Unit 6B, Building A, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0305
- Date of inspection: 6 July 2026
- Inspector: Grace Holloway
- Tenant: Yusuf Dixon
- Tenant present: No
- Overall condition: Fair

Condition by Room

- Kitchen: Good
- Bathroom: Poor
- Living area: Good
- Bedrooms: Good
- Laundry: Poor
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Laundry: Washing machine tap leaking at the connection.
- Bathroom: Shower screen seal is cracked and leaking onto the floor.

Follow-up Actions

- Work order WO-6498 raised with Coastline Plumbing to replace the washing machine tap washer, due by 20 July 2026.
- Work order WO-6478 raised with Coastline Plumbing to reseal the shower screen, due by 20 July 2026.
- Next routine inspection due: January 2027.

Inspector Notes

The unit is presented in good order overall.

Unit 6C, Building A

Routine inspection report INS-2026-0384 for Unit 6C, Building A, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0384
- Date of inspection: 20 August 2026
- Inspector: Samuel Okafor
- Tenant: Victor Novak
- Tenant present: Yes
- Overall condition: Needs attention

Condition by Room

- Kitchen: Good
- Bathroom: Good
- Living area: Fair
- Bedrooms: Poor
- Laundry: Good
- Balcony: Fair
- Smoke alarms: Tested, all working

Issues Found

- Bedrooms: Water stain on the main bedroom ceiling.
- Balcony: Balcony sliding door lock is stiff and hard to engage.
- Living area: Carpet stain of about 30 cm near the balcony door.

Follow-up Actions

- Work order WO-6524 raised with Coastline Plumbing to investigate a possible leak from the unit above, due by 3 September 2026.
- Work order WO-6786 raised with SecureLock Locksmiths to service the sliding door lock, due by 3 September 2026.
- Tenant advised to arrange carpet cleaning before the next inspection.
- Next routine inspection due: February 2027.

Inspector Notes

The tenant reported no other concerns during the inspection.

Unit 7B, Building A

Routine inspection report INS-2026-0356 for Unit 7B, Building A, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0356
- Date of inspection: 22 June 2026
- Inspector: Mei Tanaka
- Tenant: Tariq Zhou
- Tenant present: Yes
- Overall condition: Fair

Condition by Room

- Kitchen: Good
- Bathroom: Good
- Living area: Good
- Bedrooms: Fair
- Laundry: Good
- Balcony: Poor
- Smoke alarms: Tested, all working

Issues Found

- Balcony: Blocked balcony floor drain with pooling water.
- Bedrooms: Water stain on the main bedroom ceiling.

Follow-up Actions

- Work order WO-6847 raised with Coastline Plumbing to clear the balcony drain, due by 6 July 2026.
- Work order WO-6510 raised with Coastline Plumbing to investigate a possible leak from the unit above, due by 6 July 2026.
- Next routine inspection due: December 2026.

Inspector Notes

The tenant reported no other concerns during the inspection.

Unit 7D, Building A

Routine inspection report INS-2026-0160 for Unit 7D, Building A, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0160
- Date of inspection: 24 June 2026
- Inspector: Samuel Okafor
- Tenant: Fatima Castillo
- Tenant present: Yes
- Overall condition: Good

Condition by Room

- Kitchen: Fair
- Bathroom: Good
- Living area: Good
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Kitchen: Evidence of cockroaches in the cupboard under the sink.

Follow-up Actions

- Work order WO-6828 raised with Evergreen Pest Control to carry out a pest treatment, due by 8 July 2026.
- Next routine inspection due: December 2026.

Inspector Notes

The tenant reported no other concerns during the inspection.

Unit 8A, Building A

Routine inspection report INS-2026-0318 for Unit 8A, Building A, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0318
- Date of inspection: 16 January 2026
- Inspector: Grace Holloway
- Tenant: Yusuf Lindqvist
- Tenant present: Yes
- Overall condition: Good

Condition by Room

- Kitchen: Good
- Bathroom: Good
- Living area: Good
- Bedrooms: Poor
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Bedrooms: Wardrobe sliding door has come off its track.

Follow-up Actions

- Work order WO-6445 raised with Harbour Handyman Services to refit the wardrobe door, due by 30 January 2026.
- Next routine inspection due: July 2026.

Inspector Notes

The tenant keeps the unit clean and tidy.

Unit 8C, Building A

Routine inspection report INS-2026-0360 for Unit 8C, Building A, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0360
- Date of inspection: 20 April 2026
- Inspector: Grace Holloway
- Tenant: Yusuf Jensen
- Tenant present: No
- Overall condition: Good

Condition by Room

- Kitchen: Good
- Bathroom: Good
- Living area: Good
- Bedrooms: Fair
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Bedrooms: Water stain on the main bedroom ceiling.

Follow-up Actions

- Work order WO-6572 raised with Coastline Plumbing to investigate a possible leak from the unit above, due by 4 May 2026.
- Next routine inspection due: October 2026.

Inspector Notes

The tenant keeps the unit clean and tidy.

Unit 9B, Building A

Routine inspection report INS-2026-0352 for Unit 9B, Building A, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0352
- Date of inspection: 17 February 2026
- Inspector: Grace Holloway
- Tenant: Laura Quinn
- Tenant present: Yes
- Overall condition: Good

Condition by Room

- Kitchen: Fair
- Bathroom: Good
- Living area: Good
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Kitchen: Dripping kitchen mixer tap.

Follow-up Actions

- Work order WO-6680 raised with Coastline Plumbing to replace the tap cartridge, due by 3 March 2026.
- Next routine inspection due: August 2026.

Inspector Notes

The tenant reported no other concerns during the inspection.

Unit 9C, Building A

Routine inspection report INS-2026-0304 for Unit 9C, Building A, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0304
- Date of inspection: 23 February 2026
- Inspector: Mei Tanaka
- Tenant: Elliot Abbott
- Tenant present: Yes
- Overall condition: Good

Condition by Room

- Kitchen: Good
- Bathroom: Good
- Living area: Fair
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Living area: Split-system air conditioner not cooling.

Follow-up Actions

- Work order WO-6930 raised with Brightwire Electrical to service the air conditioner, due by 9 March 2026.
- Next routine inspection due: August 2026.

Inspector Notes

The unit is presented in good order overall.

Unit 9D, Building A

Routine inspection report INS-2026-0369 for Unit 9D, Building A, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0369
- Date of inspection: 17 August 2026
- Inspector: Grace Holloway
- Tenant: Jasmine Dixon
- Tenant present: Yes
- Overall condition: Fair

Condition by Room

- Kitchen: Good
- Bathroom: Good
- Living area: Good
- Bedrooms: Good
- Laundry: Good
- Balcony: Fair
- Smoke alarms: Tested, all working

Issues Found

- Balcony: Balcony sliding door lock is stiff and hard to engage.
- Balcony: Blocked balcony floor drain with pooling water.

Follow-up Actions

- Work order WO-6035 raised with SecureLock Locksmiths to service the sliding door lock, due by 31 August 2026.
- Work order WO-6852 raised with Coastline Plumbing to clear the balcony drain, due by 31 August 2026.
- Next routine inspection due: February 2027.

Inspector Notes

The tenant asked about repainting the second bedroom; referred to the property manager.

Unit 1A, Building B

Routine inspection report INS-2026-0233 for Unit 1A, Building B, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0233
- Date of inspection: 26 February 2026
- Inspector: Mei Tanaka
- Tenant: Jasmine Vega
- Tenant present: Yes
- Overall condition: Good

Condition by Room

- Kitchen: Good
- Bathroom: Good
- Living area: Good
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- No issues found. The unit is well maintained.

Follow-up Actions

- Next routine inspection due: August 2026.

Inspector Notes

The tenant asked about repainting the second bedroom; referred to the property manager.

Unit 1D, Building B

Routine inspection report INS-2026-0316 for Unit 1D, Building B, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0316
- Date of inspection: 1 July 2026
- Inspector: Grace Holloway
- Tenant: Aaron Fischer
- Tenant present: Yes
- Overall condition: Needs attention

Condition by Room

- Kitchen: Fair
- Bathroom: Fair
- Living area: Good
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: One alarm failed the test (see Issues Found)

Issues Found

- Kitchen: Rangehood light not working.
- Bathroom: Shower screen seal is cracked and leaking onto the floor.
- Smoke alarms: Hallway smoke alarm failed the test.

Follow-up Actions

- Work order WO-6298 raised with Brightwire Electrical to replace the rangehood globe and switch, due by 15 July 2026.
- Work order WO-6325 raised with Coastline Plumbing to reseal the shower screen, due by 15 July 2026.
- Smoke alarm battery replaced on site by the inspector; alarm retested and working.
- Next routine inspection due: January 2027.

Inspector Notes

Minor wear and tear consistent with the age of the fittings.

Unit 2B, Building B

Routine inspection report INS-2026-0389 for Unit 2B, Building B, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0389
- Date of inspection: 15 June 2026
- Inspector: Grace Holloway
- Tenant: Deepa Zhou
- Tenant present: Yes
- Overall condition: Needs attention

Condition by Room

- Kitchen: Poor
- Bathroom: Good
- Living area: Fair
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: One alarm failed the test (see Issues Found)

Issues Found

- Living area: Carpet stain of about 30 cm near the balcony door.
- Kitchen: Rangehood light not working.
- Smoke alarms: Hallway smoke alarm failed the test.

Follow-up Actions

- Tenant advised to arrange carpet cleaning before the next inspection.
- Work order WO-6469 raised with Brightwire Electrical to replace the rangehood globe and switch, due by 29 June 2026.
- Smoke alarm battery replaced on site by the inspector; alarm retested and working.
- Next routine inspection due: December 2026.

Inspector Notes

The tenant reported no other concerns during the inspection.

Unit 2C, Building B

Routine inspection report INS-2026-0346 for Unit 2C, Building B, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0346
- Date of inspection: 20 March 2026
- Inspector: Grace Holloway
- Tenant: Uma Jensen
- Tenant present: Yes
- Overall condition: Needs attention

Condition by Room

- Kitchen: Poor
- Bathroom: Good
- Living area: Fair
- Bedrooms: Poor
- Laundry: Good
- Balcony: Good
- Smoke alarms: One alarm failed the test (see Issues Found)

Issues Found

- Living area: Carpet stain of about 30 cm near the balcony door.
- Kitchen: Rangehood light not working.
- Bedrooms: Water stain on the main bedroom ceiling.
- Smoke alarms: Hallway smoke alarm failed the test.

Follow-up Actions

- Tenant advised to arrange carpet cleaning before the next inspection.
- Work order WO-6939 raised with Brightwire Electrical to replace the rangehood globe and switch, due by 3 April 2026.
- Work order WO-6832 raised with Coastline Plumbing to investigate a possible leak from the unit above, due by 3 April 2026.
- Smoke alarm battery replaced on site by the inspector; alarm retested and working.
- Next routine inspection due: September 2026.

Inspector Notes

The tenant asked about repainting the second bedroom; referred to the property manager.

Unit 3A, Building B

Routine inspection report INS-2026-0363 for Unit 3A, Building B, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0363
- Date of inspection: 10 June 2026
- Inspector: Mei Tanaka
- Tenant: Oliver Castillo
- Tenant present: Yes
- Overall condition: Good

Condition by Room

- Kitchen: Good
- Bathroom: Good
- Living area: Good
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- No issues found. The unit is well maintained.

Follow-up Actions

- Next routine inspection due: December 2026.

Inspector Notes

Windows and window tracks are clean. No signs of damp apart from the items noted.

Unit 3B, Building B

Routine inspection report INS-2026-0366 for Unit 3B, Building B, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0366
- Date of inspection: 30 July 2026
- Inspector: Mei Tanaka
- Tenant: Rosa Jensen
- Tenant present: Yes
- Overall condition: Good

Condition by Room

- Kitchen: Good
- Bathroom: Poor
- Living area: Good
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Bathroom: Shower screen seal is cracked and leaking onto the floor.

Follow-up Actions

- Work order WO-6101 raised with Coastline Plumbing to reseal the shower screen, due by 13 August 2026.
- Next routine inspection due: January 2027.

Inspector Notes

Windows and window tracks are clean. No signs of damp apart from the items noted.

Unit 3C, Building B

Routine inspection report INS-2026-0395 for Unit 3C, Building B, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0395
- Date of inspection: 6 April 2026
- Inspector: Grace Holloway
- Tenant: Zara Gupta
- Tenant present: Yes
- Overall condition: Fair

Condition by Room

- Kitchen: Fair
- Bathroom: Poor
- Living area: Good
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Kitchen: Evidence of cockroaches in the cupboard under the sink.
- Bathroom: Mould on the bathroom ceiling above the shower.

Follow-up Actions

- Work order WO-6449 raised with Evergreen Pest Control to carry out a pest treatment, due by 20 April 2026.
- Work order WO-6706 raised with FreshAir Mould Solutions to treat the mould and check the exhaust fan, due by 20 April 2026.
- Next routine inspection due: October 2026.

Inspector Notes

Windows and window tracks are clean. No signs of damp apart from the items noted.

Unit 4A, Building B

Routine inspection report INS-2026-0215 for Unit 4A, Building B, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0215
- Date of inspection: 27 July 2026
- Inspector: Mei Tanaka
- Tenant: Hana Sato
- Tenant present: Yes
- Overall condition: Fair

Condition by Room

- Kitchen: Poor
- Bathroom: Fair
- Living area: Good
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Bathroom: Mould on the bathroom ceiling above the shower.
- Kitchen: Evidence of cockroaches in the cupboard under the sink.

Follow-up Actions

- Work order WO-6734 raised with FreshAir Mould Solutions to treat the mould and check the exhaust fan, due by 10 August 2026.
- Work order WO-6804 raised with Evergreen Pest Control to carry out a pest treatment, due by 10 August 2026.
- Next routine inspection due: January 2027.

Inspector Notes

Windows and window tracks are clean. No signs of damp apart from the items noted.

Unit 4C, Building B

Routine inspection report INS-2026-0167 for Unit 4C, Building B, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0167
- Date of inspection: 23 March 2026
- Inspector: Mei Tanaka
- Tenant: Bianca Dixon
- Tenant present: No
- Overall condition: Needs attention

Condition by Room

- Kitchen: Poor
- Bathroom: Fair
- Living area: Good
- Bedrooms: Fair
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Bathroom: Bathroom exhaust fan not working.
- Kitchen: Evidence of cockroaches in the cupboard under the sink.
- Bedrooms: Water stain on the main bedroom ceiling.

Follow-up Actions

- Work order WO-6528 raised with Brightwire Electrical to replace the exhaust fan motor, due by 6 April 2026.
- Work order WO-6266 raised with Evergreen Pest Control to carry out a pest treatment, due by 6 April 2026.
- Work order WO-6464 raised with Coastline Plumbing to investigate a possible leak from the unit above, due by 6 April 2026.
- Next routine inspection due: September 2026.

Inspector Notes

Minor wear and tear consistent with the age of the fittings.

Unit 5A, Building B

Routine inspection report INS-2026-0126 for Unit 5A, Building B, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0126
- Date of inspection: 4 June 2026
- Inspector: Samuel Okafor
- Tenant: Phoebe Abbott
- Tenant present: Yes
- Overall condition: Fair

Condition by Room

- Kitchen: Poor
- Bathroom: Good
- Living area: Poor
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Living area: Split-system air conditioner not cooling.
- Kitchen: Dripping kitchen mixer tap.

Follow-up Actions

- Work order WO-6945 raised with Brightwire Electrical to service the air conditioner, due by 18 June 2026.
- Work order WO-6188 raised with Coastline Plumbing to replace the tap cartridge, due by 18 June 2026.
- Next routine inspection due: December 2026.

Inspector Notes

The tenant asked about repainting the second bedroom; referred to the property manager.

Unit 5B, Building B

Routine inspection report INS-2026-0368 for Unit 5B, Building B, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0368
- Date of inspection: 8 April 2026
- Inspector: Samuel Okafor
- Tenant: George Quinn
- Tenant present: Yes
- Overall condition: Good

Condition by Room

- Kitchen: Good
- Bathroom: Good
- Living area: Poor
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Living area: Split-system air conditioner not cooling.

Follow-up Actions

- Work order WO-6436 raised with Brightwire Electrical to service the air conditioner, due by 22 April 2026.
- Next routine inspection due: October 2026.

Inspector Notes

Minor wear and tear consistent with the age of the fittings.

Unit 6D, Building B

Routine inspection report INS-2026-0153 for Unit 6D, Building B, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0153
- Date of inspection: 27 January 2026
- Inspector: Mei Tanaka
- Tenant: Zara Zhou
- Tenant present: No
- Overall condition: Fair

Condition by Room

- Kitchen: Poor
- Bathroom: Good
- Living area: Good
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: One alarm failed the test (see Issues Found)

Issues Found

- Kitchen: Evidence of cockroaches in the cupboard under the sink.
- Smoke alarms: Hallway smoke alarm failed the test.

Follow-up Actions

- Work order WO-6863 raised with Evergreen Pest Control to carry out a pest treatment, due by 10 February 2026.
- Smoke alarm battery replaced on site by the inspector; alarm retested and working.
- Next routine inspection due: July 2026.

Inspector Notes

Minor wear and tear consistent with the age of the fittings.

Unit 7D, Building B

Routine inspection report INS-2026-0320 for Unit 7D, Building B, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0320
- Date of inspection: 13 August 2026
- Inspector: Mei Tanaka
- Tenant: Yusuf Zhou
- Tenant present: No
- Overall condition: Good

Condition by Room

- Kitchen: Good
- Bathroom: Good
- Living area: Good
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- No issues found. The unit is well maintained.

Follow-up Actions

- Next routine inspection due: February 2027.

Inspector Notes

The tenant keeps the unit clean and tidy.

Unit 8B, Building B

Routine inspection report INS-2026-0341 for Unit 8B, Building B, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0341
- Date of inspection: 24 July 2026
- Inspector: Samuel Okafor
- Tenant: Jasmine Fischer
- Tenant present: Yes
- Overall condition: Good

Condition by Room

- Kitchen: Good
- Bathroom: Fair
- Living area: Good
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Bathroom: Shower screen seal is cracked and leaking onto the floor.

Follow-up Actions

- Work order WO-6746 raised with Coastline Plumbing to reseal the shower screen, due by 7 August 2026.
- Next routine inspection due: January 2027.

Inspector Notes

The tenant keeps the unit clean and tidy.

Unit 9B, Building B

Routine inspection report INS-2026-0347 for Unit 9B, Building B, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0347
- Date of inspection: 3 August 2026
- Inspector: Mei Tanaka
- Tenant: Elliot Quinn
- Tenant present: Yes
- Overall condition: Fair

Condition by Room

- Kitchen: Fair
- Bathroom: Good
- Living area: Good
- Bedrooms: Fair
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Kitchen: Rangehood light not working.
- Bedrooms: Water stain on the main bedroom ceiling.

Follow-up Actions

- Work order WO-6491 raised with Brightwire Electrical to replace the rangehood globe and switch, due by 17 August 2026.
- Work order WO-6066 raised with Coastline Plumbing to investigate a possible leak from the unit above, due by 17 August 2026.
- Next routine inspection due: February 2027.

Inspector Notes

The tenant reported no other concerns during the inspection.

Unit 9D, Building B

Routine inspection report INS-2026-0218 for Unit 9D, Building B, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0218
- Date of inspection: 5 February 2026
- Inspector: Samuel Okafor
- Tenant: Laura Zhou
- Tenant present: Yes
- Overall condition: Needs attention

Condition by Room

- Kitchen: Good
- Bathroom: Poor
- Living area: Good
- Bedrooms: Fair
- Laundry: Poor
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Bathroom: Mould on the bathroom ceiling above the shower.
- Bedrooms: Wardrobe sliding door has come off its track.
- Laundry: Cracked floor tile at the laundry entrance.

Follow-up Actions

- Work order WO-6665 raised with FreshAir Mould Solutions to treat the mould and check the exhaust fan, due by 19 February 2026.
- Work order WO-6273 raised with Harbour Handyman Services to refit the wardrobe door, due by 19 February 2026.
- Work order WO-6925 raised with Harbour Handyman Services to replace the cracked tile, due by 19 February 2026.
- Next routine inspection due: August 2026.

Inspector Notes

The unit is presented in good order overall.

Unit 1C, Building C

Routine inspection report INS-2026-0163 for Unit 1C, Building C, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0163
- Date of inspection: 13 July 2026
- Inspector: Grace Holloway
- Tenant: Zara Rossi
- Tenant present: Yes
- Overall condition: Good

Condition by Room

- Kitchen: Good
- Bathroom: Good
- Living area: Good
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- No issues found. The unit is well maintained.

Follow-up Actions

- Next routine inspection due: January 2027.

Inspector Notes

The tenant keeps the unit clean and tidy.

Unit 3B, Building C

Routine inspection report INS-2026-0334 for Unit 3B, Building C, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0334
- Date of inspection: 23 March 2026
- Inspector: Mei Tanaka
- Tenant: Mateo Novak
- Tenant present: Yes
- Overall condition: Good

Condition by Room

- Kitchen: Good
- Bathroom: Good
- Living area: Poor
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Living area: Carpet stain of about 30 cm near the balcony door.

Follow-up Actions

- Tenant advised to arrange carpet cleaning before the next inspection.
- Next routine inspection due: September 2026.

Inspector Notes

The tenant reported no other concerns during the inspection.

Unit 3C, Building C

Routine inspection report INS-2026-0380 for Unit 3C, Building C, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0380
- Date of inspection: 9 April 2026
- Inspector: Mei Tanaka
- Tenant: Laura Kaur
- Tenant present: Yes
- Overall condition: Needs attention

Condition by Room

- Kitchen: Fair
- Bathroom: Fair
- Living area: Good
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Bathroom: Shower screen seal is cracked and leaking onto the floor.
- Bathroom: Bathroom exhaust fan not working.
- Kitchen: Dripping kitchen mixer tap.

Follow-up Actions

- Work order WO-6511 raised with Coastline Plumbing to reseal the shower screen, due by 23 April 2026.
- Work order WO-6380 raised with Brightwire Electrical to replace the exhaust fan motor, due by 23 April 2026.
- Work order WO-6099 raised with Coastline Plumbing to replace the tap cartridge, due by 23 April 2026.
- Next routine inspection due: October 2026.

Inspector Notes

The tenant reported no other concerns during the inspection.

Unit 3D, Building C

Routine inspection report INS-2026-0229 for Unit 3D, Building C, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0229
- Date of inspection: 20 May 2026
- Inspector: Grace Holloway
- Tenant: Callum Brennan
- Tenant present: Yes
- Overall condition: Good

Condition by Room

- Kitchen: Good
- Bathroom: Good
- Living area: Fair
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Living area: A dog was observed living in the unit. Dogs are not permitted under the Building C House Rules.

Follow-up Actions

- Breach notice issued to the tenant under the Building C House Rules; the dog must be removed within 14 days.
- Next routine inspection due: November 2026.

Inspector Notes

The tenant said the dog belongs to a relative and is staying temporarily.

Unit 5A, Building C

Routine inspection report INS-2026-0387 for Unit 5A, Building C, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0387
- Date of inspection: 15 May 2026
- Inspector: Mei Tanaka
- Tenant: Fatima Petrov
- Tenant present: Yes
- Overall condition: Good

Condition by Room

- Kitchen: Good
- Bathroom: Poor
- Living area: Good
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Bathroom: Shower screen seal is cracked and leaking onto the floor.

Follow-up Actions

- Work order WO-6200 raised with Coastline Plumbing to reseal the shower screen, due by 29 May 2026.
- Next routine inspection due: November 2026.

Inspector Notes

Minor wear and tear consistent with the age of the fittings.

Unit 5C, Building C

Routine inspection report INS-2026-0306 for Unit 5C, Building C, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0306
- Date of inspection: 30 March 2026
- Inspector: Samuel Okafor
- Tenant: Elliot Hughes
- Tenant present: Yes
- Overall condition: Good

Condition by Room

- Kitchen: Good
- Bathroom: Good
- Living area: Good
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- No issues found. The unit is well maintained.

Follow-up Actions

- Next routine inspection due: September 2026.

Inspector Notes

The tenant reported no other concerns during the inspection.

Unit 5D, Building C

Routine inspection report INS-2026-0258 for Unit 5D, Building C, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0258
- Date of inspection: 15 July 2026
- Inspector: Grace Holloway
- Tenant: Laura Gupta
- Tenant present: Yes
- Overall condition: Good

Condition by Room

- Kitchen: Good
- Bathroom: Good
- Living area: Fair
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Living area: Carpet stain of about 30 cm near the balcony door.

Follow-up Actions

- Tenant advised to arrange carpet cleaning before the next inspection.
- Next routine inspection due: January 2027.

Inspector Notes

The tenant asked about repainting the second bedroom; referred to the property manager.

Unit 6C, Building C

Routine inspection report INS-2026-0381 for Unit 6C, Building C, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0381
- Date of inspection: 18 August 2026
- Inspector: Grace Holloway
- Tenant: Elliot Castillo
- Tenant present: No
- Overall condition: Needs attention

Condition by Room

- Kitchen: Good
- Bathroom: Fair
- Living area: Good
- Bedrooms: Good
- Laundry: Fair
- Balcony: Fair
- Smoke alarms: Tested, all working

Issues Found

- Bathroom: Shower screen seal is cracked and leaking onto the floor.
- Laundry: Cracked floor tile at the laundry entrance.
- Balcony: Blocked balcony floor drain with pooling water.

Follow-up Actions

- Work order WO-6766 raised with Coastline Plumbing to reseal the shower screen, due by 1 September 2026.
- Work order WO-6878 raised with Harbour Handyman Services to replace the cracked tile, due by 1 September 2026.
- Work order WO-6422 raised with Coastline Plumbing to clear the balcony drain, due by 1 September 2026.
- Next routine inspection due: February 2027.

Inspector Notes

Minor wear and tear consistent with the age of the fittings.

Unit 6D, Building C

Routine inspection report INS-2026-0357 for Unit 6D, Building C, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0357
- Date of inspection: 27 July 2026
- Inspector: Mei Tanaka
- Tenant: Tariq O'Brien
- Tenant present: No
- Overall condition: Fair

Condition by Room

- Kitchen: Poor
- Bathroom: Good
- Living area: Good
- Bedrooms: Good
- Laundry: Fair
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Laundry: Cracked floor tile at the laundry entrance.
- Kitchen: Rangehood light not working.

Follow-up Actions

- Work order WO-6150 raised with Harbour Handyman Services to replace the cracked tile, due by 10 August 2026.
- Work order WO-6461 raised with Brightwire Electrical to replace the rangehood globe and switch, due by 10 August 2026.
- Next routine inspection due: January 2027.

Inspector Notes

The unit is presented in good order overall.

Unit 7A, Building C

Routine inspection report INS-2026-0322 for Unit 7A, Building C, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0322
- Date of inspection: 9 April 2026
- Inspector: Mei Tanaka
- Tenant: Priya Raman
- Tenant present: No
- Overall condition: Fair

Condition by Room

- Kitchen: Good
- Bathroom: Good
- Living area: Good
- Bedrooms: Good
- Laundry: Good
- Balcony: Fair
- Smoke alarms: One alarm failed the test (see Issues Found)

Issues Found

- Balcony: Blocked balcony floor drain with pooling water.
- Smoke alarms: Hallway smoke alarm failed the test.

Follow-up Actions

- Work order WO-6968 raised with Coastline Plumbing to clear the balcony drain, due by 23 April 2026.
- Smoke alarm battery replaced on site by the inspector; alarm retested and working.
- Next routine inspection due: October 2026.

Inspector Notes

The tenant was not home; entry was made with the agent's key after 7 days written notice.

Unit 7B, Building C

Routine inspection report INS-2026-0204 for Unit 7B, Building C, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0204
- Date of inspection: 16 March 2026
- Inspector: Samuel Okafor
- Tenant: Hana Hughes
- Tenant present: Yes
- Overall condition: Good

Condition by Room

- Kitchen: Good
- Bathroom: Good
- Living area: Good
- Bedrooms: Poor
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Bedrooms: Water stain on the main bedroom ceiling.

Follow-up Actions

- Work order WO-6015 raised with Coastline Plumbing to investigate a possible leak from the unit above, due by 30 March 2026.
- Next routine inspection due: September 2026.

Inspector Notes

The unit is presented in good order overall.

Unit 7C, Building C

Routine inspection report INS-2026-0251 for Unit 7C, Building C, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0251
- Date of inspection: 29 July 2026
- Inspector: Grace Holloway
- Tenant: Elliot Mensah
- Tenant present: Yes
- Overall condition: Fair

Condition by Room

- Kitchen: Good
- Bathroom: Fair
- Living area: Good
- Bedrooms: Good
- Laundry: Fair
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Bathroom: Shower screen seal is cracked and leaking onto the floor.
- Laundry: Cracked floor tile at the laundry entrance.

Follow-up Actions

- Work order WO-6095 raised with Coastline Plumbing to reseal the shower screen, due by 12 August 2026.
- Work order WO-6001 raised with Harbour Handyman Services to replace the cracked tile, due by 12 August 2026.
- Next routine inspection due: January 2027.

Inspector Notes

Windows and window tracks are clean. No signs of damp apart from the items noted.

Unit 7D, Building C

Routine inspection report INS-2026-0238 for Unit 7D, Building C, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0238
- Date of inspection: 16 June 2026
- Inspector: Grace Holloway
- Tenant: Callum Novak
- Tenant present: No
- Overall condition: Good

Condition by Room

- Kitchen: Fair
- Bathroom: Good
- Living area: Good
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Kitchen: Evidence of cockroaches in the cupboard under the sink.

Follow-up Actions

- Work order WO-6463 raised with Evergreen Pest Control to carry out a pest treatment, due by 30 June 2026.
- Next routine inspection due: December 2026.

Inspector Notes

The tenant keeps the unit clean and tidy.

Unit 8B, Building C

Routine inspection report INS-2026-0105 for Unit 8B, Building C, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0105
- Date of inspection: 24 March 2026
- Inspector: Mei Tanaka
- Tenant: Phoebe Evans
- Tenant present: No
- Overall condition: Good

Condition by Room

- Kitchen: Good
- Bathroom: Good
- Living area: Good
- Bedrooms: Fair
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- Bedrooms: Water stain on the main bedroom ceiling.

Follow-up Actions

- Work order WO-6595 raised with Coastline Plumbing to investigate a possible leak from the unit above, due by 7 April 2026.
- Next routine inspection due: September 2026.

Inspector Notes

Minor wear and tear consistent with the age of the fittings.

Unit 8C, Building C

Routine inspection report INS-2026-0117 for Unit 8C, Building C, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0117
- Date of inspection: 11 May 2026
- Inspector: Samuel Okafor
- Tenant: Hana Walsh
- Tenant present: Yes
- Overall condition: Fair

Condition by Room

- Kitchen: Good
- Bathroom: Good
- Living area: Good
- Bedrooms: Good
- Laundry: Poor
- Balcony: Good
- Smoke alarms: One alarm failed the test (see Issues Found)

Issues Found

- Laundry: Cracked floor tile at the laundry entrance.
- Smoke alarms: Hallway smoke alarm failed the test.

Follow-up Actions

- Work order WO-6560 raised with Harbour Handyman Services to replace the cracked tile, due by 25 May 2026.
- Smoke alarm battery replaced on site by the inspector; alarm retested and working.
- Next routine inspection due: November 2026.

Inspector Notes

The unit is presented in good order overall.

Unit 9B, Building C

Routine inspection report INS-2026-0177 for Unit 9B, Building C, Harbourview Residences, 42 Quay Street, Port Ellison.

Inspection Details

- Inspection reference: INS-2026-0177
- Date of inspection: 25 June 2026
- Inspector: Grace Holloway
- Tenant: Wen O'Brien
- Tenant present: Yes
- Overall condition: Good

Condition by Room

- Kitchen: Good
- Bathroom: Good
- Living area: Good
- Bedrooms: Good
- Laundry: Good
- Balcony: Good
- Smoke alarms: Tested, all working

Issues Found

- No issues found. The unit is well maintained.

Follow-up Actions

- Next routine inspection due: December 2026.

Inspector Notes

Minor wear and tear consistent with the age of the fittings.