

HEAT EXCHANGER INSPECTION CHECKLIST
Equipment: E-201 (Shell & Tube Heat Exchanger)
Date: 20/03/2024
Inspector: R. Sharma
Revision 2

VISUAL INSPECTION

Item	Status	Notes
Tube sheet condition	PASS	No corrosion found
Shell flanges	PASS	Gaskets in good condition
Support structures	PASS	Bolts tightened to spec
Instrumentation PT-201	FAIL	Calibration due
Insulation integrity	PASS	Minor damage at inlet

PRESSURE TEST

Test Pressure: 12 bar
Duration: 30 minutes
Result: PASS · No leaks detected

FOULING ASSESSMENT

Shell side: Low fouling (within acceptable limits)
Tube side: Moderate fouling · cleaning scheduled

Next inspection due: 20/09/2024

Equipment IDs: E-201, PT-201, HX-201