Recommended heating-up schedules of castable refractories

Low Coment Castables for

maintained shall be 20 hours

25°C/hour

Please control such deviation within ±30°C from the standard one for any area and carry out the homogeneous heating up as much as possible.

Product

From 350°C to the operational

temperature

schedule shall be deviated from the standard one, area by area of the lining.

Heating-up schedules	Aluminum Industries Example: GIBRAM, ASAL-85Z	Example: Ramcrete, Drysic, Rheo- f ow WPC-S series	Conventional Castable Refractories Example: CA, LC and WPC series
From room temperature to 200°C	50°C/hour	50°C/hour	50°C/hour
Maintain a temperature of 200°C for certain hours calculated as per the instructions provided.	Calculate the time to be maintained considering the lining thickness. 10-mm thickness corresponds to 1 hour.	Calculate the time to be maintained considering the lining thickness. 20-mm thickness corresponds to 1 hour.	Calculate the time to be maintained considering the lining thickness. 20-mm thickness corresponds to 1 hour.
	Example: When the lining thickness is 200 mm, the time to be maintained shall be 20 hours.	Example: When the lining thickness is 200 mm, the time to be maintained shall be 10 hours.	Example: When the lining thickness is 200 mm, the time to be maintained shall be 10 hours.
From 200°C to 350°C	25°C/hour	25°C/hour	50°C/hour
Maintain a temperature of 350°C for certain hours calculated as per the instructions provided.	Calculate the time to be maintained considering the lining thickness. 10-mm thickness corresponds to 1 hour.	Calculate the time to be maintained considering the lining thickness. 20-mm thickness corresponds to 1 hour.	Calculate the time to be maintained considering the lining thickness. 20-mm thickness corresponds to 1 hour.
	Example: When the lining thickness is 200 mm, the time to be	Example: When the lining thickness is 200 mm, the time to be	Example: When the lining thickness is 200 mm, the time to be

Remarks: The heating-up schedule for drying in the above table is our recommended standard one to prevent cracks and explosive fractures. In actual heating up for drying, if the lining area to be dried is relatively broad, the actual heating up

Category

"RF" type Low Cement Castables

maintained shall be 10 hours

50°C/hour

maintained shall be 10 hours.

50°C/hour