



No: 43749975

DATE: 2020-06-17T21:00:00.000Z

LOCATION : **KEEMK** 

## **INWARD EQUIPMENT INTERCHANGE**

CONTAINER NO: MAGU2523324

22G0

SEAL -

DEST KEMBA

SHIPPING LINE : CMA CGM KENYA LTD

**VESSEL: EMIRATES ASANTE** 

TRANSPORTER: MURANGA

DRIVER: HESBON KEN


PARTY DELIVERING CONTAINER: MURANGA

B\L NO: 43749975

VOY NO:ESA/0740/2020

TRUCK NO: KCW001H

**DELIVERY NOTE:** 



## **Tally Report**

## MINOR DENTS AND SCRATCHES SEEN

Repair Code Description of Damage/Repair Qty Hours Labour Cost\$ Material Cost Total Cost

BSRF ST/1 Straighten Bottom Side Rail Flange upto first 15 cm 0.15 96

96

Prepared by: Kennedy Walucho

Repair Estimated by: Kennedy Walucho

Distribution: 1, Transporter: 2, Shpg Line 3 BBL