



No : 12734718

DATE: 2020-05-30T21:00:00.000Z

LOCATION : **KEEMK**

INWARD EQUIPMENT INTERCHANGE

CONTAINER NO :TEMU2861180

22G0

SEAL -

DEST KEMBA

SHIPPING LINE : INDUS LOGISTICS LTD

VESSEL: TSYT023590

111023330

TRANSPORTER: INDUS

DRIVER : KEN Walucho


PARTY DELIVERING CONTAINER: INDUS

B\L NO: 12734718

VOY NO:EMTY/0000/0000

TRUCK NO: KBC 234L

DELIVERY NOTE:



Tally Report

MINOR DENTS AND SCRATCHES SEEN

Repair Code	Description of Damage/Repair Qty	Hours Labour Cost\$	Material Cost Total Cost
BSRF ST/1	Straighten Bottom Side Rail Flange upto first 15 cm	0.15	96
BSRF ST/1	Straighten Bottom Side Rail Flange upto first 15 cm	0.15	96
BSRF ST/1	Straighten Bottom Side Rail Flange upto first 15 cm	0.15	96

288

Prepared by: boxback admin

Repair Estimated by: boxback admin

Distribution: 1, Transporter: 2, Shpg Line 3 BBL

