



No: 18073976

DATE: 2020-06-17T21:00:00.000Z

LOCATION: **KEEMK**

INWARD EQUIPMENT INTERCHANGE

CONTAINER NO: GAOU6121530

45G0

SEAL -

DEST KEMBA

SHIPPING LINE : CMA CGM KENYA LTD

VESSEL: **EMIRATES ASANTE**

TRANSPORTER : MURANGA

DRIVER : JOHN WAMALWA


PARTY DELIVERING CONTAINER: MURANGA

B\LN0:18073976

VOY NO:ESA/0740/2020

TRUCK NO: KBN 224L

DELIVERY NOTE:



Tally Report

MINOR DENTS AND SCRATCHES SEEN

Repair Code Description of Damage/Repair Qty Hours Labour Cost\$ Material Cost Total Cost

BSRF ST/1 Straighten Bottom Side Rail Flange upto first 15 cm 0.15 96

96

Prepared by : Kennedy Walucho Repair Estimated by: Kennedy Walucho

Distribution: 1, Transporter: 2, Shpg Line 3 BBL