## **Percentage Loss in Function** in Paretic Arm 8.0 Percentage Decrease in Energy 0.6 FMA: 37 0.4 FMA: 17 FMA: 13 0.2 FMA: 32 FMA: 7 0.0 FMA: 9 FMA: 21 -0.21Hz 1.5Hz 2.5Hz Resonant Frequency of Ball