

VAPLI Inspection Telemetry Report

Client: MUTHU_STORES | Date: 2026-06-26 | Generated: 26/06/2026 17:04:50

Group: PM6 OILTANKS

Asset Name	E q u i p m e n t s t a t u s	C o m m e n t s	O i l L e v e l	P r e d i c t e d O i l L e a k	T a n k O i l L e a k	R e a s o n f o r O i l L e a k	P r e s s u r e	D i f f P R	F i l t e r s t a t u s	T e m p e r a t u r e	B r e a t h e r s	B r e a t h e r O i l L e a k	H e a t E x c h a n g e r	O i l B u n d S t a t u s	T a n k S h i n e R a t i n g	F r o n t v i e w	S i d e v i e w (R i g h t)	S i d e v i e w (L e f t)	T o p v i e w	W a t e r P R	W a t e r D i f f e r e n t i a l P R	S h i n e r a t i n g A V G	C a p t u r e T i m e	
PM6 Flexo Hydraulic	R e p a i r	-	2	3 0	1	S y s t e m p i p e l e a k	1 / 2	- 1	B A D	1 1	A V E R A G E	N O T O K	R U N N I N G - N O L E A K	N O T O K	-	2	3	4	2	-	-	-	0 3 : 0 8 P M	
PM6 Unirun	Readings not taken																							
PM6 Kirma Hydraulic	Readings not taken																							
PM6 Flexo Lube	Readings not taken																							
PM6 Main Lube	Readings not taken																							

Group: PM6 GEARBOX

Asset Name	Oil Level	Input Shaft Seal	Output Shaft Seal	Breather	Leak From Cooler	Temperature	Cooler Fins	Cooler Temperature	Difference In Temperature	Fan Direction	Capture Time
PM6 M704	Readings not taken										

Group: PM3 OILTANKS

Asset Name	Equipment status	Comments	Oil Level	Predicted Oil Leak	Tank Oil Leak	Reason for Oil Leak	Pressure	Diff PR	Filtr status	Temperature	Breathers	Breather Oil Leak	Heat Exchanger	Oil Bund Status	Tank Sighting Rating	Front view	Side View (Right)	Side View (Left)	Top View	Shine rating AVG	Capture Time
PM3 Flexo Hydraulic	Readings not taken																				
PM3 Flexo Lube	Readings not taken																				
PM3 Main Lube	Readings not taken																				
PM3/PM6 Pope Reel Hydraulics	Readings not taken																				