

Release Notes

Document No. SW-RN-2026-SP-X-YAFU-RN

SP-X

AMI Yafuflash 7.01 Release Notes

Revision: 1.93

Published by Software R&D

AMI-CONFIDENTIAL | NDA Required

Copyright © 2026 American Megatrends International LLC.

All Rights Reserved.

AMI.

3095 Satellite Boulevard, Building 800, Suite 425,

Duluth, Georgia 30096, U.S.A

Property of AMI.



Document Change History

Date	Doc Version	Description
04/01/2020	1.01	Updated for 7.00.002 release
04/13/2020	1.02	Updated for 7.00.003 release
04/26/2020	1.03	Updated for 7.00.004 release
06/02/2020	1.04	Updated for 7.00.0010 release
06/21/2020	1.05	Updated for 7.00.0013 release
07/01/2020	1.06	Updated for 7.00.0015 release
07/06/2020	1.07	Updated for 7.00.0016 release
07/07/2020	1.08	Updated for 7.00.0017 release
07/12/2020	1.09	Updated for 7.00.0018 release
07/28/2020	1.10	Updated for 7.00.0019 release
08/01/2020	1.11	Updated for 7.00.0021 release
08/05/2020	1.12	Updated for 7.00.0022 release
08/05/2020	1.13	Updated for 7.00.0023 release
08/12/2020	1.14	Updated for 7.00.0024 release
08/18/2020	1.15	Updated for 7.00.0027 release
08/19/2020	1.16	Updated for 7.00.0028 release
08/21/2020	1.17	Updated for 7.00.0029 release
09/25/2020	1.18	Updated for 7.01.0031 release and updated Supported OS list
09/28/2020	1.19	Updated for 7.01.0032 release
10/08/2020	1.20	Updated for 7.01.0034 release
10/16/2020	1.21	Updated for 7.01.0035 release

11/11/2020	1.22	Updated for 7.01.0037 release
12/08/2020	1.23	Updated for 7.01.0038 release
12/14/2020	1.24	Updated for 7.01.0039 release and updated supported OS list
12/18/2020	1.25	Updated for 7.01.0040 release
12/29/2020	1.26	Updated for 7.01.0041 release
02/02/2021	1.27	Updated for 7.01.0042 release
03/23/2021	1.28	Updated for 7.01.0043 release
07/02/2021	1.29	Updated for 7.01.0049 release
07/12/2021	1.30	Updated for 7.01.0052 release
08/02/2021	1.31	Updated for 7.01.0054 release
08/20/2021	1.32	Updated for 7.01.0055 release
08/24/2021	1.33	Updated for 7.01.0056 release
09/17/2021	1.34	Updated for 7.01.0057 release
10/11/2021	1.35	Updated for 7.01.0059 release
12/06/2021	1.36	Updated for 7.01.0064 release and updated Supported OS list
12/21/2021	1.37	Updated for 7.01.0065 release
12/24/2021	1.38	Updated for 7.01.0067 release
01/05/2022	1.39	Updated for 7.01.0068 release
01/13/2022	1.40	Updated for 7.01.0069 release
01/25/2022	1.41	Updated for 7.01.0071 release
02/16/2022	1.42	Updated for 7.01.0072 release
03/15/2022	1.43	Updated for 7.01.0075 release
03/21/2022	1.44	Updated Supported OS list
04/12/2022	1.45	Updated for 7.01.0076 release

05/06/2022	1.46	Updated for 7.0.1.0077 release
05/19/2022	1.47	Updated for 7.0.1.0078 release
06/02/2022	1.48	Updated for 7.0.1.0079 release
06/07/2022	1.49	Updated for 7.01.0081 release
07/13/2022	1.50	Updated for 7.01.0084 release
07/21/2022	1.51	Updated for 7.01.0085 release
09/06/2022	1.52	Updated for 7.01.0086 release
09/12/2022	1.53	Updated for 7.01.0087 release
09/20/2022	1.54	Updated for 7.01.0088 release
09/30/2022	1.55	Updated for 7.01.0090 release
10/06/2022	1.56	Updated for 7.01.0091 release
10/19/2022	1.57	Updated for 7.01.0092 release
10/26/2022	1.58	Updated for 7.01.0093 release
11/24/2022	1.59	Updated for 7.01.0094 release and updated Supported OS list
12/08/2022	1.60	Updated for 7.01.0096 release
12/14/2022	1.61	Updated for 7.01.0097 release
01/09/2023	1.62	Updated for 7.01.0098 release
01/25/2023	1.63	Updated for 7.01.0099 release
02/24/2023	1.64	Updated for 7.01.0100 release
05/08/2023	1.65	Updated for 7.01.0101 release
05/16/2023	1.66	Updated for 7.01.0102 release
06/07/2023	1.67	Updated for 7.01.0104 release
06/26/2023	1.68	Updated for 7.01.0105 release
07/12/2023	1.69	Updated for 7.01.0106 release

08/17/2023	1.70	Updated for 7.01.0107 release
08/29/2023	1.71	Updated for 7.01.0108 release
09/22/2023	1.72	Updated for 7.01.0109 release
10/10/2023	1.73	Updated for 7.01.0110 release
10/25/2023	1.74	Updated for 7.01.0111 release
11/28/2023	1.75	Updated for 7.01.0112 release
12/12/2023	1.76	Updated for 7.01.0113 release
12/26/2023	1.77	Updated for 7.01.0114 release
02/01/2024	1.78	Updated for 7.01.0115 release
02/09/2024	1.79	Updated for 7.01.0116 release
02/20/2024	1.80	Updated for 7.01.0117 release
03/06/2024	1.81	Updated Supported Operating Systems & Updated for 7.01.0119 release
03/26/2024	1.82	Updated for 7.01.0120 release
05/09/2024	1.83	Updated for 7.01.0121 release
06/11/2024	1.84	Updated for 7.01.0122 release
08/22/2024	1.85	Updated for 7.01.0123 release
03/27/2025	1.86	Updated for 7.01.0127 release
06/17/2025	1.87	Updated for 7.01.0128 release
09/11/2025	1.88	Updated Supported Operating Systems & Updated for 7.01.0129 release
10/03/2025	1.89	Updated for 7.01.0130 release
10/21/2025	1.90	Updated for 7.01.0131 release
11/18/2025	1.91	Updated for 7.01.0132 release

01/22/2026	1.92	Updated Supported Operating Systems
02/24/2026	1.93	Updated for 7.01.0133 release

Contents

1	Release	8
2	Deliverables	8
3	Features	9
4	Supported Operating Systems	12
5	Version History	13

1 Release

- Yafuflash 7.01.0133

2 Deliverables

- For Windows
 - Yafuflash.exe
 - LIBIPMI.dll
 - amigendrv64.sys
- For Linux
 - Yafuflash
- For DOS
 - Yafuflash.exe
 - Yafuflash.sym
- AMI_Yafuflash_User_Guide_NDA.pdf
- AMI_Yafuflash_Release_Notes_NDA.pdf

3 Features

- Option to display information about current FW and new FW, FW Sections, and FW Versions.
- Option to FORCE BootLoader upgrade during full upgrade, and also skips user interaction in Interactive Upgrade mode.
- Option to Flash using Block by Block method.
- Option to Flash using OEM specific Netfunction.
- Option to preserve Config Module during full upgrade.
- Option to preserve all the configs by enabling preserve items in web.
- Option to skip user interaction and continues update process.
- Option to skip reselecting the active image.
- Options to split image.
- Option to interactive upgrade.
- Option to flash particular section Eg. -flash-conf, -flash-[www](#).
- Option to skip the CRC check (Only for Dual Image Support).
- Option to skip the FMH check (Only for Dual Image Support).
- Option to specify the peripheral (Only for Dual Image Support).
- Option to specify the Image to be updated.
- Option to activate peripheral devices.
- Option to give ini file as input. Inifile.
- Option to Flash HPM Image Component wise.
- Option to skip the reboot.
- Option to skip the BMC update with module by module.
- Option to preserve XXX configuration where XXX falls in sdr, fru, sel, ipmi, auth, net, ntp, web, snmp, ssh, kvm, syslog, redfish, and rsd.
- Option to replace the Signed Image Key in existing firmware.
- Option to skip flashing modules only if the versions are same.
- Option to use USB Medium.
- Option to use Network Medium.
- Option to use KCS Medium.
- Option to use alternate KCS port (Base address of Data Port and Status Port) when using KCS Medium.
- Option to preserve extlog configuration during firmware flash.
- Option to update image in SD Card.
- Add Changes for Windows driver Security.
- Yafuflash Show BIOS Firmware Version.
- Support BIOS Preserved Parameter Functions in Yafuflash.
- Support Redfish Preservation option in Yafuflash.
- Needed YAFU tool option to Skip Preserve Uboot Environment Variables.
- Option (pweb) to preserve tftp configuration file in Yafuflash.

- Option to Timeout based on Yafu size.
- Option to erase full SPI.
- Option to flash PFR component manager plugin (supports both Intel PFR and AMI PFR).
- Option to Read SPI data and Dump into file.
- Option to use decommission support.
- Option to use key cancellation support.
- Option to reboot BMC via YAFU. Allowed only in KCS medium.
- Option to initiate firmware update via YAFU with stateless changes.
- Option to specify CPLD device id (Only for CPLD update).
- Option to verify CPLD device interface (Only for CPLD update).
- Option to display YAFU command specific failure error code when flashing failed.
- Option to display information about current FW and new FW, FW Sections, FW Versions.
- Option to FORCE BootLoader upgrade during full upgrade and also skips user interaction in Interactive Upgrade mode.
- Option to flash using block by block method.
- Option to flash using OEM specific Netfunction.
- Option to preserve Config Module during full upgrade.
- Option to preserve all the configs by enabling preserve items in web.
- Option to skips user interaction and continues update process.
- Option to skip reselecting the active image.
- Option to flash split image.
- Option to flash particular section Eg. -flash-conf,-flash-[www](#).
- Option to interactive upgrade.
- Option to skip the CRC check (Onlyfor DualImageSupport)
- Option to skip the FMH check (Onlyfor DualImageSupport)
- Option to specify the peripheral (OnlyforDualImageSupport)
- Option to specify the Image to be updated.
- Option to activate peripheral devices.
- Option to give ini file as input.Inifile
- Option to Flash HPM Image Component wise.
- Option to skip the reboot.
- Option to skip the BMC update with module by module.
- Option to preserve XXXconfiguration. Where XXXfallsin sdr, fru, sel, ipmi, auth, net, ntp, web, snmp, ssh, kvm, syslog, redfish, and rsd.
- Option to replace the Signed Image Key in existing firmware.
- Option to skip flashing modules only if the versions are same.
- Option to use USB Medium.
- Option to use Network Medium.
- Option to use KCS Medium.

- Option to use alternate KCS port (Base address of Data Port, Status Port) when using KCS Medium.
- Option to preserve extlog configuration during firmware flash.
- Option to update image in SD Card.
- Add changes for Windows driver security.
- YafuFlash Show BIOS firmware version.
- Support BIOS preserved parameter functions in Yafuflash.
- Support Redfish preservation option in Yafuflash
- Needed YAFU tool option to skip preserving UBoot Environmental Variables.
- Option (pweb) to preserve tftp configuration file in Yafuflash.
- Option to erase full SPI.
- Option to Yafu timeout based Image size.
- Option to flash PFR component manager plugin.
- Option to Read SPI Data and Dump into file.
- Option to use decommission support.
- Option to use key cancellation support.
- Option to reboot BMC via YAFU. Allowed only in KCS medium.
- Option to initiate firmware update via YAFU with stateless changes.
- Option to specify CPLD device id (Only for CPLD update).
- Option to verify CPLD device interface (Only for CPLD update).
- Option to display YAFU command specific failure error code when flashing failed.
- Option to display -pfupdate and support BIOS component to do parallel firmware update.

4 Supported Operating Systems

The following operating systems support Yafuflash tool.

Server OS (In band - USB and KCS mediums)	Client OS (In band and Out of band)
Windows Server 2022 and 2025	Windows 10 and 11
Ubuntu Server 22.04 and 24.04 LTS	Ubuntu 22.04 and 24.04 LTS
RHEL/CentOS 8 and 9	Fedora 39 and 40
DOS (KCS medium alone)	Debian 11 and 12

5 Version History

- Ver 1.93 24/02/26
 - SPX-12582 - Yafuflash Tool is not working for any BMC / PCH Firmware updates.
- Ver 1.91 13/11/25
 - SPX-11183 - Yafuflash cannot display the complete BIOS firmware version.
- Ver 1.90 21/10/25
 - SPX-10913 - U-Boot Environment Variables Lost After Firmware Upgrade.
- Ver 1.89 03/10/25
 - SPX-10221 - When trying to do yafuflash PFR update with non-interactive mode, still its asks for options.
- Ver 1.88 11/09/25
 - SPX-10027 - AMI PFR Support with Core YAFU
- Ver 1.87 17/06/2025
 - SPX - 8624 - Cannot access WebUI after upgrading BMC via Yafuflash
- Ver 1.86 27/03/2025
 - SPX-7211 - Yafuflash shows the FW version with garbled characters
 - SPX-6754 - Upgrading with yafuv7.01.0125 version does not display the minor version number
 - SPX-5757 - Yafuflash "-npb" option not work when updating with different FW image
 - SPX-4388 - SPX Tools - Release repo update using CI/CD
- Ver 1.85 22/08/2024
 - SPX -3675: Yafuflash LAN cannot work on Fedora 38, 39, 40
- Ver 1.84 11/06/2024
 - SPX-2578: Yafuflash v7.01.0121 doesn't work by using hpm file which is at other folder
- Ver 1.83 09/05/2024
 - SPX-1696: SPX Tools - Build automation using CI/CD.
- Ver 1.82 26/03/2024
 - EIP 794798: YAFU KCS update in windows terminated by get device ID via ipmiutil cmd.
- Ver 1.81 06/03/2024
 - EIP 767038: Parallel firmware update support for multiple components.

- EIP 780099: CPLD FW update via i2c.
- Ver 1.80 20/02/2024
 - EIP 785252: Cannot update firmware via Yafuflash KCS in u-boot fwupdate mode.
- Ver 1.79 09/02/2024
 - EIP 771152: Verification failed if using option -autospi to update firmware via Yafuflash.
- Ver 1.78 01/02/2024
 - EIP 784881: Yafuflash failed when upgrade/downgrade firmware with "-smu" option.
- Ver 1.77 26/12/2023
 - EIP 781187: Cannot update BIOS fw via Yafuflash KCS, got error "Floating point exception (core dumped)".
- Ver 1.76 12/12/2023
 - EIP 777408: Coverity - SPX13 YAFU Flash [Part 1].
- Ver 1.75 11/28/2023
 - EIP 777132: Yafu Update with capsule image more than 32 mb fails.
- Ver 1.74 10/25/2023
 - EIP 761989: Need to add warning message in Yafuflash.
- Ver 1.73 10/10/2023
 - EIP 768801: Yafuflash failed when update firmware with "-smu" and "-fb".
- Ver 1.72 09/22/2023
 - EIP 767102: Parallel Bios firmware update fail to update due to verify error.
- Ver 1.71 08/29/2023
 - EIP 746352: Parallel firmware update support for components.
- Ver 1.70 08/17/2023
 - EIP 758664: YAFuflash ARM64/aarch64 cannot work via LAN interface.
- Ver 1.69 07/12/2023
 - EIP 749473: CPLD List will show garbled characters via Yafuflash.
- Ver 1.68 06/26/2023
 - EIP 750138: Amifldr64.sys needs to be updated/reviewed.
- Ver 1.67 06/07/2023
 - EIP 746343: Yafuflash tool does not work on server CentOS 9 (5.14 kernel).
 - EIP 746945: Yafuflash for BMC update is producing segmentation fault (core dumped) error.
- Ver 1.66 05/16/2023
 - EIP 738846: IPv6 link local address support on Yafuflash.
- Ver 1.65 05/08/2023

- EIP 741732: Yafuflash -pc functionality.
- Ver 1.64 02/24/2023
 - EIP 732816: "-pc" doesn't work when IPMI_AMI_OEM_NETFUN_SUPPORT change to 0x34 different image.
- Ver 1.63 01/25/2023
 - EIP 726575: Yafuflash will prompt "Existing Image and Current Image are Same" when update with different image.
 - EIP 727736: Upgrade using YafuTool with a secure boot signed image (SHA 512) with the existing BMC image (SHA 256) was unsuccessful.
- Ver 1.62 01/09/2023
 - EIP 724954: Add YAFU flash via IPMI over USB (-cd interface) in SPX-13.
- Ver 1.61 12/14/2022
 - EIP 722102: Porting bug fixes from LTS-v12 YAFU to LTS-v13 YAFU (v7).
- Ver 1.60 12/08/2022
 - EIP 696636: More error codes need to be added in YAFU.
 - EIP 711269: The MAC address of Image-2 will be lost after updated both images.
- Ver 1.59 11/24/2022
 - EIP 714599: In Redhat OS, the Yafuflash tool is unable to update BMC firmware.
- Ver 1.58 10/26/2022
 - EIP 711287: Cannot update firmware via Yafuflash KCS in u-boot fwupdate mode.
- Ver 1.57 10/19/2022
 - EIP 699285: Yafuflash failed with error "Exiting as IPMI Session timed out due to inactivity".
- Ver 1.56 10/06/2022
 - EIP 707760: Key Cancellation via Yafu flails with "invalid offset" error.
 - EIP 707761: Decommission via Yafu fails with error in memory allocation.
- Ver 1.55 09/30/2022
 - EIP 684268: jffs2 error occurred when upgrading with different extlog location image.
 - EIP 706910: Yafuflash will stuck at "Prepare Device is in processing" when Device is already in Firmware Update Mode.
- Ver 1.54 09/20/2022
 - EIP 704394: Option to check the CPLD device interface.

- Ver 1.53 09/12/2022
 - PLDM/RAID FW update support with PFR TP enabled using YAFU tool.
- Ver 1.52 09/06/2022
 - EIP 702538: Yafuflash do not show existing image BIOS Version.
- Ver 1.51 07/21/2022
 - EIP 693758: Yafuflash v7.01.0078 not working on Ubuntu 22.04 OS.
- Ver 1.50 07/13/2022
 - EIP 550256: Removal of Write/Erase Flash Command in YAFU tool.
 - EIP 687114: PCIe Devices and PCIe Function Health status is not getting updated.
 - EIP 689916: BMC will not reset automatically after cancel to update Image-2.
- Ver 1.49 06/07/2022
 - EIP 674125: Fixed Coverity issue for Large stack use (STACK_USE).
 - EIP 682798: BMC password reset to default after flashing incorrect image via Yafuflash.
- Ver 1.48 06/02/2022
 - EIP 674928: Failed to use "Version compare flash" to upgrade BMC firmware.
- Ver 1.47 05/19/2022
 - EIP 672296: Need a stateless Yafu BMC Changes Porting from LTS-v12 to LTS- v13 (Added bug fix in yafutool related firmware stages displaying while flashing).
- Ver 1.46 05/06/2022
 - EIP 672296: Need a stateless Yafu BMC Changes Porting from LTS-v12 to LTS-v13.
- Ver 1.45 04/12/2022
 - EIP 674187: Yafuflash shows confused messages when signed-hashed verification failed.
- Ver 1.44 03/21/2022
 - EIP 642097: Supported Operation system for YafuFlash USB Medium (server edition).
- Ver 1.43 03/15/2022
 - EIP 669464: FwUpd.CPLD.HPM.YafuFlash.KCS fail.
 - YAFU flash fails via KCS medium with "Invalid Firmware Upload selector" when compiling using RHEL OS.
 - EIP 658502: Add rebootbmc option in YAFU.
- Ver 1.42 02/16/2022

- EIP 661555: Yafuflash support ARM64/aarch64 architecture.
- Ver 1.41 01/25/2022
 - EIP 652611: Cannot recovery corrupted Image-1 by Yafuflash.
 - EIP 661452: PFR Firmware update via KCS not working.
- Ver 1.40 01/13/2022
 - EIP 637251: multip Yafu issues seen in RR11-5/7 and LTS-12.
 - SCM CPLD update not supporting custom "-netfn".
- Ver 1.39 01/05/2022
 - EIP 658502: Add rebootbmc option in YAFU.
- Ver 1.38 12/24/2021
 - EIP 616061: Yafuflash to support an option for SCM CPLD update.
 - EIP 654178: CPLD capsule update fails via YafuflashTool.
 - EIP 655061: Seamless update options given via WebUI and Yafuflash are different.
 - YafuflashTool needs to check CPLD status and BIOS status prior to allowing seamless update.
- Ver 1.37 12/21/2021
 - EIP 651471: Yafuflash display "upgrading" when uploading image.
 - EIP 652351: Cannot get FW info by Yafuflash (IPMI restart after failure occurred).
- Ver 1.36 12/06/2021
 - EIP 639668: amifldr.sys not getting unloaded when exited abnormally or when user presses ctrl+c.
 - EIP 633392: BMC Active Image Immediate Update via Yafuflash on Windows 10 failed.
 - EIP 647392: Firmware with Yafuflash with win64 not working.
 - EIP 604072: Yafuflash shows error message as follows "Error: While deactivating the device" when update firmware via KCS.
 - Seamless Update: YAFU code changes for seamless update.
 - EIP 628987: ME will not reload after update BIOS FW.
 - EIP 629533: Yafuflash displayed fw info incorrectly and had error during update Image-2.
 - EIP 646885: Error message shows during the yafuflash update.
- Ver 1.35 10/11/2021
 - Analysis on retry flashing in case of failure.
 - EIP 631035: sel entry is not getting preserved when we do FW update via YAFU with -pc.
- Ver 1.34 09/17/2021
 - EIP 609600: Interruption during YAFU firmware update results in undefined behavior in BMC.
- Ver 1.33 08/24/2021

- EIP 630351: BMC boot failed after upgrade from 1/1 to 7/12 LTS-v13 build.
- EIP 595824: U-boot gone after flashing TB2 image through Web UI.
- Ver 1.32 08/20/2021
 - EIP 629817: Key Cancellation & Key Decommissioning Support in YAFU.
- Ver 1.31 08/02/2021
 - EIP 602998: Yafuflash section-based update failed via KCS medium (Error in Free Memory).
 - EIP 625761: Yafuflash shows garbled text before update customer's BIOS image.
- Ver 1.30 07/12/2021
 - EIP 622230: [PFR] PFR image update from KCS interface.
 - EIP 623224: Yafuflash KCS update is failing with Yafuflash - Firmware Upgrade Utility v7.01.0048.
- Ver 1.29 07/02/2021
 - EIP 525915: Yafuflash change for PLDM firmware update for fixing PRJ macro definition to distinguish different PLDM Specification support.
 - EIP 615779: Yafuflash via USB medium failed (ERROR: Module ipmi_msghandler is in use by: ipmi_ssif).
 - EIP 616802: PLDM firmware update of the BCM Switch via Yafuflash (or UI) fails.
 - EIP 579603: Cannot update BIOS by yafuflash KCS.
 - EIP 609989: Yafuflash memory corruption when update "boot" module by option "-i".
 - EIP 609541: Cannot update BMC firmware via yafu KCS medium (Error: GetAllBootVars failed).
 - EIP 614756: "GetAllBootVars failed" when using latest Yafuflash with -fb option on previous BMC firmware.
 - EIP 614183: Option "-nr" should be able to work when "extendedlog_support" is enabled.
 - EIP 606366: Error "Exiting as IPMI Session timed out due to inactivity" occurred during update different image by Yafuflash.
- Ver 1.28 03/23/2021
 - EIP 592165: Need Yafuflash show messages for some cases in active tree.
 - EIP 599652: Yafuflash tool will hang if BMC IPMI interfaced is abled.
 - EIP 600959: Typo in help info of Yafuflash.
- Ver 1.27 02/02/2021
 - EIP 591227: Errors in Yafuflash on Dual Image, becomes unresponsive.
 - EIP 567040: Not able to reboot the BMC after doing Yafuflash with no reboot option.
- Ver 1.26 12/29/2020
 - EIP 585300: No error messages seen when doing FW with both active and recover option in YAFU.
- Ver 1.25 12/18/2020

- EIP 579403: Need option to have a SPI dump from BMC.
- Ver 1.24 12/14/2020
 - EIP 576853: Cannot update firmware via USB medium. (Segmentation fault).
 - EIP 566883: Yafuflash cannot progress to uploading phase, BMC hang at FW update mode and restart after 5400 seconds.
 - EIP 571790: [Yafuflash] The display in Yafuflash update BIOS is abnormal.
 - EIP 557116: Yafuflash shows error "SetBootConfig failed" when flash via KCS with option "-fb".
 - EIP 529961: Why verify firmware stage fail didn't show any errors.
 - EIP 584139: Document update.
- Ver 1.23 12/08/2020
 - EIP 565254: Yafuflash "-msi" is asking items to be preserved while getting image info every time.
- Ver 1.22 11/11/2020
 - EIP 553033: Yafuflash support MSCC Raid card firmware update.
 - EIP 575525: Yafu flash via KCS medium not working.
- Ver 1.21 10/16/2020
 - EIP527706: Getting "Segmentation fault (core dumped)" in Yafu utility when we interrupt the flash by disconnecting the LAN Cable.
- Ver 1.20 10/08/2020
 - EIP570993: Need to fix bugs found in PFR Support in YAFU.
 - EIP555999: Segmentation fault occurred when using -f-XXX to flash more than 8 modules.
- Ver 1.19 09/28/2020
 - EIP552685: Segmentation fault occurred when flashing both images with preserve configuration.
 - EIP551400: BMC environment variables are cleared, and BMC stops at u-boot after flashing both the images with Yafu utility.
- Ver 1.18 09/21/2020
 - EIP549183: Yafuflash DOS cannot reset BMC after firmware update was completed.
 - EIP564497: The grammatical errors have been found in yafuflash.
- Ver 1.17 08/21/2020
 - EIP559159: YAFU Changes for PFR.
- Ver 1.16 08/19/2020
 - EIP 554158: Yafu timer uses the default value, and it's not based on the image size, flashing medium and speed.

- Ver 1.15 08/18/2020
 - EIP 559626: Driver is not unloaded on YAFU Exit.
- Ver 1.14 08/12/2020
 - EIP 555332: Yafuflash is not throwing any error for the user which doesn't have IPMI messaging enabled.
- Ver 1.13 08/05/2020
 - EIP 555347: ieo option is not working properly in YAFU flash.
- Ver 1.12 08/05/2020
 - EIP 556939: CPLD Firmware Update with YAFU 7.0.20 is failing in MSFT Platform.
- Ver 1.11 08/01/2020
 - EIP 553013: PFR Support via YAFU.
- Ver 1.10 07/28/2020
 - EIP 553240: Yafu tool v7.00.0017, gives failure print while flashing FW with option – fe in C2030.
- Ver 1.09 07/12/2020
 - EIP 548880: -flash-conf and -preserve-config.
- Ver 1.08 07/07/2020
 - EIP 534487: -fe option included in help content in Yafuflash tool.
- Ver 1.07 07/06/2020
 - EIP 534487: KCS medium doesn't work with –fe option in msft platform.
- Ver 1.06 07/01/2020
 - EIP 539602: Firmware upgrade failed from LTS12-update-2.06 to LTS12-update-3.00_RC1 with option "-pc"
 - EIP 549884: Yafu tool v7.0.13, gives failure print while flashing with option –fb.
 - EIP 550255: YAFU tool with -mse option gives error.
- Ver 1.05 06/21/2020
 - EIP 516753: values sometimes get mismatched while flashing through YAFU Tool.
 - EIP 521249: Yafuflash KCS firmware Update failed.
 - EIP 540791: Yafuflash cannot progress to Uploading phase, BMC hang at fw update mode and restart after 5400 seconds.
 - EIP 542776: Yafu tool version 6.64 fails to do firmware update in MSFT platforms.
 - EIP 543062: Yafu tool fails in updating BMC firmware while using alternate KCS port.
 - EIP 544234: Document update yafuflash -rp option.

- Ver 1.04 06/02/2020
 - EIP 487983: Preserve Configuration options for UI and for YAFU should be the same but actually web is missing from Yafu.
 - EIP 527794: Yafuflash DOS cannot flash fw with message "Error while parsing the file".
 - EIP 529136: Firmware update fails when downgrade from 3.00_TB4 to 2.06 with option "-pc".
 - EIP 531013: using 18.04 gcc 7.5.0 to build Yafuflash, will have Segmentation fault error.
 - EIP 534487: Erase Full SPI option in BMC Flash tool.
 - EIP 543058: Replacing public key option is removed in latest YAFU tool.
 - Ver 1.03 04/26/2020
 - EIP 511161: Option to skip Read/Compare and write in YAFU firmware.
 - Ver 1.02 04/13/2020
 - EIP 532237: Unable to Flash Primary Image alone if Uboot Versions Mismatch.
 - EIP 529111: The SEL log cannot be preserved with option "-pc" by Yafuflash.
 - EIP 531733: [Yafuflash] Command Yafuflash with option info is not worked properly.
 - Ver 1.01 04/01/2020
 - EIP 501973: Add Driver Changes in Yafuflash.
 - EIP 476310: Yafuflash shows BIOS Firmware Version.
 - EIP 502985: Support BIOS Preserved Parameter Functions in Yafuflash.
 - EIP 510492: Support Redfish Preservation option in Yafuflash.
 - EIP 511159: Needed YAFU tool option to skip Preserve Uboot Environment Variables.
 - Ver 1.00 02/27/2020
- Initial release