**Steering Noise Diagnostic Report** 

1. Diagnosis:

The noise you've reported while turning the steering wheel is most likely caused by one of the following:

- Worn-out or dry suspension bushings

- Loose or damaged tie rods or ball joints

- Power steering pump issues or fluid leaks

- Steering rack mount deterioration

An inspection under the hood and near the wheels can often reveal visual signs of leakage, loose

components, or worn parts.

2. Personalized Message:

Thanks for using MyAutoSound! Identifying steering noise early can prevent larger issues. Based on the

sound you've identified, it's likely a mechanical wear issue. This type of noise is common and fixable. You're

already taking the right step by investigating it.

3. GRAVITY Level:

Medium - While the issue might not require immediate emergency intervention, it can worsen over time and

affect your control of the vehicle.

4. DANGER Level:

Moderate - A failing steering component could affect handling, especially in emergency maneuvers or tight

turns.

5. Rough Cost Estimate:

- Tie rod end replacement: \$100 - \$300

- Ball joint replacement: \$150 - \$400

- Steering rack repairs: \$500 - \$1,200

- Fluid flush or pump fix: \$80 - \$300

6. Next Recommended Step:

If you're comfortable, you can:

- Check the power steering fluid level and look for leaks.

- Turn the wheel left and right while the car is stationary to reproduce the sound and localize it.

- Look under the car for loose parts around the wheel area.

## **Steering Noise Diagnostic Report**

If unsure,	bring your	vehicle	to a	trusted	garage	or	mechanic	to	avoid	worse	ening	the	situation.	Mention	the
specific noise and circumstances (e.g., 'squeak when turning at low speed').															