## Worksheet 5 - Solution

## **PART 1: Mass-Spring Systems**


1) In the following system, the input is the angular displacement  $\phi$  of the end of the shaft, and the output is the angular displacement  $\theta$  of the inertia J. The shafts have torsional stiffnness  $k_1$  and  $k_2$ . The equilibrium position corresponds to  $\phi = \theta = 0$ . Derive the equation of motion and find the transfer function  $\Theta(s)/\Phi(s)$ .

From the free-body diagram, considering the CW as the positive direction, apply Newton's second law.

$$-k_1(\theta - \phi) - k_2\theta = J\ddot{\theta}$$

The differential equation model of system is obtained.

$$J\ddot{\theta} + (k_1 + k_2)\theta = k_1\phi$$




Take Laplace transform:


$$Js^2\theta(s) + (k_1 + k_2)\theta(s) = k_1\phi(s)$$


Form the equation as a transfer function model, where the input is the angular displacement  $\phi$  of the end of the shaft, and the output is the angular displacement  $\theta$  of the inertia J:

$$\frac{\theta(s)}{\phi(s)} = \frac{k_1}{Js^2 + k_1 + k_2}$$

2) The following figure models the three shafts as massless torsional springs. When  $\theta_1=\theta_2=0$ , the springs are at their free lengths. Derive the equations of motion with the torque  $\tau_2$  as the input.







From the free-body diagram, considering the CW as the positive direction, apply Newton's second law:

Inertia 
$$J_1 \rightarrow -k_1\theta_1 - k_2(\theta_1 - \theta_2) = J_1\ddot{\theta}_1$$

Inertia 
$$J_2 \rightarrow \tau_2(t) - k_2(\theta_2 - \theta_1) - k_3\theta_2 = J_2\ddot{\theta}_2$$

Simplify to obtain the equation of motion of the system

$$J_1 \ddot{\theta}_1 + (k_1 + k_2)\theta_1 - k_2\theta_2 = 0$$

$$\tau_2(t) = J_2 \ddot{\theta}_2 + (k_2 + k_3)\theta_2 - k_2 \theta_1$$

MENG 3020 Worksheet 5 -Solution

3) Consider the spur gear shown in the following figure. The input shaft (shaft 1) is connected to a motor that produces a torque  $\tau_1$  at a speed  $\omega_1$ , and drives the output load shaft (shaft 2). One use of such a system is to increase the effective motor torque.  $\theta_1$  is the input rotation and  $\theta_2$  is the output rotation.

a) Derive the expression for the equivalent inertia  $J_e$  felt on the input shaft, and obtain the equation of motion in terms of the displacement  $\theta_1$ .

The equivalent inertia felt on the input shaft is:

$$J_e = J_1 + J_2 \left(\frac{N_1}{N_2}\right)^2$$


The equivalent torque in the input shaft is:

$$\tau_e = \tau_1 + \tau_2 \left(\frac{N_1}{N_2}\right)$$


where,  $\tau_2\left(\frac{N_1}{N_2}\right)$  is the reflected torque from shaft 2 to shaft 1.

The equation of motion in terms of  $\theta_1$  is:

$$\tau_e = J_e \ddot{\theta}_1 \quad \rightarrow \quad \tau_1 + \tau_2 \left(\frac{N_1}{N_2}\right) = \left[J_1 + J_2 \left(\frac{N_1}{N_2}\right)^2\right] \ddot{\theta}_1$$



$$\frac{\tau_1}{\tau_2} = \frac{\theta_2}{\theta_1} = \frac{N_1}{N_2} = \frac{\omega_2}{\omega_1}$$



b) If the inertias are  $J_1=0.1~kg.m^2$  for the motor shaft and  $J_2=0.4~kg.m^2$  for the load shaft. The motor speed  $\omega_1$  is five times faster than the load speed  $\omega_2$ , so this device is called a *speed reducer*. Obtain the equation of motion in terms of  $\omega_2$ . Assuming that the motor torque  $\tau_1$  and load torque  $\tau_2$  are given.

From the given speed information we have:

$$\frac{\omega_2}{\omega_1} = \frac{1}{5} \quad \rightarrow \quad \frac{N_1}{N_2} = \frac{1}{5}$$

The equivalent inertia is:

$$J_e = J_1 + J_2 \left(\frac{N_1}{N_2}\right)^2 = 0.1 + 0.4 \left(\frac{1}{5}\right)^2 = 0.116 \text{ kg. } m^2$$

Since  $\ddot{\theta}_1 = \dot{\omega}_1$ , the equation of motion in terms of  $\omega_1$  is:

$$\tau_1 + \tau_2 \left(\frac{N_1}{N_2}\right) = J_e \dot{\omega}_1 \quad \rightarrow \quad \tau_1 + \frac{\tau_2}{5} = 0.116 \dot{\omega}_1$$

From the relation of  $\omega_1=5\omega_2$ , we can find the equation of motion in terms of  $\omega_2$ :

$$\tau_1 + \frac{\tau_2}{5} = 0.116\dot{\omega}_1 \longrightarrow \tau_1 + \frac{\tau_2}{5} = 0.58\dot{\omega}_2$$

2

4) For the system shown in the following figure, assume that the shaft inertias are small. The remaining inertias in kg.  $m^2$  are  $J_1=0.005$ ,  $J_2=0.01$ ,  $J_3=0.02$ ,  $J_4=0.04$ , and  $J_5=0.2$ . The speed ratios are:

$$\frac{\omega_1}{\omega_2} = \frac{3}{2}, \quad \frac{\omega_2}{\omega_3} = 2$$

Obtain the equation of motion in terms of  $\omega_3$ . Assume that the torque  $\tau$  is given.

From the speed ratios we have:

$$\frac{N_2}{N_1} = \frac{\omega_1}{\omega_2} = \frac{3}{2}$$
 and  $\frac{N_3}{N_2} = \frac{\omega_2}{\omega_3} = 2$ 

Reflect all inertias to shaft 3.

$$J_e = \left( (J_4 + J_1) \left( \frac{N_2}{N_1} \right)^2 + J_2 \right) \left( \frac{N_3}{N_2} \right)^2 + J_3 + J_5$$


$$J_e = \left( (0.04 + 0.005) \left( \frac{3}{2} \right)^2 + 0.01 \right) (2)^2 + 0.02 + 0.2 = 0.665 \, kg. \, m^2$$

Reflected torque in shaft 3:

$$\tau_e = \tau \left(\frac{N_2}{N_1}\right) \left(\frac{N_3}{N_2}\right) = \tau \left(\frac{3}{2}\right)(2) = 3\tau$$



$$\tau_e = J_e \dot{\omega}_3 \quad \rightarrow \quad 3\tau = 0.665 \dot{\omega}_3$$





## **PART 2: Mass-Spring-Damper Systems**


5) Represent the rotational mechanical system shown below in the state-space form, where  $heta_1(t)$  is the output.

Reflect all components and the torque and displacement from input side 1 to side 2:

$$\tau_e(t) = \tau(t) \left(\frac{N_2}{N_1}\right) = \tau(t) \left(\frac{100}{25}\right) = 4\tau(t)$$

$$\theta_{1e}(t) = \theta_1(t) \left( \frac{N_1}{N_2} \right) = \theta_1(t) \left( \frac{25}{100} \right) = \frac{1}{4} \theta_1(t)$$

$$J_{1e} = J_1 \left(\frac{N_2}{N_1}\right)^2 = (100) \left(\frac{100}{25}\right)^2 = 1600 \ kg. m^2$$



$$\frac{\tau_1}{\tau_2} = \frac{\theta_2}{\theta_1} = \frac{N_1}{N_2} = \frac{\omega_2}{\omega_1}$$

MENG 3020 Worksheet 5 -Solution

$$T_e \theta_{1e}$$
 $\theta_2$ 
 $100 \text{ N-m/rad}$ 
 $\theta_2$ 
 $\theta_{100 \text{ N-m-s/rad}}$ 

The equation of motion is:

Inertia 
$$J_{1e} \rightarrow \tau_e(t) - K(\theta_{1e}(t) - \theta_2(t)) = J_{1e}\ddot{\theta}_{1e}(t) \rightarrow 4\tau(t) - 100\left(\frac{1}{4}\theta_1(t) - \theta_2(t)\right) = 1600\left(\frac{1}{4}\ddot{\theta}_1(t)\right)$$

$$Egn.(1) \rightarrow 400\ddot{\theta}_1(t) + 25\theta_1(t) - 100\theta_2(t) = 4\tau(t)$$

Inertia 
$$J_2 \rightarrow -K(\theta_2(t) - \theta_{1e}(t)) - D\dot{\theta}_2(t) = J_2\ddot{\theta}_2(t) \rightarrow -100(\theta_2(t) - \frac{1}{4}\theta_1(t)) - 100\dot{\theta}_2(t) = 50\ddot{\theta}_2(t)$$

$$Eqn.(2) \rightarrow 50\ddot{\theta}_2(t) - 25\theta_1(t) + 100\theta_2(t) + 100\dot{\theta}_2(t) = 0$$

Define the state variables:

$$q_1(t) = \theta_1(t)$$

$$q_2(t) = \dot{\theta}_1(t)$$

$$q_3(t) = \theta_2(t)$$

$$q_4(t) = \dot{\theta}_2(t)$$

Find the first derivative of the state variables and rewrite them in terms of the state variables and the input.

$$\dot{q}_1(t) = \dot{\theta}_1(t) \quad \rightarrow \quad \dot{q}_1(t) = q_2(t)$$

$$\dot{q}_2(t) = \ddot{\theta}_1(t) \quad \rightarrow \quad \dot{q}_2(t) = \frac{1}{400} \left( 4\tau(t) - 25\theta_1(t) + 100\theta_2(t) \right) = 0.01\tau(t) - 0.0625q_1(t) + 0.25q_3(t)$$

$$\dot{q}_3(t) = \dot{\theta}_2(t) \quad \rightarrow \quad \dot{q}_3(t) = q_4(t)$$

$$\dot{q}_4(t) = \ddot{\theta}_2(t) \quad \rightarrow \quad \dot{q}_4(t) = \frac{1}{50} \Big( 25\theta_1(t) - 100\theta_2(t) - 100\dot{\theta}_2(t) \Big) = 0.5x_1(t) - 2q_3(t) - 2q_4(t)$$

Find the output in terms of the state variables and the input.

$$y(t) = \theta_1(t) = q_1(t)$$


The system model has 4 state variables, 1 input, and 1 output.

Form the state equation and the output equation in the standard matrix-vector form.

State Equation 
$$\rightarrow \begin{bmatrix} \dot{q}_1(t) \\ \dot{q}_2(t) \\ \dot{q}_3(t) \\ \dot{q}_4(t) \end{bmatrix} = \begin{bmatrix} 0 & 1 & 0 & 0 \\ -0.0625 & 0 & 0.25 & 0 \\ 0 & 0 & 0 & 1 \\ 0.5 & 0 & -2 & -2 \end{bmatrix} \begin{bmatrix} q_1(t) \\ q_2(t) \\ q_3(t) \\ q_4(t) \end{bmatrix} + \begin{bmatrix} 0 \\ 0.01 \\ 0 \\ 0 \end{bmatrix} \tau(t)$$

Output Equation 
$$\rightarrow$$
  $y(t) = \begin{bmatrix} 1 & 0 & 0 & 0 \end{bmatrix} \begin{bmatrix} q_1(t) \\ q_2(t) \\ q_3(t) \\ q_4(t) \end{bmatrix} + \begin{bmatrix} 0 \end{bmatrix} \tau(t)$ 

6) Find the transfer function  $\theta_2(s)/T(s)$ , for the rotaional mechanical system with greas as shown below:




Reflect all components and the torque from side 1 to side 2:

$$\tau_e(t) = \tau(t) \left(\frac{N_2}{N_1}\right) = \tau(t) \left(\frac{50}{25}\right) = 2\tau(t)$$

$$J_e = J \left(\frac{N_2}{N_1}\right)^2 = (1) \left(\frac{50}{25}\right)^2 = 4 \, kg. \, m^2$$

$$D_e = D \left(\frac{N_2}{N_1}\right)^2 = (1) \left(\frac{50}{25}\right)^2 = 4 \, N. \, m. \, s/rad$$



Find the equation of motion:

Inertia 
$$J_e \rightarrow \tau_e(t) - D_e \left( \dot{\theta}_e(t) - \dot{\theta}_2(t) \right) = J_e \ddot{\theta}_e(t) \rightarrow 2\tau(t) - 4 \left( \dot{\theta}_e(t) - \dot{\theta}_2(t) \right) = 4 \ddot{\theta}_e(t)$$

Point  $A \rightarrow -D_e \left( \dot{\theta}_2(t) - \dot{\theta}_e(t) \right) - K \left( \theta_2(t) \right) = 0 \rightarrow 4 \left( \dot{\theta}_2(t) - \dot{\theta}_e(t) \right) + 4 \theta_2(t) = 0$ 

Taking Laplace transform and form as a transfer function model:

$$2T(s) - 4s\theta_e(s) + 4s\theta_2(s) = 4s^2\theta_e(s)$$
 Eqn. (1)  
 $4s\theta_2(s) - 4s\theta_e(s) + 4\theta_2(s) = 0$  Eqn. (2)

Find  $\theta_e(s)$  from Eqn. (2) and substitute in Eqn. (1):

From Eqn. (2) 
$$\rightarrow \theta_e(s) = \frac{(s+1)}{s}\theta_2(s)$$

$$2T(s) - 4s \left(\frac{(s+1)}{s}\theta_2(s)\right) + 4s\theta_2(s) = 4s^2 \left(\frac{(s+1)}{s}\theta_2(s)\right)$$

$$\to 2T(s) - 4(s+1)\theta_2(s) + 4s\theta_2(s) = 4s(s+1)\theta_2(s)$$

 $2T(s) - 4s\theta_2(s) - 4\theta_2(s) + 4s\theta_2(s) = 4s^2\theta_2(s) + 4s\theta_2(s)$ 

$$\rightarrow \frac{\theta_2(s)}{T(s)} = \frac{2}{4s^2 + 4s + 4} = \frac{1/2}{s^2 + s + 1}$$

MENG 3020 Worksheet 5 -Solution


7) The following figure shows a drive train with a spur-gear pair. The first shaft turns  $N_2/N_1$  times faster than the second shaft. Develop a model of the system including the elasticity of the second shaft. Assume the first shaft is rigid, and neglect the gear and shaft masses. The input is the applied torque  $\tau_1$ . The outputs are the angles  $\theta_1$  and  $\theta_3$ .


Assume that 
$$\frac{N_2}{N_1} = N$$

Reflect all components and the torque and the displacement from side 1 to side 2:

$$\begin{split} &\tau_{1e}(t) = \tau_1(t) \left(\frac{N_2}{N_1}\right) = N \tau_1(t) \\ &\theta_2(t) = \theta_1(t) \left(\frac{N_1}{N_2}\right) = \frac{1}{N} \theta_1(t) \end{split}$$

$$J_{1e} = J_1 \left(\frac{N_2}{N_1}\right)^2 = N^2 J_1$$





Find the equation of motion:

Inertia 
$$J_{1e} \rightarrow \tau_{1e}(t) - k_T \left(\theta_2(t) - \theta_3(t)\right) = J_{1e}\ddot{\theta}_2(t)$$

$$\rightarrow N\tau_1(t) - k_T \left(\frac{1}{N}\theta_1(t) - \theta_3(t)\right) = (N^2J_1)\left(\frac{1}{N}\ddot{\theta}_1(t)\right)$$

$$\rightarrow N^2\tau_1(t) - k_T \left(\theta_1(t) - N\theta_3(t)\right) = N^2J_1\ddot{\theta}_1(t) \qquad Eqn. (1)$$

Inertia 
$$J_2 \rightarrow -k_T \left(\theta_3(t) - \theta_2(t)\right) - c_T \left(\dot{\theta}_3(t)\right) = J_2 \ddot{\theta}_3(t)$$

$$\rightarrow -k_T \left(\theta_3(t) - \frac{1}{N}\theta_1(t)\right) - c_T \left(\dot{\theta}_3(t)\right) = J_2 \ddot{\theta}_3(t)$$

$$\rightarrow -k_T \left(\theta_3(t) - \frac{1}{N}\theta_1(t)\right) - c_T \left(\dot{\theta}_3(t)\right) = J_2 \ddot{\theta}_3(t) \qquad \textit{Eqn. (2)}$$

The system model consists of Eqn. (1) and Eqn. (2).

$$\begin{cases} N^2\tau_1(t)-k_T\big(\theta_1(t)-N\theta_3(t)\big)=N^2J_1\ddot{\theta}_1(t) \\ -k_T\bigg(\theta_3(t)-\frac{1}{N}\theta_1(t)\bigg)-c_T\bigg(\dot{\theta}_3(t)\bigg)=J_2\ddot{\theta}_3(t) \end{cases} \rightarrow \begin{cases} N^2\tau_1(t)=N^2J_1\ddot{\theta}_1(t)-N\theta_3(t)+k_T\theta_1(t) \\ \vdots \vdots \vdots \\ J_2\ddot{\theta}_3(t)+c_T\dot{\theta}_3(t)+k_T\theta_3(t)-\frac{k_T}{N}\theta_1(t)=0 \end{cases}$$

6