## SURVEYING AND MAPPING DIVISION

## Alberta Survey Control Marker (ASCM) Information MASCOT DSS-1

	MASCOT DSS-1
Horz Datum NAD83 Updated: 1994-05-24	ASCM 68189
Latitude 50 56 28.52082 dms	Marker Installed 79-12
Longitude 114 07 19.09312 dms Horz Class INTEGRATED , ORDER 2	Tablet Markings 643-8.48
Horz Class INTEGRATED , ORDER 2	Date Printed 2025-08-03
	Date Printed 2025-08-03 Last Updated 2018-02-13 Mapsheet Name CALGARY F Mapsheet Number 5643 - 008
Vert Datum CVD28 Updated: 2001-02-07	Mapsheet Number 5643 - 008
Elevation 1104.759 m	For current information call Geodetic Survey
Vert Class INTEGRATED , SPIRIT LEVELS	(780) 427-3143 FAX: (780) 427-1493 Marker Condition GOOD 91-03-26
·	
3TM COORDINATES	ADJACENT MARKERS (calculated) Updated: 2018-02-13
	- The state of the
Scale Factor 0.999900 At Ref Mer 114	ASCM Tablet Horizontal Std PPM/ Grid/ Grnd Grid Std T-t To Markings Distance Dev Order Factor Bearing Dev Corr (m)(cm) (dms) (s) (s) 55442 643-8.86 191.694 1 52/2 0.999730 172 50 34.20 4.0 0.00 46250 643-8.47 259.569 1 42/2 0.999730 270 09 09.25 3.2 0.00 265975 643-8.41 310.037 1 35/2 0.999731 109 34 04.62 3.0 0.00 463679 643-8.93 348.942 1 46/2 0.999729 50 46 52.53 3.6 0.00 463664 643-8.85 377.298 1 40/2 0.999730 213 40 39.81 3.5 0.01 135483 643-8.87 393.175 1 33/2 0.999731 175 00 03.81 2.7 0.01
	To Markings Distance Dev Order Factor Bearing Dev Corr
Northing 5644993.092 m	$(m)(cm) \qquad (dms)  (s)  (s)$
Easting -8571.981 m	55442 643-8.86 191.694 1 52/2 0.999730 172 50 34.20 4.0 0.00
Convergence -0 05 40.96 dms	46250 643-8.47 259.569 1 42/2 0.999730 270 09 09.25 3.2 0.00
Station Ellipsoid Factor 0.999829	265975 643-8.41 310.037 1 35/2 0.999731 109 34 04.62 3.0 0.00
Station Combined Factor 0.999730	463679 643-8.93 348.942 1 46/2 0.999729 50 46 52.53 3.6 0.00
	- 80564 643-8.85 377.298 1 40/2 0.999730 213 40 39.81 3.5 0.01
GEOID DATA (GSD95) Updated: 96-01-06	135483 643-8.87 393.175 1 33/2 0.999731 175 00 03.81 2.7 0.01
, ,	
Component Magnitude Std Dev	MARKER TYPE Updated: 1980-09-10
•	-
Meridian Defl,XI(+N) 4.1 s 2 s	ASC CAP SET IN CONCRETE SIDEWALK
Prime Vert Defl,ETA(+E) 6.9 s 2 s	
Geoid_Ellip Separation -15.90 m 1 m	
	- MARKER LOCATION Updated: 1989-04-29
COORDINATE HISTORY HORZ VERT	-
	LOCATED AT THE INTERSECTION OF WOODVIEW DRIVE AND WOODFIELD DRIVE SOUTH WEST;
Originating Project 79042 79042	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); 0.4 M WEST OF EAST END
Originating Project 79042 79042 Published 79-12-01 79-12-01	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); 0.4 M WEST OF EAST END
Published 79-12-01 79-12-01	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); $0.4$ M WEST OF EAST END OF BULLNOSE OF MEDIAN.
Published 79-12-01 79-12-01	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); $0.4$ M WEST OF EAST END OF BULLNOSE OF MEDIAN.
Published 79-12-01 79-12-01	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); $0.4$ M WEST OF EAST END OF BULLNOSE OF MEDIAN.
Published 79-12-01 79-12-01  Revising Project NAD83 98017  Published 94-05-24 01-02-07	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); 0.4 M WEST OF EAST END
Published 79-12-01 79-12-01	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); $0.4$ M WEST OF EAST END OF BULLNOSE OF MEDIAN.
Published 79-12-01 79-12-01  Revising Project NAD83 98017 Published 94-05-24 01-02-07 Revising Project 83047	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); $0.4$ M WEST OF EAST END OF BULLNOSE OF MEDIAN.
Published 79-12-01 79-12-01  Revising Project NAD83 98017  Published 94-05-24 01-02-07  Revising Project 83047  Published 84-09-05	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); $0.4$ M WEST OF EAST END OF BULLNOSE OF MEDIAN.
Published 79-12-01 79-12-01  Revising Project NAD83 98017 Published 94-05-24 01-02-07 Revising Project 83047 Published 84-09-05 Revising Project	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); 0.4 M WEST OF EAST END OF BULLNOSE OF MEDIAN.  NOTE: MONUMENT REVISED VERTICALLY AS OF AUGUST 1984 IN PF #83047.
Published 79-12-01 79-12-01  Revising Project NAD83 98017 Published 94-05-24 01-02-07 Revising Project 83047 Published 84-09-05 Revising Project Published	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); 0.4 M WEST OF EAST END OF BULLNOSE OF MEDIAN.  NOTE: MONUMENT REVISED VERTICALLY AS OF AUGUST 1984 IN PF #83047.
Published 79-12-01 79-12-01  Revising Project NAD83 98017 Published 94-05-24 01-02-07 Revising Project 83047 Published 84-09-05 Revising Project Published NON COORDINATE REVISIONS	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); 0.4 M WEST OF EAST END OF BULLNOSE OF MEDIAN.  NOTE: MONUMENT REVISED VERTICALLY AS OF AUGUST 1984 IN PF #83047.
Published 79-12-01 79-12-01  Revising Project NAD83 98017 Published 94-05-24 01-02-07 Revising Project 83047 Published 84-09-05 Revising Project Published	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); 0.4 M WEST OF EAST END OF BULLNOSE OF MEDIAN.  NOTE: MONUMENT REVISED VERTICALLY AS OF AUGUST 1984 IN PF #83047.
Published 79-12-01 79-12-01  Revising Project NAD83 98017 Published 94-05-24 01-02-07 Revising Project 83047 Published 84-09-05 Revising Project Published NON COORDINATE REVISIONS  1980-09-10 FIRST MARKER LOCATION	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); 0.4 M WEST OF EAST END OF BULLNOSE OF MEDIAN.  NOTE: MONUMENT REVISED VERTICALLY AS OF AUGUST 1984 IN PF #83047.  MARKER CONDITION COMMENTS  Inspected Updated
Published 79-12-01 79-12-01  Revising Project NAD83 98017 Published 94-05-24 01-02-07 Revising Project 83047 Published 84-09-05 Revising Project Published NON COORDINATE REVISIONS  1980-09-10 FIRST MARKER LOCATION	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); 0.4 M WEST OF EAST END OF BULLNOSE OF MEDIAN.  NOTE: MONUMENT REVISED VERTICALLY AS OF AUGUST 1984 IN PF #83047.  MARKER CONDITION COMMENTS  Inspected Updated
Published 79-12-01 79-12-01  Revising Project NAD83 98017 Published 94-05-24 01-02-07 Revising Project 83047 Published 84-09-05 Revising Project Published	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); 0.4 M WEST OF EAST END OF BULLNOSE OF MEDIAN.  NOTE: MONUMENT REVISED VERTICALLY AS OF AUGUST 1984 IN PF #83047.
Published 79-12-01 79-12-01  Revising Project NAD83 98017 Published 94-05-24 01-02-07 Revising Project 83047 Published 84-09-05 Revising Project Published NON COORDINATE REVISIONS  1980-09-10 FIRST MARKER LOCATION	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); 0.4 M WEST OF EAST END OF BULLNOSE OF MEDIAN.  NOTE: MONUMENT REVISED VERTICALLY AS OF AUGUST 1984 IN PF #83047.  MARKER CONDITION COMMENTS  Inspected Updated
Published 79-12-01 79-12-01  Revising Project NAD83 98017 Published 94-05-24 01-02-07 Revising Project 83047 Published 84-09-05 Revising Project Published NON COORDINATE REVISIONS  1980-09-10 FIRST MARKER LOCATION	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); 0.4 M WEST OF EAST END OF BULLNOSE OF MEDIAN.  NOTE: MONUMENT REVISED VERTICALLY AS OF AUGUST 1984 IN PF #83047.  MARKER CONDITION COMMENTS  Inspected Updated
Published 79-12-01 79-12-01  Revising Project NAD83 98017 Published 94-05-24 01-02-07 Revising Project 83047 Published 84-09-05 Revising Project Published NON COORDINATE REVISIONS  1980-09-10 FIRST MARKER LOCATION	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); 0.4 M WEST OF EAST END OF BULLNOSE OF MEDIAN.  NOTE: MONUMENT REVISED VERTICALLY AS OF AUGUST 1984 IN PF #83047.  MARKER CONDITION COMMENTS  MARKER REPORTED IN GOOD CONDITION  1991-03-26 1991-08-19 MARKER REPORTED IN GOOD CONDITION.  1989-02-22 1989-04-29
Published 79-12-01 79-12-01  Revising Project NAD83 98017 Published 94-05-24 01-02-07 Revising Project 83047 Published 84-09-05 Revising Project Published NON COORDINATE REVISIONS  1980-09-10 FIRST MARKER LOCATION	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); 0.4 M WEST OF EAST END OF BULLNOSE OF MEDIAN.  NOTE: MONUMENT REVISED VERTICALLY AS OF AUGUST 1984 IN PF #83047.  MARKER CONDITION COMMENTS  Inspected Updated
Published 79-12-01 79-12-01  Revising Project NAD83 98017 Published 94-05-24 01-02-07 Revising Project 83047 Published 84-09-05 Revising Project Published NON COORDINATE REVISIONS  1980-09-10 FIRST MARKER LOCATION	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); 0.4 M WEST OF EAST END OF BULLNOSE OF MEDIAN.  NOTE: MONUMENT REVISED VERTICALLY AS OF AUGUST 1984 IN PF #83047.  MARKER CONDITION COMMENTS  MARKER REPORTED IN GOOD CONDITION  MARKER REPORTED IN GOOD CONDITION  MARKER REPORTED IN GOOD CONDITION.  1991-03-26 1991-08-19 MARKER REPORTED IN GOOD CONDITION.  1989-02-22 1989-04-29 MARKER REPORTED IN GOOD CONDITION.
Published 79-12-01 79-12-01  Revising Project NAD83 98017 Published 94-05-24 01-02-07 Revising Project 83047 Published 84-09-05 Revising Project Published  NON COORDINATE REVISIONS  1980-09-10 FIRST MARKER LOCATION DESCRIPTION ENTERED 2003-03-12 "MAPSHEET NAME" AND/OR "MAPSHEET NO" CHANGED	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); 0.4 M WEST OF EAST END OF BULLNOSE OF MEDIAN.  NOTE: MONUMENT REVISED VERTICALLY AS OF AUGUST 1984 IN PF #83047.  MARKER CONDITION COMMENTS  MARKER REPORTED IN GOOD CONDITION  MARKER REPORTED IN GOOD CONDITION  1991-03-26 1991-08-19 MARKER REPORTED IN GOOD CONDITION  1989-02-22 1989-04-29  COORDINATE HISTORY COMMENTS  HORZ 94-05-24  ALBERTA NAD83 READJUSTMENT
Published 79-12-01 79-12-01  Revising Project NAD83 98017 Published 94-05-24 01-02-07 Revising Project 83047 Published 84-09-05 Revising Project Published  NON COORDINATE REVISIONS  1980-09-10 FIRST MARKER LOCATION DESCRIPTION ENTERED 2003-03-12 "MAPSHEET NAME" AND/OR "MAPSHEET NO" CHANGED	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); 0.4 M WEST OF EAST END OF BULLNOSE OF MEDIAN.  NOTE: MONUMENT REVISED VERTICALLY AS OF AUGUST 1984 IN PF #83047.  MARKER CONDITION COMMENTS  MARKER REPORTED IN GOOD CONDITION  MARKER REPORTED IN GOOD CONDITION.  1991-03-26 1991-08-19 MARKER REPORTED IN GOOD CONDITION.  1989-02-22 1989-04-29 COORDINATE HISTORY COMMENTS  HORZ 94-05-24  ALBERTA NAD83 READJUSTMENT
Published 79-12-01 79-12-01  Revising Project NAD83 98017 Published 94-05-24 01-02-07 Revising Project 83047 Published 84-09-05 Revising Project Published  NON COORDINATE REVISIONS  1980-09-10 FIRST MARKER LOCATION DESCRIPTION ENTERED 2003-03-12 "MAPSHEET NAME" AND/OR "MAPSHEET NO" CHANGED	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); 0.4 M WEST OF EAST END OF BULLNOSE OF MEDIAN.  NOTE: MONUMENT REVISED VERTICALLY AS OF AUGUST 1984 IN PF #83047.  MARKER CONDITION COMMENTS  MARKER REPORTED IN GOOD CONDITION MARKER REPORTED IN GOOD CONDITION.  1991-03-26 1991-08-19 MARKER REPORTED IN GOOD CONDITION.  1989-02-22 1989-04-29 MARKER REPORTED IN GOOD CONDITION.  COORDINATE HISTORY COMMENTS  HORZ 94-05-24 ALBERTA NAD83 READJUSTMENT 84-09-05 88 35 16 0.019 m MOVEMENT DETECTED
Published 79-12-01 79-12-01  Revising Project NAD83 98017 Published 94-05-24 01-02-07 Revising Project 83047 Published 84-09-05 Revising Project Published	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); 0.4 M WEST OF EAST END OF BULLNOSE OF MEDIAN.  NOTE: MONUMENT REVISED VERTICALLY AS OF AUGUST 1984 IN PF #83047.  MARKER CONDITION COMMENTS Inspected Updated MARKER REPORTED IN GOOD CONDITION 1991-03-26 1991-08-19 MARKER REPORTED IN GOOD CONDITION. 1989-02-22 1989-04-29 MARKER REPORTED IN GOOD CONDITION 1989-04-29 MARKER REPORTED IN GOOD CONDITI
Published 79-12-01 79-12-01  Revising Project NAD83 98017 Published 94-05-24 01-02-07 Revising Project 83047 Published 84-09-05 Revising Project Published  NON COORDINATE REVISIONS  1980-09-10 FIRST MARKER LOCATION DESCRIPTION ENTERED 2003-03-12 "MAPSHEET NAME" AND/OR "MAPSHEET NO" CHANGED	IN MEDIAN ON WOODVIEW DRIVE (WEST SIDE OF INTERSECTION); 0.4 M WEST OF EAST END OF BULLNOSE OF MEDIAN.  NOTE: MONUMENT REVISED VERTICALLY AS OF AUGUST 1984 IN PF #83047.  MARKER CONDITION COMMENTS  MARKER REPORTED IN GOOD CONDITION MARKER REPORTED IN GOOD CONDITION.  1991-03-26 1991-08-19 MARKER REPORTED IN GOOD CONDITION.  1989-02-22 1989-04-29 MARKER REPORTED IN GOOD CONDITION.  COORDINATE HISTORY COMMENTS  HORZ 94-05-24 ALBERTA NAD83 READJUSTMENT 84-09-05 88 35 16 0.019 m MOVEMENT DETECTED

HISTORY 56434 8 48