SURVEYING AND MAPPING DIVISION

Alberta Survey Control Marker (ASCM) Information MASCOT DSS-1

Horz Datum NAD83 Updated: 1994-05-24	MASCOT DSS-1 ASCM 19778
Latitude 50 58 52.65515 dms Longitude 114 06 02.24588 dms Horz Class INTEGRATED , ORDER 2	Marker Installed 67-03
Longitude 114 06 02.24588 dms	Tablet Markings D102
Vert Datum CVD28 Updated: 2001-02-07	Mapsheet Number 5649 - 004
Vert Class INTEGRATED , SPIRIT LEVELS	For current information call Geodetic Survey (780) 427-3143 FAX: (780) 427-1493 Marker Condition SEE BELOW 22-05-16
3TM COORDINATES	ADJACENT MARKERS (calculated) Updated: 2018-02-1
Scale Factor 0.999900 At Ref Mer 114	ASCM Tablet Horizontal Std PPM/ Grid/ Grnd Grid Std T-t To Markings Distance Dev Order Factor Bearing Dev Corr (m)(cm) (dms) (s) (s) 159749 D100 369.234 1 19/1 0.999730 287 35 23.61 1.5 0.00 157842 649-4.177 370.457 1 30/1 0.999732 327 33 03.41 2.6 -0.01 102871 D94A 398.267 1 28/1 0.999731 321 49 07.02 2.3 -0.01 239434 649-4.176 422.967 1 26/1 0.999735 49 44 55.52 2.0 0.00 - 219006 649-4.116 466.884 1 24/1 0.999735 60 53 07.96 1.7 0.00 176339 646-4.238 468.824 1 17/1 0.999734 165 40 22.02 1.3 0.01
Northing 5649444.435 m	(m)(cm) (dms) (s) (s)
Easting -7065.694 m	159749 D100 369.234 1 19/1 0.999730 287 35 23.61 1.5 0.00
Convergence -0 04 41.44 dms	157842 649-4.177 370.457 1 30/1 0.999732 327 33 03.41 2.6 -0.01
Station Combined Factor 0.999734	239434 649-4 176 422.967 1 26/1 0.393731 321 49 07.02 2.3 -0.01
	- 219006 649-4.116 466.884 1 24/1 0.999735 60 53 07.96 1.7 0.00
GEOID DATA (GSD95) Updated: 96-01-06	176339 646-4.238 468.824 1 17/1 0.999734 165 40 22.02 1.3 0.01
Component Magnitude Std Dev	MARKER TYPE Updated: 2022-05-3
Meridian Defl,XI(+N) 3.5 s 2 s Prime Vert Defl,ETA(+E) 6.5 s 2 s Geoid Fllip Separation -16.03 m 1 m	ASC CAP ON 6 CM DIA STEEL PIPE 3.0 M LONG FLUSH W/GRD, LANDSCAPED.
Geold_Eilip Separation -10.05 m	- MARKER LOCATION Updated: 1991-09-2
COORDINATE HISTORY HORZ VERT	
Originating Project 72117 72117 Published 72-07-11 72-07-11	ON S.W. SIDE OF ROAD NEAR INTER. OF GLENMORE DAM BOAT DOCK & HERITAGE PARK ROAD; 2.25M S.W. OF S.W. SIDE OF ASPHALT PATH; 18.0M (SLOPE DIST.) N.E. OF STONE BANK FOR DAM; ON CABLE FENCE FOR W/S OF HERITAGE PARK ROAD, PROD. SOUTH;
Revising Project 98014 Published 99-08-16 Revising Project Published	ON S.W. SIDE OF ROAD NEAR INTER. OF GLENMORE DAM BOAT DOCK & HERITAGE PARK ROAD; 2.25M S.W. OF S.W. SIDE OF ASPHALT PATH; 18.0M (SLOPE DIST.) N.E. OF STONE BANK FOR DAM; ON CABLE FENCE FOR W/S OF HERITAGE PARK ROAD, PROD. SOUTH; 33.3M SOUTH OF HERITAGE PARK AND BOAT DOCK SIGN; 44.5M S.W. OF MOST S. WESTERLY TRACK FOR HERITAGE PARK TROLLEY CAR.
Published 99-08-16 Revising Project	2.25M S.W. OF S.W. SIDE OF ASPHALT PATH; 18.0M (SLOPE DIST.) N.E. OF STONE BANK FOR DAM; ON CABLE FENCE FOR W/S OF HERITAGE PARK ROAD, PROD. SOUTH; 33.3M SOUTH OF HERITAGE PARK AND BOAT DOCK SIGN; 44.5M S.W. OF MOST S. WESTERLY TRACK FOR HERITAGE PARK TROLLEY CAR.
Revising Project 98014 Published 99-08-16 Revising Project Published	2.25M S.W. OF S.W. SIDE OF ASPHALT PATH; 18.0M (SLOPE DIST.) N.E. OF STONE BANK FOR DAM; ON CABLE FENCE FOR W/S OF HERITAGE PARK ROAD, PROD. SOUTH; 33.3M SOUTH OF HERITAGE PARK AND BOAT DOCK SIGN; 44.5M S.W. OF MOST S. WESTERLY TRACK FOR HERITAGE PARK TROLLEY CAR.
Published 99-08-16 Revising Project 98014 Published 99-08-16 Published NON COORDINATE REVISIONS 1972-07-11 FIRST MARKER LOCATION	2.25M S.W. OF S.W. SIDE OF ASPHALT PATH; 18.0M (SLOPE DIST.) N.E. OF STONE BANK FOR DAM; ON CABLE FENCE FOR W/S OF HERITAGE PARK ROAD, PROD. SOUTH; 33.3M SOUTH OF HERITAGE PARK AND BOAT DOCK SIGN; 44.5M S.W. OF MOST S. WESTERLY TRACK FOR HERITAGE PARK TROLLEY CAR. MARKER CONDITION COMMENTS Inspected Update
Published 99-08-16 Revising Project 99-08-16 Revising Project Published NON COORDINATE REVISIONS 1972-07-11 FIRST MARKER LOCATION DESCRIPTION ENTERED	2.25M S.W. OF S.W. SIDE OF ASPHALT PATH; 18.0M (SLOPE DIST.) N.E. OF STONE BANK FOR DAM; ON CABLE FENCE FOR W/S OF HERITAGE PARK ROAD, PROD. SOUTH; 33.3M SOUTH OF HERITAGE PARK AND BOAT DOCK SIGN; 44.5M S.W. OF MOST S. WESTERLY TRACK FOR HERITAGE PARK TROLLEY CAR. MARKER CONDITION COMMENTS Inspected Update MARKER REPORTED AS CAP MISSING 2022-05-3 MARKER REPORTED IN GOOD CONDITION 1990-11-07 1991-09-2
Published 99-08-16 Revising Project 99-08-16 Revising Project Published NON COORDINATE REVISIONS 1972-07-11 FIRST MARKER LOCATION DESCRIPTION ENTERED	2.25M S.W. OF S.W. SIDE OF ASPHALT PATH; 18.0M (SLOPE DIST.) N.E. OF STONE BANK FOR DAM; ON CABLE FENCE FOR W/S OF HERITAGE PARK ROAD, PROD. SOUTH; 33.3M SOUTH OF HERITAGE PARK AND BOAT DOCK SIGN; 44.5M S.W. OF MOST S. WESTERLY TRACK FOR HERITAGE PARK TROLLEY CAR. MARKER CONDITION COMMENTS Inspected Update MARKER REPORTED AS CAP MISSING 2022-05-16 2022-05-3 MARKER REPORTED IN GOOD CONDITION 1990-11-07 1991-09-2
Published 99-08-16 Revising Project 99-08-16 Revising Project Published NON COORDINATE REVISIONS 1972-07-11 FIRST MARKER LOCATION DESCRIPTION ENTERED	2.25M S.W. OF S.W. SIDE OF ASPHALT PATH; 18.0M (SLOPE DIST.) N.E. OF STONE BANK FOR DAM; ON CABLE FENCE FOR W/S OF HERITAGE PARK ROAD, PROD. SOUTH; 33.3M SOUTH OF HERITAGE PARK AND BOAT DOCK SIGN; 44.5M S.W. OF MOST S. WESTERLY TRACK FOR HERITAGE PARK TROLLEY CAR. MARKER CONDITION COMMENTS Inspected Update MARKER REPORTED AS CAP MISSING MARKER REPORTED IN GOOD CONDITION 1990-11-07 1991-09-2 COORDINATE HISTORY COMMENTS HORZ 94-05-24 ALBERTA NAD83 READJUSTMENT
Published 99-08-16 Revising Project Published NON COORDINATE REVISIONS 1972-07-11 FIRST MARKER LOCATION DESCRIPTION ENTERED 2003-03-12 "MAPSHEET NAME" AND/OR "MAPSHEET NO" CHANGED	2.25M S.W. OF S.W. SIDE OF ASPHALT PATH; 18.0M (SLOPE DIST.) N.E. OF STONE BANK FOR DAM; ON CABLE FENCE FOR W/S OF HERITAGE PARK ROAD, PROD. SOUTH; 33.3M SOUTH OF HERITAGE PARK AND BOAT DOCK SIGN; 44.5M S.W. OF MOST S. WESTERLY TRACK FOR HERITAGE PARK TROLLEY CAR. MARKER CONDITION COMMENTS Inspected Update MARKER REPORTED AS CAP MISSING 2022-05-16 2022-05-3 MARKER REPORTED IN GOOD CONDITION 1990-11-07 1991-09-2 COORDINATE HISTORY COMMENTS HORZ 94-05-24 ALBERTA NAD83 READJUSTMENT
Published 99-08-16 Revising Project Published NON COORDINATE REVISIONS 1972-07-11 FIRST MARKER LOCATION DESCRIPTION ENTERED 2003-03-12 "MAPSHEET NAME" AND/OR "MAPSHEET NO" CHANGED	2.25M S.W. OF S.W. SIDE OF ASPHALT PATH; 18.0M (SLOPE DIST.) N.E. OF STONE BANK FOR DAM; ON CABLE FENCE FOR W/S OF HERITAGE PARK ROAD, PROD. SOUTH; 33.3M SOUTH OF HERITAGE PARK AND BOAT DOCK SIGN; 44.5M S.W. OF MOST S. WESTERLY TRACK FOR HERITAGE PARK TROLLEY CAR. MARKER CONDITION COMMENTS Inspected Update MARKER REPORTED AS CAP MISSING MARKER REPORTED IN GOOD CONDITION 1990-11-07 1991-09-2 COORDINATE HISTORY COMMENTS HORZ 94-05-24 ALBERTA NAD83 READJUSTMENT