SURVEYING AND MAPPING DIVISION

Alberta Survey Control Marker (ASCM) Information
MASCOT DSS-1

	MASCOT DSS-1	
Horz Datum NAD83 Updated: 1994-05-24	ASCM 2717	
Latitude 51 03 32.24957 dms Longitude 114 10 39.31840 dms	Marker Installed 72-03 Tablet Markings 655-12.40 Date Printed 2025-08-03 Last Updated 2016-04-08 Mapsheet Name CALGARY G Mapsheet Number 5658 - 012	
Horz Class INTEGRATED , ORDER 3	Date Printed 2025-08-03	
Vert Datum CVD28 Updated: 2000-06-15	Last Updated 2016-04-08 Mapsheet Name CALGARY G Mapsheet Number 5658 - 012	
Elevation 1207.803 m Vert Class INTEGRATED , SPIRIT LEVELS	For current information call Geodetic Survey (780) 427-3143 FAX: (780) 427-1493 Marker Condition GOOD 15-10-26	6
3TM COORDINATES	ADJACENT MARKERS (calculated) Updated: 2016-04-0	
Scale Factor 0.999900 At Ref Mer 114		
Northing 5658093 897 m	To Markings Distance Dev Order Factor Bearing Dev Corn) L
Easting -12449.241 m	117101 655-12.54	0
Convergence -0 08 17.26 dms	11932 655-12.55 215.615 1 32/1 0.999716 287 04 38.37 2.4 0.00	0
Station Ellipsoid Factor 0.999813	193367 655-12.53 217.115 1 51/2 0.999718 234 02 36.33 4.0 0.00	0
Station Combined Factor 0.999715	72678 655-12.75 254.740 1 51/2 0.999717 270 39 14.54 3.9 0.00	0
	265686 655-12.51 282.167 1 43/2 0.999716 216 29 01.30 3.6 0.01	1
GEOID DATA (GSD95) Updated: 96-01-06	To Markings Distance Dev Order Factor Bearing Dev Corr (m)(cm) (dms) (s) (s) 117101 655-12.54 141.251 1 49/2 0.999722 275 23 25.99 3.1 0.00 11932 655-12.55 215.615 1 32/1 0.999716 287 04 38.37 2.4 0.00 193367 655-12.53 217.115 1 51/2 0.999718 234 02 36.33 4.0 0.00 72678 655-12.75 254.740 1 51/2 0.999717 270 39 14.54 3.9 0.00 265686 655-12.51 282.167 1 43/2 0.999716 216 29 01.30 3.6 0.01 52191 655-12.57 293.730 1 41/2 0.999717 265 28 11.71 3.4 0.00	0
Component Magnitude Std Dev	MARKER TYPE Updated: 2016-03-2	21
Meridian Defl.XI(+N) 2.8 s 2 s	ASC BRASS TABLET ON TOP OF 2" X 10' STEEL PIPE	
Prime Vert Defl,ETA(+E) 7.1 s 2 s	ASC BRASS TABLET ON TOP OF 2" X 10' STEEL PIPE. 100 CM BGL, 60 CM S OF GP.	
Geoid Ellip Separation -15.98 m 1 m		
	MARKER LOCATION Updated: 2016-03-2	21
COORDINATE HISTORY HORZ VERT		
Originating Project 72107 72107 Published 83-03-03 83-03-03	MARKER IS LOCATED ON THE NE CORNER OF OLD BANFF COACH RD AT LANE E OF PATTERSON BLVD SE; 2.9 M N OF B.O.W. ON CURVE; 0.7 M E OF POW.P. LINE PROD. S; 3.3 M NW OF POW.P; MARKER IS ENCASED IN BLUE PLASTIC PIPE WITH	
	MARKER IS LOCATED ON THE NE CORNER OF OLD BANFF COACH RD AT LANE E OF PATTERSON BLVD SE; 2.9 M N OF B.O.W. ON CURVE; 0.7 M E OF POW.P. LINE PROD. S; 3.3 M NW OF POW.P; MARKER IS ENCASED IN BLUE PLASTIC PIPE WITH COVER ATTACHED.	
Revising Project NAD83 98016	PATTERSON BLVD SE; 2.9 M N OF B.O.W. ON CURVE; 0.7 M E OF POW.P. LINE PROD. S; 3.3 M NW OF POW.P; MARKER IS ENCASED IN BLUE PLASTIC PIPE WITH	
Revising Project NAD83 98016 Published 94-05-24 00-06-15	PATTERSON BLVD SE; 2.9 M N OF B.O.W. ON CURVE; 0.7 M E OF POW.P. LINE PROD. S; 3.3 M NW OF POW.P; MARKER IS ENCASED IN BLUE PLASTIC PIPE WITH	
Revising Project NAD83 98016 Published 94-05-24 00-06-15 Revising Project	PATTERSON BLVD SE; 2.9 M N OF B.O.W. ON CURVE; 0.7 M E OF POW.P. LINE PROD. S; 3.3 M NW OF POW.P; MARKER IS ENCASED IN BLUE PLASTIC PIPE WITH	
Revising Project NAD83 98016 Published 94-05-24 00-06-15 Revising Project Published	PATTERSON BLVD SE; 2.9 M N OF B.O.W. ON CURVE; 0.7 M E OF POW.P. LINE PROD. S; 3.3 M NW OF POW.P; MARKER IS ENCASED IN BLUE PLASTIC PIPE WITH	
Revising Project NAD83 98016 Published 94-05-24 00-06-15 Revising Project Published Revising Project	PATTERSON BLVD SE; 2.9 M N OF B.O.W. ON CURVE; 0.7 M E OF POW.P. LINE PROD. S; 3.3 M NW OF POW.P; MARKER IS ENCASED IN BLUE PLASTIC PIPE WITH	
Revising Project NAD83 98016 Published 94-05-24 00-06-15 Revising Project Published	PATTERSON BLVD SE; 2.9 M N OF B.O.W. ON CURVE; 0.7 M E OF POW.P. LINE PROD. S; 3.3 M NW OF POW.P; MARKER IS ENCASED IN BLUE PLASTIC PIPE WITH	
Revising Project NAD83 98016 Published 94-05-24 00-06-15 Revising Project Published Revising Project Published	PATTERSON BLVD SE; 2.9 M N OF B.O.W. ON CURVE; 0.7 M E OF POW.P. LINE PROD. S; 3.3 M NW OF POW.P; MARKER IS ENCASED IN BLUE PLASTIC PIPE WITH	
Revising Project NAD83 98016 Published 94-05-24 00-06-15 Revising Project Published Revising Project Published NON COORDINATE REVISIONS 1972-05-10 FIRST MARKER LOCATION	PATTERSON BLVD SE; 2.9 M N OF B.O.W. ON CURVE; 0.7 M E OF POW.P. LINE PROD. S; 3.3 M NW OF POW.P; MARKER IS ENCASED IN BLUE PLASTIC PIPE WITH COVER ATTACHED.	 ed
Revising Project NAD83 98016 Published 94-05-24 00-06-15 Revising Project Published Revising Project Published NON COORDINATE REVISIONS 1972-05-10 FIRST MARKER LOCATION DESCRIPTION ENTERED	PATTERSON BLVD SE; 2.9 M N OF B.O.W. ON CURVE; 0.7 M E OF POW.P. LINE PROD. S; 3.3 M NW OF POW.P; MARKER IS ENCASED IN BLUE PLASTIC PIPE WITH COVER ATTACHED. MARKER CONDITION COMMENTS Inspected Update	
Revising Project NAD83 98016 Published 94-05-24 00-06-15 Revising Project Published Revising Project Published NON COORDINATE REVISIONS 1972-05-10 FIRST MARKER LOCATION	PATTERSON BLVD SE; 2.9 M N OF B.O.W. ON CURVE; 0.7 M E OF POW.P. LINE PROD. S; 3.3 M NW OF POW.P; MARKER IS ENCASED IN BLUE PLASTIC PIPE WITH COVER ATTACHED. MARKER CONDITION COMMENTS Inspected Update MARKER REPORTED IN GOOD CONDITION 2015-10-26 2016-03-2	21
Revising Project NAD83 98016 Published 94-05-24 00-06-15 Revising Project Published Revising Project Published NON COORDINATE REVISIONS 1972-05-10 FIRST MARKER LOCATION DESCRIPTION ENTERED	PATTERSON BLVD SE; 2.9 M N OF B.O.W. ON CURVE; 0.7 M E OF POW.P. LINE PROD. S; 3.3 M NW OF POW.P; MARKER IS ENCASED IN BLUE PLASTIC PIPE WITH COVER ATTACHED. MARKER CONDITION COMMENTS Inspected Update MARKER REPORTED IN GOOD CONDITION 2015-10-26 2016-03-2	21 17 29
Revising Project NAD83 98016 Published 94-05-24 00-06-15 Revising Project Published Revising Project Published NON COORDINATE REVISIONS 1972-05-10 FIRST MARKER LOCATION DESCRIPTION ENTERED 2003-03-12 "MAPSHEET NAME" AND/OR "MAPSHEET NO" CHANGED	PATTERSON BLVD SE; 2.9 M N OF B.O.W. ON CURVE; 0.7 M E OF POW.P. LINE PROD. S; 3.3 M NW OF POW.P; MARKER IS ENCASED IN BLUE PLASTIC PIPE WITH COVER ATTACHED. MARKER CONDITION COMMENTS MARKER REPORTED IN GOOD CONDITION MARKER REPORTED AS DESTROYED MARKER REPORTED IN GOOD CONDITION MARKER REPORTED IN GOOD CONDITION. 1988-11-22 1989-02-0	21 17 29 02
Revising Project NAD83 98016 Published 94-05-24 00-06-15 Revising Project Published Revising Project Published NON COORDINATE REVISIONS 1972-05-10 FIRST MARKER LOCATION DESCRIPTION ENTERED 2003-03-12 "MAPSHEET NAME" AND/OR "MAPSHEET NO" CHANGED	PATTERSON BLVD SE; 2.9 M N OF B.O.W. ON CURVE; 0.7 M E OF POW.P. LINE PROD. S; 3.3 M NW OF POW.P; MARKER IS ENCASED IN BLUE PLASTIC PIPE WITH COVER ATTACHED. MARKER CONDITION COMMENTS Inspected Update MARKER REPORTED IN GOOD CONDITION 2015-10-26 2016-03-2	21 17 29 02
Revising Project NAD83 98016 Published 94-05-24 00-06-15 Revising Project Published Revising Project Published NON COORDINATE REVISIONS 1972-05-10 FIRST MARKER LOCATION DESCRIPTION ENTERED 2003-03-12 "MAPSHEET NAME" AND/OR "MAPSHEET NO" CHANGED 2001-12-10 NGDB NUMBER ENTERED	PATTERSON BLVD SE; 2.9 M N OF B.O.W. ON CURVE; 0.7 M E OF POW.P. LINE PROD. S; 3.3 M NW OF POW.P; MARKER IS ENCASED IN BLUE PLASTIC PIPE WITH COVER ATTACHED. MARKER CONDITION COMMENTS MARKER REPORTED IN GOOD CONDITION MARKER REPORTED AS DESTROYED MARKER REPORTED IN GOOD CONDITION MARKER REP	21 17 29 02
Revising Project NAD83 98016 Published 94-05-24 00-06-15 Revising Project Published Revising Project Published NON COORDINATE REVISIONS 1972-05-10 FIRST MARKER LOCATION DESCRIPTION ENTERED 2003-03-12 "MAPSHEET NAME" AND/OR "MAPSHEET NO" CHANGED 2001-12-10 NGDB NUMBER ENTERED	PATTERSON BLVD SE; 2.9 M N OF B.O.W. ON CURVE; 0.7 M E OF POW.P. LINE PROD. S; 3.3 M NW OF POW.P; MARKER IS ENCASED IN BLUE PLASTIC PIPE WITH COVER ATTACHED. MARKER CONDITION COMMENTS MARKER REPORTED IN GOOD CONDITION MARKER REPORTED AS DESTROYED MARKER REPORTED IN GOOD CONDITION MARKER REP	21 17 29 02
Revising Project NAD83 98016 Published 94-05-24 00-06-15 Revising Project Published Revising Project Published NON COORDINATE REVISIONS 1972-05-10 FIRST MARKER LOCATION DESCRIPTION ENTERED 2003-03-12 "MAPSHEET NAME" AND/OR "MAPSHEET NO" CHANGED 2001-12-10 NGDB NUMBER ENTERED	PATTERSON BLVD SE; 2.9 M N OF B.O.W. ON CURVE; 0.7 M E OF POW.P. LINE PROD. S; 3.3 M NW OF POW.P; MARKER IS ENCASED IN BLUE PLASTIC PIPE WITH COVER ATTACHED. MARKER CONDITION COMMENTS MARKER REPORTED IN GOOD CONDITION MARKER REPORTED AS DESTROYED MARKER REPORTED IN GOOD CONDITION MARKER REPORTED IN GOOD CONDITION. 1995-09-21 2001-08-2 MARKER REPORTED IN GOOD CONDITION. 1988-11-22 1989-02-0 COORDINATE HISTORY COMMENTS HORZ 94-05-24 ALBERTA NAD83 READJUSTMENT	21 17 29 02
Revising Project NAD83 98016 Published 94-05-24 00-06-15 Revising Project Published Revising Project Published NON COORDINATE REVISIONS 1972-05-10 FIRST MARKER LOCATION DESCRIPTION ENTERED 2003-03-12 "MAPSHEET NAME" AND/OR "MAPSHEET NO" CHANGED 2001-12-10 NGDB NUMBER ENTERED	PATTERSON BLVD SE; 2.9 M N OF B.O.W. ON CURVE; 0.7 M E OF POW.P. LINE PROD. S; 3.3 M NW OF POW.P; MARKER IS ENCASED IN BLUE PLASTIC PIPE WITH COVER ATTACHED. MARKER CONDITION COMMENTS MARKER REPORTED IN GOOD CONDITION MARKER REPORTED AS DESTROYED MARKER REPORTED IN GOOD CONDITION MARKER REP	21 17 29 02
Revising Project NAD83 98016 Published 94-05-24 00-06-15 Revising Project Published Revising Project Published NON COORDINATE REVISIONS 1972-05-10 FIRST MARKER LOCATION DESCRIPTION ENTERED 2003-03-12 "MAPSHEET NAME" AND/OR "MAPSHEET NO" CHANGED 2001-12-10 NGDB NUMBER ENTERED	PATTERSON BLVD SE; 2.9 M N OF B.O.W. ON CURVE; 0.7 M E OF POW.P. LINE PROD. S; 3.3 M NW OF POW.P; MARKER IS ENCASED IN BLUE PLASTIC PIPE WITH COVER ATTACHED. MARKER CONDITION COMMENTS MARKER REPORTED IN GOOD CONDITION MARKER REPORTED AS DESTROYED MARKER REPORTED IN GOOD CONDITION MARKER REP	21 17 29 02
Revising Project NAD83 98016 Published 94-05-24 00-06-15 Revising Project Published Revising Project Published NON COORDINATE REVISIONS 1972-05-10 FIRST MARKER LOCATION DESCRIPTION ENTERED 2003-03-12 "MAPSHEET NAME" AND/OR "MAPSHEET NO" CHANGED 2001-12-10 NGDB NUMBER ENTERED HISTORICAL/OTHER MARKER NAMES OLD ASC # 56554 12 40 NGBD # 77X1044	PATTERSON BLVD SE; 2.9 M N OF B.O.W. ON CURVE; 0.7 M E OF POW.P. LINE PROD. S; 3.3 M NW OF POW.P; MARKER IS ENCASED IN BLUE PLASTIC PIPE WITH COVER ATTACHED. MARKER CONDITION COMMENTS MARKER REPORTED IN GOOD CONDITION MARKER REPORTED AS DESTROYED MARKER REPORTED IN GOOD CONDITION MARKER REP	21 17 29 02