SURVEYING AND MAPPING DIVISION

Alberta Survey Control Marker (ASCM) Information
MASCOT DSS-1

77 D : 377 D 0 2 77 1 : 1004 0 5 0 4	MASCOT DSS-1	2001 14514
Horz Datum NAD83 Updated: 1994-05-24 Latitude 51 04 53.83878 dms	Marker Installed 80-04	ASCM 14514
Longitude 113 56 31 77310 dmg	Tablet Ma	arkings 658+8.108
Horz Class INTEGRATED , ORDER 2	Date Printed 2025-08-03	arkings 050/0.100
HOLE CLUBS INTEGRATED , ORDER E		et Name CALGARY B
Vert Datum CVD28 Updated: 1999-10-21		Number 5658 + 008
Elevation 1079.208 m	For current information call Geodetic Survey	
Vert Class INTEGRATED , SPIRIT LEVELS	For current information call Geodetic Survey (780) 427-3143 FAX: (780) 427-1493 Marker Cor	ndition GOOD 88-10-05
3TM COORDINATES	ADJACENT MARKERS (calculated)	Updated: 2020-01-09
- 1		
Scale Factor 0.999900 At Ref Mer 114	ASCM Tablet Horizontal Std PPM/ Grid/ Grnd To Markings Distance Dev Order Factor	d Grid Std T-t
Northing FCC0C01 FFF m	To Markings Distance Dev Order Factor	Bearing Dev Corr
Rocking 4052 757 m	(III)(CIII) 206021 650±0 127 156 270 1 70/2 0 000724	(allis) (S) (S)
Convergence 0.02.737 m	146126 658+8 103 189 357 1 69/2 0 999733	9 86 49 29 90 3 7 0 00
Station Ellipsoid Factor 0 999834	64089 658+8 106 195 732 1 56/2 0 999734	1 356 12 45 95 4 4 0 00
Station Combined Factor 0.999734	146704 658+8.112 206.002 1 73/2 0.999733	330 12 13.33 1.1 0.00
	- 41475 658+8.96 217.764 1 55/2 0.999732	2 24 41 55.89 4.5 0.00
GEOID DATA (GSD95) Updated: 96-01-06	22673 658+4.332 230.321 1 65/2 0.999735	5 226 32 19.93 5.5 0.00
	10 Markings	
Component Magnitude Std Dev	MARKER TYPE	Updated: 1982-03-01
Meridian Defl,XI(+N) 2.7 s 2 s	ASC CAP ON 6 CM DIA STEEL PIPE 3.0 M LONG	
Prime Vert Defl,ETA(+E) 4.1 s 2 s		
Geoid_Ellip Separation -16.46 m 1 m	MARKER I OCCUPANTON	
COORDINATE HISTORY HORZ VERT	- MARKER LOCATION	Updated: 1988-11-03
COORDINATE HISTORY HORZ VERT	INCATED ON TEMPLEVIEW DRIVE AND 32 AVENUE MORTH FAST (N THE SOUTH FAST CORNER:
	LOCATED ON TEMPLEVIEW DRIVE AND 32 AVENUE NORTH EAST (
Originating Project 77045 77045	LOCATED ON TEMPLEVIEW DRIVE AND 32 AVENUE NORTH EAST (0.2 M NORTH OF THE NORTH FACE OF CURB OF 32 AVENUE; ON PRODUCED SOUTH OF TEMPLEVIEW DRIVE.	
Originating Project 77045 77045	0.2 M NORTH OF THE NORTH FACE OF CURB OF 32 AVENUE; ON	
Originating Project 77045 77045	0.2 M NORTH OF THE NORTH FACE OF CURB OF 32 AVENUE; ON	
Originating Project 77045 77045 Published 82-03-01 82-03-01 Revising Project NAD83 98015 Published 94-05-24 99-10-21	0.2 M NORTH OF THE NORTH FACE OF CURB OF 32 AVENUE; ON	
Originating Project 77045 77045 Published 82-03-01 82-03-01 Revising Project NAD83 98015 Published 94-05-24 99-10-21 Revising Project	0.2 M NORTH OF THE NORTH FACE OF CURB OF 32 AVENUE; ON	
Originating Project 77045 77045 Published 82-03-01 82-03-01 Revising Project NAD83 98015 Published 94-05-24 99-10-21 Revising Project Published	0.2 M NORTH OF THE NORTH FACE OF CURB OF 32 AVENUE; ON	
Originating Project 77045 77045 Published 82-03-01 82-03-01 Revising Project NAD83 98015 Published 94-05-24 99-10-21 Revising Project Published Revising Project	0.2 M NORTH OF THE NORTH FACE OF CURB OF 32 AVENUE; ON	
Originating Project 77045 77045 Published 82-03-01 82-03-01 Revising Project NAD83 98015 Published 94-05-24 99-10-21 Revising Project Published Revising Project Published Published	0.2 M NORTH OF THE NORTH FACE OF CURB OF 32 AVENUE; ON PRODUCED SOUTH OF TEMPLEVIEW DRIVE.	
Originating Project 77045 77045 Published 82-03-01 82-03-01 Revising Project NAD83 98015 Published 94-05-24 99-10-21 Revising Project Published Revising Project Published Published	0.2 M NORTH OF THE NORTH FACE OF CURB OF 32 AVENUE; ON PRODUCED SOUTH OF TEMPLEVIEW DRIVE.	
Originating Project 77045 77045 Published 82-03-01 82-03-01 Revising Project NAD83 98015 Published 94-05-24 99-10-21 Revising Project Published Revising Project Published Published	0.2 M NORTH OF THE NORTH FACE OF CURB OF 32 AVENUE; ON PRODUCED SOUTH OF TEMPLEVIEW DRIVE.	N BACK OF WALK EAST
Originating Project 77045 77045 Published 82-03-01 82-03-01 Revising Project NAD83 98015 Published 94-05-24 99-10-21 Revising Project Published Revising Project Published Published	0.2 M NORTH OF THE NORTH FACE OF CURB OF 32 AVENUE; ON PRODUCED SOUTH OF TEMPLEVIEW DRIVE.	N BACK OF WALK EAST
Originating Project 77045 77045 Published 82-03-01 82-03-01 Revising Project NAD83 98015 Published 94-05-24 99-10-21 Revising Project Published Revising Project Published NON COORDINATE REVISIONS	0.2 M NORTH OF THE NORTH FACE OF CURB OF 32 AVENUE; ON PRODUCED SOUTH OF TEMPLEVIEW DRIVE.	N BACK OF WALK EAST
Originating Project 77045 77045 Published 82-03-01 82-03-01 Revising Project NAD83 98015 Published 94-05-24 99-10-21 Revising Project Published Revising Project Published NON COORDINATE REVISIONS 1982-03-01 FIRST MARKER LOCATION	0.2 M NORTH OF THE NORTH FACE OF CURB OF 32 AVENUE; ON PRODUCED SOUTH OF TEMPLEVIEW DRIVE.	N BACK OF WALK EAST
Originating Project 77045 77045 Published 82-03-01 82-03-01 Revising Project NAD83 98015 Published 94-05-24 99-10-21 Revising Project Published Revising Project Published NON COORDINATE REVISIONS 1982-03-01 FIRST MARKER LOCATION DESCRIPTION ENTERED	0.2 M NORTH OF THE NORTH FACE OF CURB OF 32 AVENUE; ON PRODUCED SOUTH OF TEMPLEVIEW DRIVE.	N BACK OF WALK EAST Inspected Updated
Originating Project 77045 77045 Published 82-03-01 82-03-01 Revising Project NAD83 98015 Published 94-05-24 99-10-21 Revising Project Published Revising Project Published NON COORDINATE REVISIONS 1982-03-01 FIRST MARKER LOCATION DESCRIPTION ENTERED 2003-03-12 "MAPSHEET NAME" AND/OR	0.2 M NORTH OF THE NORTH FACE OF CURB OF 32 AVENUE; ON PRODUCED SOUTH OF TEMPLEVIEW DRIVE.	N BACK OF WALK EAST Inspected Updated
Originating Project 77045 77045 Published 82-03-01 82-03-01 Revising Project NAD83 98015 Published 94-05-24 99-10-21 Revising Project Published Revising Project Published NON COORDINATE REVISIONS 1982-03-01 FIRST MARKER LOCATION DESCRIPTION ENTERED 2003-03-12 "MAPSHEET NAME" AND/OR	0.2 M NORTH OF THE NORTH FACE OF CURB OF 32 AVENUE; ON PRODUCED SOUTH OF TEMPLEVIEW DRIVE. MARKER CONDITION COMMENTS MARKER REPORTED IN GOOD CONDITION.	IN BACK OF WALK EAST Inspected Updated 1988-10-05 1988-11-03
Originating Project 77045 77045 Published 82-03-01 82-03-01 Revising Project NAD83 98015 Published 94-05-24 99-10-21 Revising Project Published Revising Project Published NON COORDINATE REVISIONS 1982-03-01 FIRST MARKER LOCATION DESCRIPTION ENTERED 2003-03-12 "MAPSHEET NAME" AND/OR	0.2 M NORTH OF THE NORTH FACE OF CURB OF 32 AVENUE; ON PRODUCED SOUTH OF TEMPLEVIEW DRIVE.	IN BACK OF WALK EAST Inspected Updated 1988-10-05 1988-11-03
Originating Project 77045 77045 Published 82-03-01 82-03-01 Revising Project NAD83 98015 Published 94-05-24 99-10-21 Revising Project Published Revising Project Published NON COORDINATE REVISIONS 1982-03-01 FIRST MARKER LOCATION DESCRIPTION ENTERED 2003-03-12 "MAPSHEET NAME" AND/OR	0.2 M NORTH OF THE NORTH FACE OF CURB OF 32 AVENUE; ON PRODUCED SOUTH OF TEMPLEVIEW DRIVE. MARKER CONDITION COMMENTS MARKER REPORTED IN GOOD CONDITION.	IN BACK OF WALK EAST Inspected Updated 1988-10-05 1988-11-03
Originating Project 77045 77045 Published 82-03-01 82-03-01 Revising Project NAD83 98015 Published 94-05-24 99-10-21 Revising Project Published Revising Project Published NON COORDINATE REVISIONS 1982-03-01 FIRST MARKER LOCATION DESCRIPTION ENTERED 2003-03-12 "MAPSHEET NAME" AND/OR	0.2 M NORTH OF THE NORTH FACE OF CURB OF 32 AVENUE; ON PRODUCED SOUTH OF TEMPLEVIEW DRIVE.	Inspected Updated 1988-10-05 1988-11-03
Originating Project 77045 77045 Published 82-03-01 82-03-01 Revising Project NAD83 98015 Published 94-05-24 99-10-21 Revising Project Published Revising Project Published NON COORDINATE REVISIONS 1982-03-01 FIRST MARKER LOCATION DESCRIPTION ENTERED 2003-03-12 "MAPSHEET NAME" AND/OR "MAPSHEET NO" CHANGED	0.2 M NORTH OF THE NORTH FACE OF CURB OF 32 AVENUE; ON PRODUCED SOUTH OF TEMPLEVIEW DRIVE. MARKER CONDITION COMMENTS MARKER REPORTED IN GOOD CONDITION. COORDINATE HISTORY COMMENTS	Inspected Updated 1988-10-05 1988-11-03
Originating Project 77045 77045 Published 82-03-01 82-03-01 Revising Project NAD83 98015 Published 94-05-24 99-10-21 Revising Project Published Revising Project Published NON COORDINATE REVISIONS 1982-03-01 FIRST MARKER LOCATION DESCRIPTION ENTERED 2003-03-12 "MAPSHEET NAME" AND/OR	0.2 M NORTH OF THE NORTH FACE OF CURB OF 32 AVENUE; ON PRODUCED SOUTH OF TEMPLEVIEW DRIVE. MARKER CONDITION COMMENTS MARKER REPORTED IN GOOD CONDITION. COORDINATE HISTORY COMMENTS HORZ 94-05-24 ALBERTA NAD83 READS	Inspected Updated 1988-10-05 1988-11-03
Originating Project 77045 77045 Published 82-03-01 82-03-01 Revising Project NAD83 98015 Published 94-05-24 99-10-21 Revising Project Published Revising Project Published NON COORDINATE REVISIONS 1982-03-01 FIRST MARKER LOCATION DESCRIPTION ENTERED 2003-03-12 "MAPSHEET NAME" AND/OR "MAPSHEET NO" CHANGED	0.2 M NORTH OF THE NORTH FACE OF CURB OF 32 AVENUE; ON PRODUCED SOUTH OF TEMPLEVIEW DRIVE. MARKER CONDITION COMMENTS MARKER REPORTED IN GOOD CONDITION. COORDINATE HISTORY COMMENTS	Inspected Updated 1988-10-05 1988-11-03

HISTORY

56583 8 108