## FRIABILITY TEST FORM

	Run
Total weight of tablets before test (g)	6.44400
Total weight of tablets after test (g)	6.27228
Loss (g)	0.171720g

$$\frac{100}{100}$$
 Mage loss =  $\frac{1000}{100}$  Loss (g)  $\frac{1000}{100}$  X 100 =  $\frac{1000}{100}$  Z 100 =  $\frac{1000}{100}$ 

Comment (s): \_\_\_0