





Updates:

* Design with manufacturing tollerance 0.175 mm

* TVSOP footprint to accomodate the tolerance

* Fixed verong placement of pmod connectors wrt board edge

* Fixed LED swap

* Used 0805 passives

* Added Mounting holes

* Fixed pmod wrong numbering

* Change chip to UL_SN74CBTLY16292GR (TVSSOP => TSSOP)

* 4 layer board

* TOD :

* mux, capas on the back?

* Surface mount headers?

* Levet shifter / Input protection ?

* Levet shifter / Input protection?

* 1.6V (other ?) Voltage reference ? as Vtrgt













