Recived, - 64m, 0128 29,0128

BIMAN BANGLADESH AIRLINES LTD. ENGINEERING PRODUCTION

Ref: DACMK/S2-AHL/2014/80

Date: 27-03-2014

Dy. Chief Engineer, Planning, Record & Docs Directorate of Engg & MM Biman, Dhaka.

Sub: Handover Delivery Acceptance Documents of Boeing 777-200ER Aircraft S2-AHL

Enclosed please find herewith the Delivery Acceptance Documents of Boeing 777-200ER Aircraft S2-AHL duly signed by both parties as per Dry Lease Agreement for your information and necessary action.

27.03,14

Md. Shafiqul Alam Siddique Chief Engineer (Engg Production) Actg

Encl: As above 31 pages.

cc: Director Engg & MM - for kind information. cc: Director Flight Operations -docc: Director Procurement & Logistic Support -docc: Director Planning -docc: Director Finance -docc: General Manager Planning - wtih attachment. cc: General Manager Cost & Budget -doco: General Manager BFCC -docc: Chief Engineer (ES)/QA -docc: Chief of Technical -docc: Dy. Chief Engineer (ES)/LM -docc: Manager Legal Afairs -do-

original coon chippoints political contractions of the contraction

1048

EXHIBIT A-1

FORM OF ACCEPTANCE CERTIFICATE

ACCEPTANCE CERTIFICATE (MSN 32630), dated [2014], 20 [MAR] (this "Acceptance Certificate"), by BIMAN AIRLINES. ("Lessee").

[Except as provided in paragraph 4 below,] Lessee hereby irrevocably and unconditionally accepts and leases
from Lessor on the date hereof and at [___Cairo___], under and for all purposes of the Operative
Documents, the Aircraft, as more particularly defined in the Lease Agreement, but including the following:

One Used BOEING Model B777-200ER airframe bearing manufacturer's serial number MSN 32630 (including the loose equipment listed on Annex 1 hereto), together with (a) two [PW4090] engines bearing manufacturer's serial numbers [Engine 1 : 222031] and [Engine 2 : 222166], respectively, (b) [Manufacturer HONEYWELL] Model [331-500B] APU bearing manufacturer's serial number [P1444], (c) three landing gear assemblies bearing manufacturer's serial numbers [MC0757P0362] (LM), [MC0758P0362] (RM) and [MC0372P0362] (N) and (d) the Aircraft Documentation listed on Annex 2 hereto. The current status of the Aircraft is set out in Annex 3 hereto.

- Lessee hereby confirms that the "Delivery Date" for all purposes of the Lease Agreement is the date set forth
 in the opening paragraph of this Acceptance Certificate and confirms that the Lease Term shall commence on
 the Delivery Date.
- 3. Lessee hereby confirms its agreement to pay Rent throughout the Lease Term in the amounts, to the Persons and otherwise in accordance with the provisions of Section 3 of the Lease Agreement and in accordance with the other provisions of the Operative Documents.
- 4. Lessee hereby confirms that it has inspected the Aircraft and that the Aircraft is in compliance with the delivery requirements of the Lease Agreement and each other Operative Document[,except for such items listed in Annex 4]. Lessee further confirms that it has read and agrees with the DISCLAIMER set forth in Section 4 of Part II of Schedule 3 to the Lease Agreement. Without limiting the terms of such DISCLAIMER, Lessee confirms and acknowledges that:
 - (1) LESSEE HAS FULLY INSPECTED THE AIRCRAFT, AND, SPECIFICALLY, HAS INSPECTED THE AIRCRAFT DOCUMENTATION.
 - (2) [EXCEPT FOR SUCH ITEMS LISTED IN ANNEX 4,] THE CONDITION OF AIRCRAFT, INCLUDING THE AIRCRAFT DOCUMENTATION, IS SATISFACTORY TO LESSEE.
 - LESSEE IS AN EXPERIENCED OPERATOR OF COMMERCIAL AIRCRAFT [AND PARTICULARLY OF AIRCRAFT OF THE SAME TYPE AS THE AIRCRAFT]. LESSEE HEREBY CONFIRMS THAT IN ACCEPTING THE AIRCRAFT LESSEE IS RELYING SOLELY ON ITS OWN INVESTIGATION AND IS NOT RELYING UPON ANY REPRESENTATION, STATEMENT OR OTHER ASSERTION OF LESSOR OR ANY PERSON OR ENTITY CONNECTED WITH LESSOR WITH RESPECT TO THE AIRCRAFT.
 - (4) LESSEE HAS BEEN ADVISED OF AND FULLY UNDERSTANDS THE LEGAL IMPORT AND IMPLICATIONS OF THIS ACCEPTANCE CERTIFICATE.
- 5. THIS ACCEPTANCE CERTIFICATE SHALL IN ALL RESPECTS, INCLUDING ALL MATTERS OF CONSTRUCTION, VALIDITY AND PERFORMANCE, BE GOVERNED BY AND CONSTRUED AND ENFORCED IN ACCORDANCE WITH THE INTERNAL LAWS OF EGYPT APPLICABLE TO CONTRACTS ENTERED INTO IN THAT STATE BETWEEN CITIZENS OF THAT STATE AND TO BE PERFORMED WHOLLY WITHIN THAT STATE WITHOUT REFERENCE TO ANY RULES GOVERNING CONFLICTS OF LAWS.

Lessee has caused this Acceptance Certificate to be executed by its duly authorized officer on the day and year first above written.

8

20/3

By:

Md. Shafiqul Alam Siddique Chief Engineer, Engg Prod (Actg) Biman E & MM, HSIA, Dhaka.

Confirmed:

EGYPTAIR HOLDING COMPANY

Ву:

Name: Hasson Mohamed Hasson

Title:

UP Planing EsypThic Hodoling Confant

Attachments:

Annex 1: Loose Equipment List (including safety and galley equipment)

Annex 2: Documentation List Annex 3: Status of the Aircraft

Annex 4: Discrepancies

Teny 20 3

Annex 3 to Acceptance Certificate MSN 32630

Airframe

Total Flight Hours

39178:50

And

Total Cycles

9467

20Mar2014

Last S4C Check: PH56 28/05/2009

Time

18:00

GMT

Aircraft Status

Engines

S/N Total Flight Hrs Total Cycles Time/Cycles SLSV Position 1 Engine

Position 2 Engine

222031 (Note 1)	222166
40427:26	32674:39
9455	7675
2167:08 / 817	2516:15 / 1096

Landing Gears

Total Flight Hrs **Total Cycles** Cycles SLSV

APU S/N

Total Flight Hrs **Total Cycles** Time/Cycles SLSV

Fuel

Left Main .	Right Main	Nose		
MC0757P0362	MC0758P0362	MC0372P0362		
39179	39179	39179		
9467	9467	9467		
825	825	825		

331-500B	
P1444	
12812	,
13326	_
N/A	

Fuel and Oil

Oil

14600 kg	
ENG I: 21 QT (FULL), ENG II: 23 QT (
FULL) APIL: 6.75 OT	

Tires and Brakes

Tires

Brakes

No. 1. [75]% remaining [] recaps	No. 7. [75]% remaining [_] recaps
No. 2. [75]% remaining [_] recaps	No. 8. [75]% remaining [] recaps
No. 3. [75]% remaining [] recaps	No. 9. 100]% remaining [y] recaps
No. 4. [75]% remaining [] recaps	No. 10. [100]% remaining [y] recaps
No. 5. [100]% remaining [y] recaps	No. 11. [100]% remaining [y] recaps
No. 6. [100]% remaining [y] recaps	No. 12. [100]% remaining [y] recaps
L Nose. [100]%remaining [y] recaps	R Nose. [75]% remaining [_] recaps
No. 1. Pin [60] mm	No. 7. Pin [30] mm
No. 2. Pin [60] mm	No. 8. Pin [55] mm
No. 3. Pin [60] mm	No. 9. Pin [30] mm
No. 4. Pin [60] mm	No. 10. Pin [60] mm
No. 5. Pin [30] mm	No. 11. Pin [35] mm
No. 6. Pin [35] mm	No. 12. Pin [60] mm

Airframe life and time controlled components

As set forth in Attachment 1 to this Annex 3.[attach]

Engine life-limited parts

As set forth in Attachment 2 to this Annex 3.[attach]

Note 1: ENGINE NO. 1 has been changed to comply with contract requirements.

Tay 2

B777-200 REG GBY leased to BIMAN Air Check list of Catering Equipments

Date: 20+03-2014

Ser.	Equipment	Quantity of one set	Quantity of two set	Delivered status	received status
1	Full Size Trolley	33	66		
2,	Half Size trolley	3	06	•	
3	Plastic Drawer	66	66		
4	Waste Trolley	2	02		
5 Oven Insert		14	28		
6 Box (STD unit)		35	35	-	
7	FOLDABLE		3		
8	SAFTY CARD		319		

On behalf of

EgyptAir In-flight Services Co.
Name: 10 htt HUMY


Signature:


On behalf of **BIMAN Air**

Name: ABDUL KADIR

Title: ASST. MANAGER EMPN P BFCC/ BIMAN

Signature: 20 450 -










PORTABLE EMERGENCY EQUIPMENT


š			# ⁴ 5		1 		:	*(**)* F	浸漉					6.87.789 #1117			Ç.,;	gi F	- :. -	:
		₽		i —4	X	***	X 0	X		*	•	懋	0	<u>(C)</u>				[—•••])	SYMBOL	
SLIDE RAFF-DOOR 4	SLIDE RAFT DOOR 3	SLIDE RAFT DOOR 2	SLIDE RAFT DOOR 1	EXTENSION BELT	SPARE LIFE.VEST	PASSENGER LIFE VEST	CABIN CREW-LIFF VEST	INFANT LIFE VEST	DEMO KIT - DEMO BELT - DEMO OF MASK	FLASHLIGHT	EMERGENCY RADIO BEACON	MEGAPHONE	EXTERNAL DEFIBRILLATOR	EMERGENCY MEDICAL KIT	FIRST AID KIT	SWOKE HOOD	O, KIT -LO, MASK	FIRE EXTINGUISHER - HALLON	EMERGENCY EQUIP.	The state of the s
62774-XXX	62773-XXX	62772-XXX	62771-XXX	2007-2-01H-4185	S-51150-6300-EGP001	S-51150-6300-EGP001	S-51150-7300-EGP001	- S-10002-1300-EGP002	S-41150-5409 DEMO-999004 502834-415-2251 174080-56	P2-07-0001-101	1151324-1	ACREM1A.	60-0056-01	6240-26	SB-01-0005-306	119003-11	5500A1ABF23A 28301-02	898062	PART NO.	
23	, N,	2	2	<i>Ο</i> 1	10	319	<u>ත්</u>	5.	6	16	2	2	<u></u>	1	4.	ი	17	ယယ	QTY.	
:	•, .				· ;					:		· 			·	٦.٠		··	.,.	

E.O.: B777-645, R10 PAGE: 3 OF 7 (E











Egyptair Maintenance & Engineering Continuous Airworthiness Management Senior Director

ACCEPTANCE STATEMENT

AIRCRAFT S/N

32630

ANNEX 2 TO ACCEPTANCE CERTIFICATE.

Documents discrepancies.

DATED

20th March, 2014

We hereby confirm the following statement concerning the manuals / documents handed over in accordance with contract delivery documents:

Manual / Document	Statement				
Flight safety manual	Not delivered				
Operation Manual part A,B,C and D	Not delivered				
Certificate regarding ownership of the aircraft.	Not delivered				
RVSM,MNPS,RNP Manuals	No manuals for the mentioned, only available approved statement on front of flight operations manual (Operation specifications) and handover satisfactorily.				

BY

TYPED NAME

TITLE

Principle and Planning S. Director

Egyptair Maintenance & Engineering Headquarter Cairo international Airport Terminal (1) A.R.E. / P.O. 11776 Tel.: (+2) 22656774 / (+2) 2265 6724

Fax: (+2) 22674638

Website: www.egyptair-me.com



Egyptair Maintenance & Engineering Continuous Airworthiness Management Senior Director

ACCEPTANCE STATEMENT

AIRCRAFT S/N

32630

ANNEX 4 TO ACCEPTANCE CERTIFICATE.

TCI NEXT DUE LESS THAN 12 MONTHS.

*PATED

20th March, 2014

We hereby commit the following:

	P/N	S/N	Next due	Commitment
1	1152682-1	1152682-00665	28/2/2015	We commit to compensate Biman by 1/24 of the required ELT function test cost.
2	1096801-1	N/A	28/2/2015	We commit to compensate Biman by 1/24 of the required ELT Battery restoration cost.
3	30100023-3	15261	28/2/2015	We commit to compensate Biman by 1/24 of the required weighing cost.
4	62771-117	210	28/2/2015	We commit to ship a validated escape slide to the nearest point at any Middle east destination for Biman to install and ship back the old one.
,5	62773-319	178	28/2/2015	We commit to ship a validated escape slide to the nearest point at any Middle east destination for Biman to install and ship back the old one.
6	62771-120	198	30/1/2015	We commit to ship a validated escape slide to the nearest point at any Middle east destination for Biman to install and ship back the old one.

BY

TYPED NAME :

TITLE

: Engineering and Planning S. Director

Egyptair Maintenance & Engineering Headquarter Cairo international Airport Terminal (1) A.R.E. / P.O. 11776

Tel.: (+2) 22656774 / (+2) 2265 6724

Fax: (+2) 22674638

Website: www.egyptair-me.com



Egyptair Maintenance & Engineering Continuous Airworthiness Management Senior Director

ACCEPTANCE STATEMENT

AIRCRAFT S/N

32630

ANNEX 4 TO ACCEPTANCE CERTIFICATE.

SR No. 53/3 & 53/4, Stage1

DATED

19th March, 2014

Following Boeing policy; operator has to request from Boeing the stage2 approval of the repair at the end of stage 1.

If Boeing requested to replace existing repair by a permanent repair Biman has to position the aircraft at Egyptair facility, Egyptair commit to perform the required permanent repair with no cost from Biman Side and a pro rata of lease invoice will be waived based on related repair grounding time at Cairo

BY

TYPED NAME

TITLE

: Engineering and Planning S. Director

Egyptair Maintenance & Engineering Headquarter Cairo international Airport Terminal (1) Å.R.E. / P.O. 11776

Tel.: (+2) 22656774 / (+2) 2265 6724

Fax: (+2) 22674638

Website: www.egyptair-me.com

From: Chief Engineer Production, Biman

Sent: 14 March 2014 03:17

To: waguiht@egyprair.com; ahmed elbaz

Cc: S R Quddus; structure; Dy. Chief Engineer, L. M. Biman; DCE CE, Biman; Chief Engineer, QA Biman; Chief Engineer Biman; Director Engineering & Material Management, Biman Subject: Enquiry of repair Category installed on Boeing 777-200ER aircraft SU-GBY, Serial

No 32630, Line No WB155 of Egyptairuiht

Dear Sir,

Please be informed that yesterday we recevied Structural repair File of SU-GBY, MSN 32630 from your concerned department. During reviewing the said documents, we found that two repairs i.e. Repair # 53/3 and 53/4 having Stage -1 approval, which is initially valid for 24 months from the date of repair installed on aircraft.

Noted, before expiry of the validity of repair i.e. 24 months. Stage II approval to be obtained from Boeing by Egyptair and shall be forwarded to Biman. Incase Boeing fails to provide Stage II repair approval and damage tolerence instructions in respect of those repairs as mentioned above, Egypt Air shall have to bear all repair cost as well as lease rent will be deducted for the repair period.

This Statement shall be included in the Annex 4 (Discrepencies), which is the part of delivery acceptance certificate.

Thanking you with best regards,