

EXPERIMENT NO - 7

THREADING

AIM : To perform threading operation on the given mild steel specimen

TOOLS AND EQUIPMENTS USED

- (i) Lathe
- (ii) Vernier Calipers
- (iii) Surface Gauge
- (iv) Thread cutting tool

PROCEDURE


- (i) First loosen the jaw then centre the workpiece by adjusting the jaws using chucks.
- (ii) Fix the thread cutting tool in the tool post.
- (iii) Select the proper gear arrangement for your required pitch according to the chart provided.
- (iv) Switch ON the machine and perform the threading operation by giving uniform feed.
- (v) Check the threading by means of a nut of the same thread.
- (vi) Finish the operation and switch off the machine.

RESULT

The thread cutting operation have been successfully completed

100%
SM
13/07

THREADING



All dimensions are in mm.