

--	--	--	--	--	--	--	--

***B.Tech. Degree III Semester Supplementary Examination
November 2016***

**ME 1306 MACHINE DRAWING
(2012 Scheme)**

Time : 4 Hours

Maximum Marks : 100

(Assume missing dimension)

- I. (a) Make a neat sketch of conventional representation of internal thread and external thread with $d=30$ mm. Mark on it the dimension with respect to d . (20)
(b) Draw a rag end type foundation bolt for 30 mm diameter and indicate standard proportions on the drawing. (10)

OR

- II. Fig.1 shows the orthographic views of parts of a sleeve and cotter joint. Assemble them and draw elevation top half in section and end view from left. (30)

- III. Draw sectional elevation and side view of a hydraulic pipe joint suitable to 70 mm diameter pipe. Take thickness of pipe as 20 mm and other dimensions proportionately. (30)


OR

- IV. Sketch the following views of a bushed journal bearing for a shaft of 40 mm diameter. (30)
(i) Elevation.
(ii) Plan bottom half in section.
(iii) Side view right half in section.



- V. Fig.2 shows details of a machine vice. Assemble the parts and draw (40)
(i) Sectional elevation.
(ii) Side view from right.

OR

- VI. Fig.3 shows details of vertical type cross head. Assemble the parts and draw (40)
(i) Elevation.
(ii) Sectional plan.



(P.T.O.)






Fig.3

CROSS HEAD (Vertical type) Parts

ITEM LIST

Item	Description	Qty.	Material
1	Rod end	1	Steel
2	Bolt	2	Steel
3	End cap	1	C.S.
4	Body	1	C.S.
5	Lock nut	2	M. S.
6	Split pin	2	M.S.
7	Brasses	1set	Brass