


--	--	--	--	--	--	--	--	--	--



**B.Tech. Degree III Semester Examination November 2018****ME 15 - 1306 MACHINE DRAWING**
(2015 Scheme)*(Missing dimensions may suitably assumed)*

Time : 4 Hours



Maximum Marks : 60

- I. (a) Draw the three views of a hexagonal headed bolt, hexagonal nut, and a washer assembly. The nominal diameter of the bolt is 24 mm. Take the length of the bolt as 75 mm and thread length is 50 mm. (10)
(b) Draw any one lock nut arrangement. (5)
- OR**
- II. (a) The isometric view of a machine component is given in figure 1. Draw the front view, top view and left side view. (10)
(b) Draw a neat sketch of Lewis foundation bolt of diameter 30 mm. (5)
- III. Isometric view of a foot step bearing is given in figure 2. Draw the elevation left half in section and a plan. (20)
- OR**
- IV. Isometric view of a protected type flanged coupling is given in figure 3. Draw an elevation bottom half in section and a left side view. (20)
- V. The disassembled parts of a stuffing box is shown in figure 4. Draw elevation right half in section, plan, and a side view of the assembled part. (25)
- OR**
- VI. The exploded view of a Ramsbottom safety valve is shown in figure 5. Draw a full sectional elevation and a plan of the assembly. (25)

(P.T.O.)



(Contd...3)



(P.T.O.)




Figure:(5)

