


Experiment - 1

Aim: To sketch the following figure in free cad.




Procedure:-

The following figure was sketched in free cad 20.2 and obtained figure is shown in techdraw of free cad

1. Draw the three inner circles with specified dimension and spacing using sketcher.
2. Draw the outer circle.
3. Draw the 2 lines for left and lower part.
4. Make the lines tangent to the outer circle.
5. Draw another circle of 100 radius on the right side.
6. Make it tangential to the outer circle.
7. Trim the unwanted parts and make it fully constructed.
8. Using techdraw, insert a sheet and insert the image.
9. Mark the dimensions.

Experiment - 2

Aim: To sketch the following figure in free cad



Procedure:


The following figure was sketched in free CAD 20.2 and the obtained figure is shown in techdraw of free CAD.

Result:

The required figure was drawn in free cad.

Experiment - 3


Ans: To sketch the following figure in free cad.



Procedure:

The following figure was sketched in free cad. The obtained figure is shown in techdraw of free cad.

Result: The required figure was drawn in free cad.



DESIGNED BY: Sal nath		experiment:6		G	-
DATE: 23/03/23		20520092		F	-
SIZE A4				E	-
SCALE 1:2	WEIGHT (kg) Weight			D	-
		DRAWING NUMBER 6	SHEET Sheet	C	-
This drawing is our property; it can't be reproduced or communicated without our written consent.				B	-
				A	-

Handwritten text at the bottom: "The following figure is shown in sketching" and "The following figure is shown in sketching".