
## Typical Sensor Switch Over diagram





Zone 1 Action Function = Idle Set Point Enable

Input State

Example 18 - Heat, closed loop, PID control without remote SP and with Idle SP