
Typical Average Sensors diagram





Example 13 - Heat, closed loop, PID control without remote SP controlling to the