How to Sharpen Drills by Steve Hildred

In order to discuss the sharpening of drills, it is necessary to define terms and description of drills: Cutting Lips: The parts of the drill that cut.

Point Angle: The inclined angle between the cutting lips. The point angle is varied to correspond with material hardness.

Chisel Angle: The line between the cutting lips, which is the length of web thickness.

Clearance Angle: The amount the cutting lips are relieved. Controls the rate of feed or how fast the drill travels through the material.


Rake Angle or Helix: The angle of the twist of the grooves to the axis of the drill.

To sharpen drills correctly, a drill gauge is highly recommended. It allows the drill point angle to be correctly measured and to center the cutting lips. The point must be in the center of the drill and the point angle must be symmetrical to the axis of the drill.

Use a general purpose, 60 grit grinding wheel, 3/4" wide. True the wheel so that the wheel runs smoothly. To test if it is true, very gently brush the wheel with your finger. Be sure that your finger points in the direction of the rotation of the wheel. If you don't, your finger WILL be grabbed by the wheel and get CHEWED UP! If you feel any bumps, it is not smooth enough for a fine edge. Hold the drill shank in your left hand, the point in your right. Steady your right hand against the wheel guard. Using a light pressure to hold the drill to the wheel, begin the grind at the very edge of the lip with the cutting lip facing up. Move the left hand downward to form an arc of 8 to 12 degrees depending on the clearance desired. At the same time, rotate the drill along its axis clockwise 5 to 10 degrees. Both the downward arc and the rotation must be timed together. Rotate the drill 180 degrees and grind the other lip. Continue grinding, rotating the drill from one lip to the other. Keep the web thickness about 1/8 to 1/10 the drill diameter. Try to grind equal amounts from each lip. When grinding don't burn the drill (turn it blue). The drill should never get too hot to touch on the end. If you quench it when hot, it will develop little cracks and chip away.

That is really all there is to it except lots of practice. The real challenge is to know how you goofed and how to fix it. Refer to the drawings for trouble shooting. When drilling tough material or when you want the least possible burr, grind the point angle wide, 128 to 135 degrees. For a soft material like plastic, change the point to 90 degrees. For general drilling use 118 degrees. When you are drilling brass or opening up a hole, put Brass Flats on the cutting lips. This makes the drill cut slower so it doesn't pull through the material. When cutting really tough material or one that has the tendency to work-harden, use a carbon steel drill and apply pressure to the work before the drill is started, and use slow speed.


Good luck. All you need is ten thousand drills to practice on and a bunch of ornery machinists to gripe at your lousy drills. Before you know it you'll be able to sharpen anything! I Reprinted from Forge Facts - by the Rocky Moutain Smiths - Winter 2009



Ed. Note: My father was a tool & die maker and taught me how to sharpen drill bits as described by Steve above. Steve mentioned a 'drill gauge.' I inherited my father's tools. On the next page are examples of drill sharpening gauges in two sizes. The point angle and centering is checked in the 'roof end' of the gauge.


Wayne Frame - Forge Facts

Drill Bit Sharpening Gauges



Above, Wayne's gauge.


Notch on top used to check the Chisel Angle (A)



My gauge in use checking point, clearance, and chisel angles.

Ed. Note:

I made this gauge (right) in shop class, more years ago than I'd like to remember. It's cut out of a piece of 16ga aluminum. With some practice and frequent checks to the gauge I can do a fair job of sharpening a drill. I have found that if I don't use a gauge, I tend to make the drills too pointy. If you let them get too far out of shape it can be hard to get them back to the proper configuration. Bob Ehrenberger - BAM



Blacksmithing Workshops and Classes:

Peters Valley Craft Education Center

19 Kuhn Rd., Layton, NJ 07851 (973)948-5200 pv@warwick.net www.pvcrafts.org

Academy of Traditional Arts Carrol County Farm Museum

500 South Center St. Westminster, MD 21157 (410)848-7775 (410)876-2667

Touchstone Center for Crafts

R.D.#1, Box 60, Farmington, PA 15437 (724)329-1370 Fax: (724)329-1371

John C Campbell Folk School

One Folk School Rd.
Brasstown, NC 28902
1-800-365-5724 www.folkschool.com

Brookfield Craft Center

286 Whisconier Road P. O. Box 122 Brookfield, CT 06804-0122 203.775.4526

Open Forges

If any members have a forge at home and work in the evenings or weekends and want to open it up to help a few local guys, let me know, Larry Brown, editor, as we get requests from members who have a hard time traveling to some of the open forge locations.

Please contact, Larry Brown, Editor. We want to encourage all to join us at:

Monday Night Open Forge in N.J.

Marshall Bienstock is hosting an open forge in his shop at 7 pm almost every Monday night (Please call ahead on holidays to make sure, (732)780-0871)

Open Forge in Long Island

Sunday from 10:00 am to 6pm.

Starting the 1st Sunday in November until the end of April. Please call ahead to confirm and get directions. Ron Grabowski, 110 Burlington Blvd. Smithtown, NY (631) 265-1564 Ronsforge@aol.com

Business Members

We would like to thank those who joined with our new Business Membership category.

Business dues are \$40

Please show them our support

<u>John Chobrda, Dragon Run Forge</u> P.O. Box 315 Delaware City, DE, 19706

302-838-1960 jchob@verizon.net

Eric Cuper Artist Blacksmith

109 Lehman Lane, Neshanic Station, NJ 08853 908 642-6420 ericuper@msn.com

Bruce Hay, Jr.

50 Pine St., Lincroft, NJ 07738

Jayesh Shah, Architectural Iron Design

950 S. 2nd St., Plainfield, NJ 07063 jay@archirondesign.com

Louise Pezzi, Blacksmith

1241 Carpenter St

Philadelphia, PA 19147

215 336 6023 pezziandjr@gmail.com

Mark Balzarette, Blue Sun Customs LLC

124 Greenwood Ave. STE.C Suite C Midland Park, NJ 07432

BLACKSMITH TOOLS FOR SALE!

John Chobrda

Has a large selection of tools for sale.

Anvils – Forges - Leg Vices—Blowers

Tongs – Hammers

and/or resurfaced Anvils

Call John for prices and availability

(302) 838-1960 cell (609) 610-3501

In Southern NJ contact

Joshua Kuehne, 543 Amos Ave. Vineland, NJ 08360 (856) 503-5297 iforgeiron88@yahoo.com In Northern Delaware and Southern NJ, contact Kerry Rhoades or John Chobrda Kerry (302) 832-1631 John (302) 838-1960 (609) 610-3501 (cell)

NAME		
ADDRESS		
CITY	ABA	NA
STATE/PRO V.	40-	
COUNTRY	Regular Member	\$55.00
ZIP (+4)/POSTAL CODE	Senior Citizen (Age 65+) Full Time Student	\$50.00 \$45.00
PHONE #	Foreign Member	\$65.00
	Public Library-USA	\$45.00
Order Online, Mail, Call or Fax your Check	Contributory	
or Credit Card Payment to:	MASTERCARD OR VISA ACCOU	NI NUMBER
ABANA	<u></u>	
15754 Widewater Drive, Dumfries, VA 22025-1212 703-680-1632 USA	EXPIRATION DATE	
703-680-6222 VOICE Website; WWW	V.ABANA.ORG Email; ABANA	@ABANA.ORG

Join ABANA or Check out other area chapters!

Northeast Blacksmiths Association

Northeast Blacksmiths holds its meets twice a year at the Ashokan Field Campus in New York State.

The Ashokan campus is located in Olivebridge, N.Y., several miles west of Kingston, N.Y. The meets are held the first weekend in May and in the first weekend in October every year. The main demonstration is in the blacksmith shop and there is a "Hands On" workshop for beginners. A main demonstrator is brought in for each meet, food and bunkhouse style lodging are provided as part of the cost of the weekend long meet.


Contact: Tim Neu
to register for hammer-ins
or subscribe to the newsletter;
Tim Neu, The Ashokan Center,
447 Beaverkill Rd.
Olivebridge, N.Y. 12461 [914]657-8333
For more info check out the web site;
http://www.northeastblacksmiths.org/

Join The Pennsylvania Blacksmiths Association!	
Name	
	_
Address	
	_
City, State, Zip code	
Home / work Phone # E-mail (optional)	_
New Member Renewal	
Do you have any particular skills (welder, accountant, carpente	er.
doctor) that may be helpful to the group or membership?	,
	_
Suggestions for PABA demonstrations	
What is your skill level?	
O Beginner O Intermediate O Advanced O Professional	
Membership paid byCashCheck #	
Send your completed application with \$ 20 (one year dues) to;	
PABA Treasurer, Buzz Glahn	
1667 Wyomissing Rd.	
Mohnton, PA 19540	

PABA Membership Application

Membership is from <u>Jan. 1 — Dec. 31</u>

New Jersey Blacksmiths Association Attn: Larry Brown, Editor 90 William Avenue Staten Island, New York 10308



Index For NJBA Volume 15, #3 08/25/10 Meets and Reports Pages 1–9; Water leaf—10; Leaf making—11-14: Drill bits 15-17; Ad Page 18

How to Join or Renew your Membership in NJBA:

NJBA Dues are \$20 per year.

NJBA Business Dues are \$40 per year Please make your check out to: "NJBA" Please mail checks to:

NJBA, P.O. Box 224, Farmingdale, NJ 07727-9998

Please include payment with the information listed below. You will receive a postcard confirmation of your membership, and will receive a newsletter within a month. NJBA's "year" runs from June to June. If you join mid-year, the postcard will offer a prorated dues option which will then allow you to extend your membership till the following June. The following information will be listed in a roster available to other members.

Name	Home Phone
Address	Day Phone
City	
State	Zip
E-Mail	Skill Level (optional)
Comments	