

# N.J.B.A.

# NJBA Volume 11, Issue 4 02/01/07 Editors Soapbox

Well I was getting spoiled by all that warm weather we were having. Unfortunately as I write this I have just spent the day working outside and it was COLD to say it nicely. Well if the cold hangs around for a while Eric Cupers Shop is a very nice indoor meet so mark your calendars and get out to Eric's and some of the other meets.

Larry Brown, Editor

### **Upcoming events for 200**

Get you calendars out and mark these events down. Please bookmark our web site and check for meet information. Remember most of our meets have an "Iron in the Hat" drawing, so be sure to bring something.

### February 17th

Meet at Eric Cupers shop in Easton, PA. (Right over the boarder)

### March 25,26

Joint meeting with FURNACE TOWN BLACK-SMITH SHOP demonstrator will be Mike Linn. Information on page .

### **April 28 2007**

Demonstration meet at Historic Speedwell in Morris County - Open hammerin/demo. Coordinator with David Macauley. Information on page .

### April 28 and 29

A-Days at Delaware Valley College in Doylestown. Doug Learn is the contact, information on page .

#### May 19 2007

Hood Workshop, David Macauley is the coordinator. Information on page .

### February Meet at Eric Cuper's Studio

On Saturday, February 17, I would like to invite everyone out to my studio in Easton, PA for another winter meeting. I plan on demonstrating several forging techniques including the forge welding of my squid forms. This involves pipe forging and about a dozen forge welds so safety glasses are a must. Tailgating is welcome and the heaters will be on. Hope to see you there!

The address is:

1301 Lynn Street Easton, PA 18042

Any problems finding my shop, call: 908-642-6420 or 610-438-8694



### **CUPER STUDIOS Eric Cuper, Artist Blacksmith**

Cuper Studios specializes in architectural, functional, sculptural, hand-forged ironwork and restoration.

Eric Cuper, the founder of Cuper Studios, holds an MFA in Blacksmithing from Southern Illinois University at Carbondale. While at SIU, Eric won the prestigious Rickert-Ziebold Trust Award, a senior competition in art and design. He was also the First Place winner at the James Renwick Alliance student competition. His work Odyssey was auctioned to benefit the Renwick Gallery of the Smithsonian Institute. Eric's work is exhibited and collected nationally. His art has been published in Dona Meilach's books, Architectural Iron Work and Fireplace Accessories.

Directions and more information on page 3.

### The NJBA Web Site!

The NJBA Web Site is up and running at:

http://njba.abana-chapter.com/

The Newsletter is at:

http://
members.bellatlantic.net/
~vze25jcc/index.htm

### Official NJBA Address

NJBA P.O. Box 224 Farmingdale, NJ

07727-9998

Rather than use room in the newsletter,
All correspondence between
ABANA and NJBA is now being posted
on the NJBA web site.
If you cannot access it there, contact me
and I will send you copies

NJBA	Board	ot	Direc	ctors

### **Eric Cuper's meet continued:** Directions:

Assuming everyone is coming from the east. Get to 78 or 22 west from wherever you are coming from. 78 and 22 merge for a while. Take the last exit in NJ, which is 22 into Phillipsburg. Take 22 all the way through Phillipsburg, through the toll (75 cents) into PA. You are taking the very first exit immediately off the bridge so stay to the right out of the toll. Exit right and stay to the right on the exit ramp and pass under 22 until you come to a stop sign at Larry Holmes Drive. Turn left onto Larry Holmes Drive. You pass McDonalds and WaWa on your left. Take the first left onto Lehigh Drive immediately after the WaWa strip mall. My shop is on the corner of Lehigh Drive and Lynn Street. It is the first white building on the right, my shop may be entered through the green door. Parking is available in front of my entire building and all up Lynn Street but please do not park in the driveway on the left side of my building, it is an active driveway for a delivery company.

You may also take 78 west into PA (also a toll) and take the first exit in PA. I do not know the street names but turn right at the end of the exit and follow the signs for the Crayola Factory/ Canal Museum/ or Attractions. These signs will bring you to a light with McDonalds on your left. Turn left at this light and take the next left onto Lehigh Drive as above.

### Furnace Town Blacksmith's Guild Joint Meeting & Workshop 24th & 25th March, 2007

Cost is \$35.00 if registration is by 14th March \$45.00 thereafter Saturday night dinner is \$15.00 extra Mike Linn is the Demonstrator

Mike is a proficient blacksmith from Alabama. His demo is aimed at the beginning and intermediate smith. Saturday will be many short projects, while Sunday will have fewer but longer projects. Saturday includes, coffee and doughnuts in the morning, all-day demo, lunch (both days), **Iron in the Hat**, please bring something. Auction and the flashy wit

of Ray Noble and David Hutchison. The demonstration continues into the afternoon. The Saturday evening dinner will be at the Eby's house which is on Rt 12 near Millville Road in Snow Hill. (maps will be available)

We will have a table of Norm Larson's books for sale. Tailgate sales are encouraged.

Registration form on page 5.

### **December Holiday Party**

Once again Marshall and Jan hosted the Holiday Party in their home. The party was a success and well attended. The food and camaraderie was excellent and enjoyed by all.

Many thanks once again to Marshall and Jan for their hospitality.

# Historic Speedwell April 28th

NJBA has been invited to demonstrate at Historic Speedwell Park in Morris Plains. This is the historic site of Speedwell Iron Works and the estate of it's owner Stephen Vail and also listed as "The Birthplace of the Telegraph". We are asking Smiths of all levels to try to attend to help in this demonstration.

Directions:

From the South take Rt287 N to Rt 510 W to Rt 202 North From the south, you would come out of Morristown heading north, and Speedwell would be on your right. From the north, you come out of Morris Plains, about 1/2 mile south of Hanover Avenue, it is on your left.

The coordinator is David Macauley

### **Sad News**


Sad News that Dona Meilach, author of many books on the works of a wide range of blacksmiths has died of cancer.

### Little Giant Rebuilding Seminar!

Please join us for the 15th annual Little Giant Rebuilding Seminar! We will host 2 classes, Friday, March 16 through Sunday, March 18 or Friday, March 23 through Sunday the 25th, 2007. This is in Nebraska City, Nebraska and led by Sid Suedmeier, Please call 402-873-6603 or email sid@littlegianthammer.com for more information.

### Forge Hood Workshop May 17 at Marshall's Farm

NJBA is organizing a forge hood workshop for



May 19th. We are making the same design as last time but we are looking into making them out of stainless steel this time. The price has not been set as of yet and more information will be in the next newsletter or contact David Macauley

### **A-Days at Delaware College**

Four years ago, with support from NJBA and PABA, I approached the A-Days student steering committee through an alumnus to see if they would be interested in including blacksmithing in A-Days. The steering committee approved our participation and thus the tradition was borne. Over the ensuing years, the popularity of the demonstration has grown. I have learned much history of blacksmithing at the college, with the course being taught up to about 1953, when the lack of demand and shift to a more disposable society, mechanized farming and a change in educational emphasis ended the blacksmithing course. Each year, at least one older alumnus will approach the tent and remark about learning blacksmithing in the basement of Allman Hall. Additionally, one of the past presidents of the college, still strong at over 80 years of age, taught blacksmithing and always comes by to say hello and tell stories of those times. One of my goals is to sit with him and record his memories of that time to preserve this part of that history. Perhaps this year.

During demonstrations, we make small items that demonstrate basic techniques while allowing a running discussion with the crowd. Because of the structure of the event, we cannot sell any items, but I have brought items from my collection of traditional and contemporary iron, both of my own

work and of others, to show the public the range of the craft. I also bring copies of the NJBA newsletter, PABA newsletter and ABANA publications with membership applications and other information. This is a very good venue for recruitment and exposure of these organizations and I hope that they pick up one or two members from this effort.

Over the past two years I have made small 'horse shoes' to give to the attendees and last year, made and gave them to the steering committee members. While small, these tokens of appreciation have brought much good will to the organization from the students (and more than one set of teary eyes and a hug) and have made returning each year all the easier for me and the crew. And who is that crew? Each year my two sons and I have been there, along with NJBA, PABA and ABANA member Brent Reeb. The most patient woman in the world, my wife Fawn, has also lent her organizational expertise and help in all things to make this event work and allowed pieces from her collection to be displayed. Other members have helped through the years and I thank them for their support.

So it is time again to organize this event, and I am asking for assistance and demonstrators. If you wish to spend a pleasant day or weekend in Doylestown, supporting a great group of young adults and demonstrating the most noble of crafts, please contact me by e-mail (cjfdlearn@verizon.net) or phone (215.489.1742). Thanks

# THE BLACKSMITHS' GUILD of THE POTOMAC

### Spring Fling April 20-22, 2007

We again invite you to join us in a return to the traditional SPRING FLING, two and a half day event with demonstrations, tailgating and story telling. The **Berryville Ruritan Fairgrounds** gives us ample tailgating and camping space. The motels are but 8 miles west. This year we have an internet link to download your own SPRING FLING PDF PACKAGE. Go to our web page www.bgop.org on that page click on the Spring Fling Link that will take you to the page with the spring fling PDF

# Furnace Town Blacksmith's Guild

# Joint Meeting & Workshop 24th & 25th March, 2007

Cost is \$35.00 if registration is by 14th March \$45.00 thereafter Saturday night dinner is \$15.00 extra



### Mike Linn is the Demonstrator

Mike is a proficient blacksmith from Alabama. His demo is aimed at the beginning and intermediate smith. Saturday will be many short projects, while Sunday will have fewer but longer projects. Saturday includes, coffee and doughnuts in the morning, all-day demo, lunch (both days), **Iron in the Hat**, please bring something. Auction and the flashy wit of Ray Noble and David Hutchison. The demonstration continues into the afternoon.

The Saturday evening dinner will be at the Eby's house which is on Rt 12 near Millville Road

in Snow Hill. (maps will be available)

we will have a table of Norm Larson's books for sale. Tallgate sales are encouraged.
Registration form:
NAME / s
ADDRESS
CITY / STATE / ZIP
PHONE / EMAIL

# Blacksmithing Workshops and Clas-

### ses:

**Peters Valley Craft Education Center** 

19 Kuhn Rd., Layton, NJ 07851 (973)948-5200 pv@warwick.net www.pvcrafts.org

Academy of Traditional Arts Carrol County Farm Museum

500 South Center St. Westminster, MD 21157 (410)848-7775 (410)876-2667

**Touchstone Center for Crafts** 

R.D.#1, Box 60, Farmington, PA 15437 (724)329-1370 Fax: (724)329-1371

John C Campbell Folk School

One Folk School Rd.
Brasstown, NC 28902
1-800-365-5724 www.folkschool.com

**Brookfield Craft Center** 

286 Whisconier Road P. O. Box 122 Brookfield, CT 06804-0122

### Search

I am looking for a #250 fisher anvil in good shape. If you have one for sale or run across one, contact me; Larry Brown, NJBA Editor. (718) 967-4776

### **Business Members**

We would like to thank those who joined with our new Business Membership category Please show them our support

John Chobrda, Pine Barrens Forge

231 Morrison Ave., Hightstown, NJ 08520 609-443-3106 JChob@earthlink.net

**Grant Clark, GWC Forge** 

PO Box 158PerrinevilleNJ 08535

732 446-2638, 732 446-2638

**Eric Cuper Artist Blacksmith** 

109 Lehman Lane, Neshanic Station, NJ 08853

908 642-6420 ericuper@msn.com

Bruce Hay, Jr.

50 Pine St., Lincroft, NJ 07738

Jayesh Shah, Architectural Iron Design

950 S. 2nd St., Plainfield, NJ 07063

jay@archirondesign.com

Louise Pezzi, Blacksmith

203.775.4526

### **Open Forges**

We are looking for members who are interested in opening their forges up to members as a open forge. This does not have to be a weekly forge as is Marshall's the others can meet once or twice a month. Please contact, Larry Brown, Editor.

We want to encourage all to join us at:

# John Chobrda

Has a large selection of tools for sale.

Anvils – Forges - Leg Vices—Blowers

Tongs – Hammers

Will also repair and/or resurface Anvils

Call John for prices and availability

Evening 609-610-3501

### Monday Night Open Forge in N.J.

Marshall Bienstock is hosting an open forge in his shop at 7 pm almost every Monday night (Please call ahead on holidays to make sure, (732)780-0871)

### Open Forge in Long Island

Sunday from 10:00 am to 6pm.

Starting the 1st Sunday in November until the end of April. Please call ahead to confirm and get directions. Ron Grabowski, 110 Burlington Blvd. Smithtown, NY (631) 265-1564

### From The Bituminous Bits, The Journal of the Alabama Forge Council

## Scottish Dirks

By Mitch Latsch

I was lucky enough to receive an AFC scholarship and chose to take a class at John C. Campbell Folk School on Scottish Dirks taught by two World-Class Bladesmiths - Dr. Jim Batson, assisted by Chuck Patrick.

I am not much of a bladesmith and decided to take the class to learn more about blade making and metallurgy, while learning to make a truly significant historical blade. I got more than I bargained for not only did I get to forge an array of blades but learned how to forge a fullered groove in a blade and how to perform differential hardening. I took lots of notes and offer them here for those that might value the information.

Jim Batson began by providing several references for books that provide much information regarding the Scottish Dirk and the Sgian Dubh (pronounced Skin-Doo). The dirk is a large handled, long bladed weapon used in long ago for close quarter battle. The Sgian Dubh is a small handled shorter knife that was used mainly for everyday type chores. The following publications and organizations provide additional information on the Scottish Dirk.

"The Scottish Dirk" by James D. Forman

Scottish Swords and Dirks - by John Wallace

Oregon Knife club. org

Genealogical Society of Moultrie (Moultrie, GA) (Information on Scottish Clans)


Vince Evans - Shoco, AZ Has a very good website for methods of making sheaths (Site address may include "vevans")

"The Sorrows of Culloden" includes 3 or 4 dirks that are very good


Several of the students in the class were relatively inexperienced at forging so the first thing we were shown is how to forge a small blade - the Sgian Dubh. Chuck Patrick demonstrated the complete forging of one small blade (about 4 inches long). The idea was to get those that had less forging experience used to forging and fire management fundamentals. Both Chuck and Jim assured the class that the practice would be invaluable when it came time to produce the longer, larger Dirk blade as the degree of difficulty of forging a blade increases exponentially with the blade length. Chuck's demo went something like this -

Start with a good piece of steel - this steel was a length of (approximately 7/16 inch round rod) 1095, etc. I say etc. here because many blades can be made of old files or other good quality steel. Modem day bladesmiths will start with a new piece of very good steel, so they know what is going into their blade and the quality is unquestioned. In days of old, blades would have been made of old steel tools and broken swords, in the case of the Scottish Dirk. I discovered this fact accidentally, later in the week when I observed to Jim that I had "messed up" one of my blades by extending the fuller groove all the way down the blade into the tang area so that a hollow will show when it is handled. The reply that this was actually rather authentic startled me, and upon explanation Jim informed me that many old dirks had been forged using broken sword pieces and since many swords had the fuller groove the full length of the blade, the dirk that was forged from it would have had a fuller extending into the tang area, just as my blade had ended up.


Let's get back to the demonstration - first draw a point on the tip of the steel rod like this:



Then flatten out - 4 - 5" of the rod, which is longer than the blade since you need material for the tang to be drawn from.



Now start forging to shape - taper the flattened area into somewhat of a spear point shape. See below:



Be aware that when the blade bevel is forged, it will gain about 1/3 of the original of the width of the flattened blade so plan ahead or the blade will be massive. The point here is to not make the flattened area too tall top to bottom or the blade will be very wide instead of having a long slender taper.

Now forge the tip a little thinner. This is so that it will form a distal taper.

A distal taper is where the blade AND tang taper in both the thickness and the width (2 dimensions) away from the thickest point on the blade which should be located at the junction of the blade and the tang. Ideally, the taper should start at the junction of the blade and the tang and should gradually taper to the point of the blade with the thickest part of the blade being located at the junction of the tang and the blade. Be aware that the tang is tapered too, such that the thickest part of the tang is also located at the junction of the tang and the blade. We will get into that more in a little bit.


After the blade is tapered from the base of the tang to the tip, the blade can be beveled from back to edge with the edge being thinned and the back of the blade being left its full thickness.

Larry Brown, Editor Volume 11, Number 4 Page 8


To properly accomplish the bevel start at the tip of the blade and forge a blunt bevel all along the edge. Then forge the bevel in subsequent heats until the sides of the blade are totally flat with the bevel extending all the way from the edge to the back of the blade all the way from the tip to the tang of the blade. Actually there is no tang on the blade, as of yet, but that comes next.

When forging the bevels, make sure that the back of the blade is left thick enough to allow removing imperfections when finishing, you know - hammer marks.

As the bevel is forged, it is easy to see that the blade curves away from the thinning edge. Since you want to end up with a straight backed blade, it needs to be straightened during the forging process. To straighten the blade, place the heated blade's edge on the anvil and use a wooden mallet to straighten the blade. This method tends to cool the edge where it touches the anvil and prevents the edge from deforming much, and the wooden mallet will not deform the back of the blade much. Note that if you hammer hard, you WILL make the edge fold over, so hammer lightly and take your time, the blade will straighten while only blunting the edge ever so slightly.




Note that the blade should be about 95% finished at this point. After finishing the forging and straightening of the blade, fuller down at the point where the base of the tang is to begin, using a 3/8 inch diameter fuller. Leave the tang about 3/8 inch tall, top to bottom where it is fullered. This leaves a lot of material to work with when the tang is forged which results in a strong tang, and it is easier to take material off later than to put it back, or to have a weak tang as a result of excessive thinness.




Larry Brown, Editor

Volume 11, Number 4

Then flatten the base of the tang to straighten out the fuller cuts.



Continue to flatten and draw the tang out before cutting off and drawing the tang into a taper to the point. Make the tang thinner as well to form the distal taper on the tang as well as the blade. Again, this taper is in two planes thickness and width, with the heaviest metal being at the base of the tang.




- -A good rule of thumb for tang lengths is to make the tang 415 (80%) as long as the blade if a wood dandle is to be installed and 3/5 (60%) as long as the blade if making an antler handle.
- -After the tang is done it is time to finish the last 5% of the blade.
- -Check for straightness from BOTH ends. Make sure the blade is straight. Check that edge is in center of the blade. Make sure it is centered.
- -Check that the point of the blade and the point of the tang have the entire blade/tang in one straight line between them again, from BOTH ends.
- -After the blade is fully shaped, it is time to normalize the blade so that it may be worked and finished.
- -To normalize the steel, bring the knife to critical temperature just below a scaling heat (approximately 1650 degrees F) then let it cool down over approximately 5 minutes in still air to a black heat (- 1000'F).
- -Then lay the blade on something with NO water on it to finish cooling not on a cool piece of iron either. Let it air cool to room temperature.
- -Be careful not to handle it roughly while at the higher temperatures as it will change shape and waste all the work that was just put into it to get it straight and true.
- -Normalizing leaves the steel soft enough to work with files

### DESIGN CONSIDERATIONS FOR THE SGIAN DUBH HANDLE:

Jim TRACES the blade five different times. This gives him up to five opportunities to change the design before he starts actually making the handle. Trace the blade and tang, add any reflective surfaces that are to be included in the blade, trace in the shape of the handle and the top/bottom view of the handle. All this tracing will allow visualizing the look of the final finished knife, including the blade and the handle so that with five design attempts the best possible overall look can be achieved.

Other considerations, in the design of the Sgian Dubh is that the tang should be about 2 1/2 inches long, the blade 3 1/2 to 4 inches long and the depth of the blade, top to bottom at it's widest point should be about 3/4 inch. The total handle length should be about 3 1/2 inches long. See the drawing, below.



Sgian Dubh



Drawing #9

### Drawing #8


I learned an interesting technique (trick?) for drilling a hole exactly in the CENTER (or at least in an exact desired location and line) of the handle. Take a small square of plywood and drive a large nail through it, leaving the nail point sticking through the plywood a quarter of an inch. The plywood/nail mechanism is used as a center, similar to the center used on a lathe. Insert the correct sized drill bit into the chuck of a drill press and run the bit down to the drill press's platform. Place the plywood mechanism on the platform and line up the tip of the drill with the point of the nail and firmly clamp the plywood mechanism to the platform. Mark and center punch BOTH ends of the

handle material for the line of the hole that is desired - I marked the center of the top and bottom of the wood piece I was to use for the handle. If one is using a piece of antler or other non-uniform material, the punch marks may not be centered. Anyway, this method insures that the hole that is drilled in the handle will be in a direct line with the points that are punched in the ends of the handle material. After we made Sgian Dubh blades and handles for practice we began learning the finer points of the design and manufacture of the Scottish Dirk.

### First, the dimensions for a Dirk:

The back, base of the blade should be at least 1/4" thick. The tang should be about 4 1/2 to 5 inches long (5 inches if the tang will be threaded to install the handle) and the blade should be 10 to 12 inches long. If the tang is intended to be threaded, usually a 3/16" diameter thread is used. This means you should leave a slightly larger diameter cylindrical end on the tang so that it can be filed round and then threaded.

To forge a Scottish Dirk first begin by forging a point on the end of the file, bar or rod. Note that one should use a large enough piece of iron so that the thickest part of the blade can be formed without upsetting or welding. Jim provided 1/2 inch (maybe 7/16 inch) round 1095 steel for the class to use, which was plenty large enough. I have begun some blades since then that I have used files to forge. I would



suggest that if using a file, make sure it is a fairly thick file, even if not a full 1/4 inch thick. You will find as you forge the width of the file down the material gets thicker - since you are actually upsetting the material when forging the width narrower.

### Back to forging a Dirk blade:

First forge a point on the end of material to form the tip of the blade. In subsequent heats forge the blade into a long slender taper all the way from the tip to the area you plan on fullering to make the tang. The width of the blade from top to bottom at this point will be narrower than the finished blade, since as you forge the bevel the blade WILL get considerably wider. After tapering the width from tip to tang area, forge the thickness thinner so that you make the tip very thin and taper thicker up to the tang area. This completes the distal taper for the blade. Forge the bevel all along the blade beginning with a blunt taper along the blade's edge on the first pass, and then in subsequent heats continue forging the bevel, flattening the sides of the blade until the bevel extends the entire width of the blade (edge to back) along the entire length of the blade.

NOTE: make sure you leave the back of the blade a little thicker that the finished blade is desired to be when forging is complete. This allows you to thin the blade to straighten it, if for some reason after beveling the blade there is a lot of curving left in the blade. You will be able to straighten it by forging the back of the blade thinner.

As the bevel is forged and the blade curves up at the tip, keep in mind the straightening techniques described above in the Sgian Dubh using a wooden mallet on the curved back of the blade and with the edge of the blade held against the anvil. Remove the curvature as things progress since it gets harder to straighten without damaging the blade edge as the edge gets thinner. Once you have rough forged the entire blade - start at the base of the blade and smooth, straighten and thin any thick areas all the way to the tip.

For those that want to fuller a groove down the length of the blade, now is the time to do that. To forge the groove, take a 1/4 inch round rod and bend the end over. When used to make the groove the rod is used with the end turned up. Hammer the rod into the blade on a line that extends from the tip to the top of the tang OR in a line to the clip pane rather than the tip. The groove will be nearly parallel to the back of the blade and will not extend to the tip but will "fade out" before it extends to the tip. The tip of the 1/4 inch rod is turned up to keep the end of the rod from digging into the blade in the bottom of the groove. This results in a smoother bottom to the groove and makes it easier to finish the groove. Now that the blade is just about totally forged, it is time to fuller down for the tang. To accomplish this