

NJBA Volume 21, Issue 4

4 May, 2018

## **Upcoming Events**

Many of our meets feature an "Iron in the Hat" drawing (fund raiser), so be sure to bring a contribution. Tailgate sales are permitted at many of our events. See p. 2 for Directors' contact information.

# Sun., May 20, Walnford Day

NJBA will demonstrate blacksmithing to the public. Members are welcome to participate. Contact NJBA Director Bruce Freeman for info.

Sat., May 26. Advanced Damascus Workshop See announcement on this page.

# Sat., June 9. Anvil-Repair Workshop

This workshop has been cancelled due to lack of sufficient preregistrations.

#### Sat., July 7. Princeton U. Open Forge Meet

Princeton U. will be hosting a summer open-forge meet for students. Volunteers are solicited to help. Contact NJBA Director Ryan Amos if you would like to assist.

## Mon.-Sun., Aug. 6-12. Middlesex Co. Fair

NJBA has been again invited to demonstrate at the fair. Volunteers will be needed to demonstrate to the public from 5-9 PM all seven days. Contact NJBA Director Damian Toryak if you'd like to participate. General questions should be directed to NJBA Director Bruce Freeman.

August 19, Red Mill Picnic and Tailgate Sale Mark your calendar.

Sat., Sep. 15. Days of the Past Engine Show Former NJBA Director John Chobrda has been demonstrating at this show for a dozen years or so. He will be there with his blacksmithing trailer on Sat., Sep. 15. Others are welcome to join him.

# N.J.B.A. Newsletter

# Sat., Sep. ? (TBD) Picnic & Open Forge Meet

The 2017 event was in June and was rained out. After some discussion, this year's even was moved to September, but the date is yet to be set.

# Autumn Workshops (Dates TBD)

Professional swordsmith and knifemaker Mark Morrow plans to hold three workshops this coming autumn, a **tong-making workshop**, a **trade-axe-making workshop**, and a **steel-smelting workshop**. Watch for additional information.

It is time to renew your membership and vote for the nominees to the NJBA Board of Directors.

See the ballot and renewal form later on the last page of this issue.

# REGISTER NOW!

# Advanced Damascus Workshop, May 26.

This workshop will be more advanced than previous Damascus workshops. The fee for this workshop is \$150, plus a \$50 material fee due when registering & reserving your place in the workshop.

The workshop is limited to 6 participants. Your \$20 membership dues are payable at workshop, if you haven't already paid them. Contact NJBA Director Mark Morrow (at swordsmith2001@verizon.net or 732-458-5823) for further information. and to register. Tailgate sales welcome.

**Note**: Tasks performed at these workshops are limited to the projects being taught, and no other.

# **NJBA Board of Directors**

**Ryan Amos** 

10 Lawrence Dr., Apt. 106, Princeton, NJ 08540 832-830-2880 rbamos@princeton.edu

William Barrett

7 Brookwood Rd, Stanhope, NJ 07874 973-234-8701 anvilman67@yahoo.com

**Marshall Bienstock** 

663 Casino Dr., Howell, NJ 07731 732-221-3015 jlfmib2@aol.com

**Larry Brown** 

90 William Ave., Staten Island, NY 10308 718 967-4776, 917-620-9774 brownln@hotmail.com

**Eric Cuper** 

2436 Birch St., Easton, PA 18042 908 642-6420 ericuper@hotmail.com

**David Ennis** 

46 Airport Rd., Pittstown, NJ 08867 908-713-1679 davidennis@att.net

**Bruce Freeman** 

222 Laurel Place, Neptune, NJ 07753 732-677-8301 freemab222@gmail.com

**Tony Fresolone** 

76 Henderson Road, Kendall Park NJ 08824 (732) 991-3987 tjfresolone@gmail.com

Ron Jani

11 McKinley Dr., Rockaway, NJ 07866 973-625-5442, 973-462-3377, blkpnfrg@aol.com

Tom Majewski

165 Robertsville Rd, Freehold, NJ 07728 732-462-2453 v2e4mab9@verizon.net

**Mark Morrow** 

53 Beverly Beach Rd, Brick, NJ 08724 732-458-5823 swordsmith2001@verizon.net

Al Mottram

188 Parsippany Rd., Whippany, NJ 07981 crankybellows@gmail.com

**Bruce Ringier** 

512 Macdonough St., Apt. 1, Brooklyn, NY 11233 973-534-2739 maplehurstforge@gmail.com

Ben Suhaka

715 Haran Ave., Manville, NJ 08835 908-722-8197 ben2ceil@gmail.com

**Damian Toryak** 

6 Leland Rd. Edison, NJ 08817 damiantoryak@yahoo.com

We like to thank those who joined NJBA as Business Members:

Marshall Bienstock Eric Cuper



#### **ABANA CONFERENCES -- 2008 & 2010**

Wed., Jun 27 – Sat., 30 Jun, 2018. ABANA 2018 Conference Meadow Event Park Richmond, Virginia. Visit ABANA.org for further information.

**Summer, 2020.** ABANA 2020 Conference. To be held near Saratoga Springs, NY. At this past Ashokan meet, Bruce volunteered the loan of our lightweight forges. For information or to volunteer for this event, contact Rand Condell at the Adirondack Folk School, 518-696-2400, P.O. Box 2, Lake Luzerne, NY 12846

## **Official NJBA Address**

NJBA, P.O. Box 224

Farmingdale, NJ 07727-9998

#### NJBA's Website:

http://www.njblacksmiths.org

# NJBA's Facebook Page:

https://www.facebook.com/njblacksmiths/

## NJBA's Private Yahoo Group...

Send an email to crankybellows@gmail.com, including your name e-mail address, and an invitation will be sent to you.

# NJBA's IForgeIron subforum:

Scroll down at

https://www.iforgeiron.com/.

#### **NJBA Newsletter:**

njblacksmiths.org/archive/index.htm or use the link on the NJBA web site for the newsletter.

# **Open Forge Meets**

Anyone 18 years or older is welcome to try their hand one time at our open forge meets. NJBA members may participate any time the forge is open. (The application form is on the last page of this newsletter.)

#### Monday Night Open Forge, Howell, NJ

NJBA Director Marshall Bienstock hosts an open forge meet every Monday evening at 7 PM, except major holidays. (Please call ahead on holidays to make sure the forge will be open.)

Sunday Open Forge, Smithtown, LI, NY From the beginning of November through the end of April, Ron Grabowski will open his forge in Smithtown, LI, NY, to NJBA members. Please call ahead to confirm and get directions: 631-265-1564. Ronsforge @aol.com

# **Participation in Hands-On Events**

Participation in NJBA-sponsored hands-on events is limited to adults (i.e., 18 years or older).

This rule was effected as of December 2016, when NJBA was having problems with its insurance coverage (which has since replaced).

This policy applies to workshops, open forge meets, demonstrations, etc.

This policy *does not* apply to open forge meets and similar events that are sponsored by youth-oriented organizations such as scouts or schools with the aid of NJBA equipment and members.

## **New NJBA T-Shirts Now Available**

We have recently received our new NJBA T-shirts. These navy blue heavy-duty pocket T's bear the anvil logo (below left) on the pocket and the vise logo (below right) on the back.

Prices are \$20 for sizes M, L & XL, or \$25 for sizes 2XL & 3XL.

NJBA Sweatshirts are still available at \$25 each for all sizes.

These T-shirts and sweatshirts may be purchased at the above prices at our Monday evening open forge meet at Marshall's Farm, and we expect to have them available as well at our upcoming workshops and meets.

If you wish to order them by mail, a postage and handling charge of \$10 for one sweatshirt or up to two T-shirts. For further information, contact NJBA Director Bruce Freeman

#### Volunteers Needed

NJBA is a volunteer-run organization. To continue to function and to deliver the benefits you have become used to, we need members to step up to help out. Mostly, the help we need is in demonstrating to the public and in running meetings or workshops.

If a member becomes a regular, reliable contributor, we may elect him to the NJBA Board of Directors so that he will have a voice in the operation of the organization. (See "NJBA Bylaws" at njblacksmiths.org.)

# We are currently soliciting volunteers to help at these upcoming events:

• Sat., July 7. Princeton U. Open Forge Meet

A number of volunteers are needed to man the coal forges (keeping the fires burning) and to provide elementary instruction to novices. Contact NJBA Director Ryan Amos (rbamos

@princeton.edu) tfor information or to volunteer.

• Mon.-Sun., Aug. 6-12. Middlesex Co. Fair Several volunteers will be needed to demonstrate blacksmithing to the public from 5-9 PM all seven days. Contact NJBA Director Damian Toryak (damiantoryak @yahoo.com) if you'd like to participate.

If you would like to put yourself on a list of members to be contacted when we need assistance, please complete and return the volunteer form (and ballot and membership renewal) on last page of this newsletter.)

# **Lawrence Fogg**

Longtime NJBA member, Larry Fogg, passed away at home this past April at the age of 75.

Larry resided in Readington Township for over 45 years. For most of that time he was a member of the Readington Volunteer Fire Company.

Throughout his life, Larry enjoyed a variety of interests and hobbies: biking, bird watching, blacksmithing, car rallies, dog training, fishing, gardening, hunting, kayaking, photography, volleyball, wine-tasting and sailing.

He also enjoyed summers at the Jersey shore at family homes in Sands Point Harbor and Lavallette, where a favorite activity was attending The Pinelands Cultural Society's Albert Music Hall.

Larry is survived by his daughters Krystal Carr (Jens) and Autumn Hobbs (Graham), six grandchildren (William, Wyatt, Everette, Sylvi, Austin and Garrett) and his long-time companion, Mary Neary.

(Obituary derived from Legacy.com)

# NJBlacksmiths.org is Now Secure

by Ryan Amos

In recent years an important web protocol, HTTPS, has been gathering increasing attention. HTTPS protects users and websites against attackers spying on or modifying their communication. Projects like HTTPS Everywhere and Let's Encrypt, as well as Chrome, Firefox, and other browsers' HTTP warnings have pushed for every website to move to HTTPS.

To keep up, we've adopted HTTPS on NJBlacksmiths.org. From now on, when you visit

our website, you should see the green lock symbol. If you don't see that lock, on our site or any other, don't trust the site. Don't enter any passwords, payment details, or click on any links that might ask for your personal information.


This change means that when you open our website, you know what you're reading is what we sent you, and no one has spied on it. This also opens the door for us to have user interactions that require more trust; for example, we're considering adding online membership renewal.

# **Forging Tongs- Part One**

# Lesson 22A- Forging the Jaws Text By Jay Close Photos by Jane Guilden and Jay Close Drawings by Tom Latané

Introduction: There are many tong forms serving myriad func-tions, and there are diverse approaches to this common tool. Some smiths collect tongs in profusion; others get by with a small number. Some like alloy steel for tongs; others find mild steel adequate. The tongs discussed here are basic, forged from mild steel and, except for those used in punching, these tongs can be made without the use of tongs.

Intent: The lesson is designed to familiarize the learner with the basics of tong forging. The student will practice basic forging operations including drawing down, hot punching, drifting, shouldering, rounding, cutting and upsetting. These operations come together forging a set of flat jaw tongs using 5/8 inch square bar and drawing down the reins. Drawing 1 illustrates one side of the tongs discussed here. Dimensions and the terms used for the major parts of the tongs are included.



Drawing 1.

*Material:* 5/8 inch square mild steel at least 24 inches long. 5/16 inch round mild steel for the rivet.

*Tools:* Basic forging tools including a hot punch and drift to make a 5/16 inch diameter hole; a post vise will be useful but is not a necessity; layout tools including a rule, dividers and center-punch.

*Procedural Overview:* Each half of the tong is forged identically; there is no left and right jaw.

To create the jaws and pivot bolster, three, one - sided shoulders are forged on the rounded edges of the anvil. Become confident with these three shoulders, their order and where on the anvil they are forged before proceeding. There is no time to puzzle over where to hit. Rehearse these shoulders in the workshop between your ears.

Photos 1 through 5 show the shoulders that start the tongs. You will review these photos later in the lesson too.


*Hint*: For a learner without an experienced coach, it may be wise is go through the procedure with an appropriately sized "bar" of

modeling clay.

**Shoulder One**— made on the near rounded edge of the anvil.

Step in the bar about one half of its thickness the full amount of the stock lying on the anvil. Address sideways spread keeping the jaw the same width as the parent bar. (Photos 1 and 2).

**Shoulder Two**– made on the far rounded edge of the anvil after tumbling or rotating the bar 90 degrees to the left. That is rotate



Drawing 2- Tumbling a bar around its long axis, as viewed from the free end of the bar. The rotation would be to the smith's left.

the bar around its long axis so the adjacent face of the bar is positioned uppermost. Drawing 2 illustrates the idea.

This shoulder comes at the base of the first one. Many smiths will also slightly angle the bar at about 30 degrees off perpendi-cular to the axis of the anvil. Here you want sideways spread. Again, reduce the bar thickness by about half. See Photos 3, 4 and 5.

**Shoulder Three**— also made on the far rounded edge of the anvil after another left hand turn or tumble of 90 degrees. Photo 6.

This shoulder defines the pivot bolster and the start of the reins.

After the jaws are forged and the pivot bolster defined, a pivot hole is hot punched and drifted.

The reins are drawn out using the anvil horn and the reins are smoothed on the anvil face.

The two tong halves are riveted together. Once assembled, they are sized to fit a specific bar thickness.

*Note*: directions assume a right handed smith forging tongs used principally in the left hand. Tongs for a left handed smith that will be held primarily in the right hand are sometimes made with 90 degree tumbling to the right. The slight offset in the handles to the left or to the right seem to better conform to the anatomy of the left or right hand. Many smiths do not bother with the distinction or bend the reins in vertical alignment creating a neu-tral grip

#### Step One (layout):

Cut a length of 5/8 inch square mild steel a minimum of 24 inches long. This will provide sufficient length to forge both halves of the tongs without use of tongs.

Put two centerpunch marks (or some other permanent layout mark) on the bar. The first should be 5 and 1/2 inches from the end of the bar and the second should be 11 inches from the end.

See Photo 7 for the layout. These marks indicate the material for each tong half.

A layout easily seen when the bar is at heat can be made by plac-ing a deep centerpunch mark very near the edge of the bar. If the mark is near enough to the edge, the steel bulges out from the bar looking like the bulging eye of a frog. Prominent "frog's eye" layout marks save precious time lost searching for more subtle indicators.

#### Step Two (first shoulder):

The student should review pre-vious lessons on shouldering at the near and far edges of the anvil using half faced hammer blows.

Heat the end of the bar to a vellow and place 1 inch of it on the anvil face at the near rounded




Photo 8. zontal and perpendicular to the edge of the anvil as in Photo 8.

Hint: if you need, place a chalk or soap stone mark on the anvil so you can readily repeat the over lap. With practice such an aid will not be necessary.

With half face hammer blows sink a vertical shoulder reducing






Photos 1 and 2.

the thickness of the bar by about half all the way to the end of the bar. You want a parallel sided extension that will become the tong jaw.

Eliminate sideways spread, keeping the bar 5/8 inch wide as you forge. See Photos 1 and 2.



Drawing 3- The first shoulder, made on the near edge of the anvil, to form the jaw.

The higher the heat and the harder you hit the more readily this shoulder will develop.

Drawing 3 shows the needed result with approximate. dimen-sions.

Target: This shoulder is readily forged in one heat. With practice you may be able to forge more than one shoulder on the same





Photos 3 and 4.



Photos 5.


heat, but it is critical to set shoulders at the highest possible temperature. Do not extend a heat attempting to do more than the temperature allows.

As the bar drops to orange temperature, get it back in the fire.

**Step Three** (second shoulder):

The second shoulder is made by tumbling or rotating the bar 90 degrees to the left and repositioning it on the anvil. See Photos 3, 4 and 5.

Place all of the drawn down portion of the first shoulder extend-



Drawing 4- The second shoulder, made on the far edge of the anvil, to form the bolster. The 30-degree angle forms a slightly stronger transition between the jaw and bolster..





Photos 6 and 7.

ing off the far side of the anvil so the base of the shoulder aligns with the far rounded edge. Keep the bar flat on the anvil face. Drawing 4 shows the positioning of the bar for the second shoul-der. Note that the bar is swung about 30 degrees to the left. This makes the joint a bit more refined. It is permissible to simply hold the bar straight across the anvil.

At a yellow heat, hit flat, half-faced hammer blows.

Thin the bar to about half of its starting thickness and create symmetrical sideways spread. You ought to be able to get 1 inch of spread and about 5/16 inch thickness. Photo 5 shows the result.

Work this reduced thickness down the length of the bar for about 2 inches. This gives a head start in drawing the reins. See Photo 6.






Photos 9 and 10.

Forging dynamics— because this spreading and shouldering is accomplished entirely from one side of the bar, the spread in cross section can be expected to be slightly wider on the top than the bottom. This is evidence of the differential impact of the hammer blow as opposed to the anvil on the hot bar. The harder you hit and the hotter the temperature, the less this asymmetry develops.

#### **Step Four** (third shoulder):

The third shoulder requires another tumble of the bar 90 degrees to the left. This orients the flat you made in Step Three verti-cally.

If you spread the bar to one inch in width when making the second shoulder, you now want to place that same amount of the spread bar extending off the anvil. Compare Photo 9 and Photo



*Drawing 5- Dressing the shoulders, which defines the bolster.* 





Photos 11 and 12.

10. These photos show use of dividers to compare dimensions for explanatory purposes; in forging make this an eye judgement.

At a yellow heat, hit hard, half face blows to forge the third shoulder. Be sure you are using the rounded edge of the anvil. See Photo 11.

Control the bar dimensions. Define the pivot bolster and begin to draw the start of the reins. At this point retain the 5/8 inch width of the bar but reduce the thickness to match that of the bolster.

You results should look like Photo 12.

Hint: After the third shoulder is established use the horn of the anvil as much as possible to do all subsequent drawing out of the reins. The rounded form will greatly enhance the stretching effect of your hammer blows and speed the work significantly.

You can refine the bolster shape by working it on the anvil as shown in Drawing 5. You can even selectively cool one edge to retain its form while the opposite side is altered. You want a sym-metrical "football" or lozenge shape to the bolster area.

Often the transitions between the first shoulder and the second when forged on the rounded edges of the anvil will develop a "web." The transitions will not be crisp and angular, but will flow into each other reflecting the curve of the anvil edge. Attempting to forge this web away will often result in a cold shut, so it is preferable to leave it for now and do a bit of file clean up as necessary prior to final assembly.





Photos 13 and 14.

#### Step Five (punching):

Review previous lessons on punches and hot punching.

The most efficient forging procedure is one in which each section is completed before moving to the next. This avoids reheating areas that have been left incomplete after they are cool.

While some smiths will reheat and punch the pivot hole after the rest of the tongs are done, efficiency dictates that now is the time to punch the pivot hole. With care drawing the reins, there

should be little or no distortion of a hole punched at this stage.

Punch the center of the bolster using a hot punch about 1/4-inch diameter on the end.

Remember to start punching from the outside of the joint with the jaw off the anvil at the far rounded edge. See Photo 13. When you flip the work 180 degrees to complete the hole and then move to the pritchel hole or punching block to free the slug or "biscuit," the flat outside of the joint will lie flat on the anvil face. See Photo 14.

Drift the hole to 5/16 inch diameter.

#### Target:

Punch and drift the hole in a single heat. The hole should be centered in the mass of the pivot bolster.

This lesson is concluded in the next issue with Controlled Hand Forging Lesson 22B, "Drawing The Reins."

Acknowledgments: Photos by the author and by Jane Gulden. Thanks to the American College of the Building Arts (www.buildingartscollege.us) for encouragement writing this lesson.



# **Demonstrators Needed**

**East Jersey Olde Towne** in Piscataway NJ is looking for blacksmiths to demonstrate to school groups and the public weekdays and weekends starting in the spring 2018 and through the fall. The Historic Village is open 8:30 till 4:00 PM and is located in Johnson's Park across River Road from Rutgers's Stadium.

Anyone who is interested can contact Matthew Stroh at EJOT <u>732.745.3030 Ext 304</u>. More information can be found at

http://www.middlesexcountynj.gov/Government/ Departments/BDE/Pages/East-Jersey-Olde-Towne-Village.aspx

Bob Bozzay (robert.bozzay@gmail.com) currently works there two days a week. He can provide additional information.

# Champion Contractors' Forge

